

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: Allianz Insurance Singapore Pte. Ltd.
79 Robinson Road #09-01
Singapore 068897

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: JANICE KOH

Date: 18 Oct 2022

Preliminary Advice

Vehicle No : SMU772R Accident Date : 11/10/2022
Make : VOLKSWAGEN SCIROCCO Policy No. :
SP2000944016
Assignment Date : 17/10/2022 Excess : S\$600.00
Date of Inspection : 18/10/2022 Est. Duration of Repair : 14 DAYS
Inspection At : SNG AH TEE MOTOR & PANEL SERVICE PTE LTD

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$ 27,938.50
Revised Amount	:S\$ 17,920.50
Check Items (Estimated)	:S\$ 9,397.00
Total	:S\$ 27,317.50
Lump Sum Repair	:S\$

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$ 72,000.00
COE / PARF Rebate	:S\$ 25,085.00
Salvage Value	:S\$
Margin for Repair	:S\$ 46,915.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.

- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.

- (X) Other comments : The vehicle repair on Lump Sum basis.
Please note that the preliminary advice amount (Revised & Check Items) stated are subject to consistency check, part prices and labour cost.