



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
UNITED OVERSEAS INSURANCE LTD 146 ROBINSON ROAD #02-01 UOI BUILDINGSINGAPORE 068909		Ref: CS/UOI22010287/Uny3m4 Date: 31/10/2022 Code: UOI2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBJ 8783U	Veh. Inspected	SFL 3121E
Policy No.		Coverage (\$)	0.00
Claim No.	M12D00012211	Excess (\$)	0.00
Assign From	KATIE LEE	Assign Date	17/10/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA CIVIC IMA HYBRID (A)	c.c	1339
Engine No.	HIDDEN	Year of Reg.	2009
Chassis No.	JHMF36209S206197	Colour	SILVER
Odometer	204027 KM	Steering	AFFECTED
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	195/65 R15	MAXIMUM	6 mm
L/H Front Tyre	195/65 R15	MAXIMUM	6 mm
R/H Rear Tyre	195/65 R15	MAXIMUM	6 mm
L/H Rear Tyre	195/65 R15	MAXIMUM	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION & O/S BODY. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/10/2022	Inspection Date	18/10/2022
Survey held at	GALAXY AUTO CARE PTE LTD 13 KAKI BUKIT ROAD 4 #01-23 BARTLEY BIZ CENTRE SINGAPORE 417807		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	