

Your Ref : D22003268MFVS

Date: 22nd Nov 2022

Our Ref : CS4/FCI22010293/Rqy3m4

M/s MS First Capital Insurance Ltd

16 Raffles Quay

#42-01 Hong Leong Building

Singapore 048581

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO. XD 6137U
ACCIDENT ON 13/10/2022**

Instruction was received to inspect the vehicle Reg. No. XD 6137U. The inspection was conducted on 17/10/2022 at the premises of M/s SC Auto Industries (S) Pte Ltd, 51/53, Senoko Road, Singapore 758133.

The following vehicle information was recorded:

Registration Number	: XD 6137U
Make/Model	: D.A.F. FAT CF75.310
Year of Registration	: 2012
Body Colour	: Yellow
Chassis Number	: XLRAT75PC0E886067
Engine Capacity	: 9186 cc

The vehicle caught fire. The cause of fire probably due to electrical. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	35,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$	25,617.00)
Nett Liability	S\$	9,383.00
	=====	

Vehicle Inspected By:



MOHAMMED RASUL BIN MOHD YUNUS
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MII(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.