



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

## Affiliated to Federation Internationale Des Experts En Automobile

LONPAC INSURANCE BHD

300 BEACH ROAD

#17-04/07 THE CONCOURSESINGAPORE 199555

Ref: ~~CS3/LPC22004728/Gqy3-1~~

Date: ~~15/10/2022~~  
15/10/2022

Code: LPC2

### 1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	GBB 4193R	Veh. Inspected	SKB 896R
Policy No.		Coverage (\$)	0.00
Claim No.	22/22/22/VC05/025804	Excess (\$)	0.00
Assign From	<del>GERALD POH</del> HUEY NI	Assign Date	<del>15/05/2022</del> 15/10/2022

### 2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--	--

### 5. General Information

Accident Date	12/05/2022	Inspection Date	20/05/2022
Survey held at	PRECISION MOTORWORKS PTE LTD 68 KAKI BUKIT AVENUE 6 #01-02 ARK@KB SINGAPORE 417896		

### 5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.  
B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.  
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.  
C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.