



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010307/Avy3e2	
			Date: 29/03/2023	
			Code: SMR	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SHD 6368J	Veh. Inspected	SNB 4490R
	Policy No.		Coverage (\$)	0.00
	Claim No.	TAX/10/22/2054	Excess (\$)	0.00
	Assign From	ASHLENE LEE	Assign Date	17/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	TOYOTA ALPHARD	c.c	2494
	Engine No.	HIDDEN	Year of Reg.	2021
	Chassis No.	JTNHS3DH308056056	Colour	BLACK
	Odometer	20098 KM	Steering	IN ORDER
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
	L/H Front Tyre	225/60 R17	YOKOHAMA	6 mm
	R/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
	L/H Rear Tyre	225/60 R17	YOKOHAMA	6 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	14/10/2022	Inspection Date	03/11/2022
	Survey held at	BIFROST AUTO PTE LTD 8 KAKI BUKIT AVENUE 4 #01-49 PREMIER @ KAKI BUKIT SINGAPORE 415875		
5a. Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days	