



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22010311/Uqy3m4 Date: 28/10/2022 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SLT 7695B	Veh. Inspected	SGW 8736D	
Policy No.		Coverage (\$)	0.00	
Claim No.	BVS22/1217	Excess (\$)	0.00	
Assign From	TED SEAH	Assign Date	17/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	BMW X3 (A)	c.c	1998	
Engine No.	HIDDEN	Year of Reg.	2021	
Chassis No.	WBATY120X09H22807	Colour	GREY	
Odometer	16010 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	245/50 R19	BRIDGESTONE	8 mm	
L/H Front Tyre	245/50 R19	BRIDGESTONE	8 mm	
R/H Rear Tyre	245/50 R19	BRIDGESTONE	8 mm	
L/H Rear Tyre	245/50 R19	BRIDGESTONE	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/10/2022	Inspection Date	18/10/2022	
Survey held at	ZOOM AUTOWERKS PTE LTD 130 BEDOK RESERVOIR ROAD, #08-1339,EUNOS SPRING SINGAPORE 470130			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	