



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
LIBERTY INSURANCE PTE LTD 51 CLUB STREET, #03-00 LIBERTY HOUSESINGAPORE 069428			Ref: CS/LIP22010312/Uqy3m4 Date: 28/10/2022 Code: LIP	
1. Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	SNC 9920D	Veh. Inspected	SME 5616K
	Policy No.	SD21V17243/VPL/R00	Coverage (\$)	0.00
	Claim No.	AVS22/2821	Excess (\$)	0.00
	Assign From	TED SEAH	Assign Date	17/10/2022
2. Vehicle Particulars & Condition				
	Make & Model	HONDA CIVIC (A)	c.c	1597
	Engine No.	HIDDEN	Year of Reg.	-
	Chassis No.	MRHFC5650JT001509	Colour	GREY
	Odometer	51360 KM	Steering	AFFECTED
	Brakes	IN ORDER	Modification	SPORTS RIM
	General	GOOD		
3. Conditions of Tyres				
		Size	Make	Balance
	R/H Front Tyre	215/55 ZR16	DUNLOP	7 mm
	L/H Front Tyre	215/55 ZR16	DUNLOP	7 mm
	R/H Rear Tyre	215/55 ZR16	DUNLOP	7 mm
	L/H Rear Tyre	215/55 ZR16	DUNLOP	7 mm
4. Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S FRONT PORTION. THE UNDERCARRIAGE AFFECTED DUE TO COLLISION. DAMAGES SEE DETAILS.			
5. General Information				
	Accident Date	05/10/2022	Inspection Date	18/10/2022
	Survey held at	2ND AUTO PTE LTD 15 KAKI BUKIT ROAD 4, #01-53, BARTLEY BIZ CENTRE, SINGAPORE 417808		
5a. Remarks				
	A)REGISTRATION DATE: 04 OCT 2018 B)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. C)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days	