

COMFORTDELGRO ENGINEERING PTE LTD

Effective Date: 1 Nov 2020

REPAIR ESTIMATE

LKK-

DATE: 17.10.2022

MODEL: Hyundai i40

INSURANCE: INCOME

VEHICLE NO.: SHD3074B

MVA: LIM T S

PART NO.	DESCRIPTION	QTY	UNIT PRICE	AMOUNT
	Front Door RH	1		\$ 2,707.70
	Front Door Upper Hinge RH	1		\$ 113.60
	Front Door Lower Hinge RH	1		\$ 113.60
	Front Fender RH	1		\$ 588.80
	<b>SUB TOTAL</b>		3410.10	\$ 3,523.70
	<b>LESS 20%</b>			\$ 704.74
	<b>DISCOUNTED TOTAL</b>		2728.08	\$ 2,818.96
	Front Door ComfortDelGro RH	1		\$ 75.00
	<b>SUB S/NETT</b>		75	\$ 75.00
	<b>LESS 10%</b>		10% - 67.50	\$ 7.50
	<b>S/NETT TOTAL</b>			\$ 67.50
	Front Door Adv.Sticker RH	1	cut	\$ 100.00
	Front Fender Adv.Sticker RH	1	cut	\$ 100.00
	<b>SPARE PARTS TOTAL</b>		200	\$ 3,086.46
	<b>Labour Charge</b>			
	Panel Beating		525	\$ 800.00
	Spray Painting Charge			\$ 600.00
	Tuff Kote		30	\$ 100.00
	Towing Fee		1155	-
	<b>TOTAL LABOUR</b>		4150.58	\$ 1,500.00
	<b>ESTIMATE TOTAL</b>		45033.00	\$ 4,586.46
			03 days	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.

- LKK Auto Consultants** hence notify the Repairer of the following:
- To resurvey before/after spray painting
  - To display damaged part(s) during resurvey
  - Parts prices are subject to confirmation
  - Third party survey is on a "Without Prejudice" basis
  - No illegal modification(s) is allowed
  - Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:

Tanpin 97495749  
 Sup' 17/10/22 @ 3pm  
 L/S Namy after repair  
 Tanpin C/Hando.com  
 03 days