



1

of 2 ?



100%

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref: CS/CTI22010390/Gny3

3 ANSON ROAD #16-00

Date: 19/10/2022

SPRINGLEAF TOWERSINGAPORE 079909

Code: CTI

1. Policy Particulars :- OWN DAMAGE

Insured Veh.		Veh. Inspected	SMV 3731J
Policy No.	DMPCSNW00185362100	Coverage (\$)	0.00
Claim No.	SNM22D206412/C01	Excess (\$)	3,750.00
Assign From	LYNN KHONG	Assign Date	18/10/2022

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	07/09/2022	Inspection Date	19/10/2022
Survey held at	8 KAKI BUKIT AVE 4 #03-41/03/42 PREMIER@KAKI BUKIT		
Repairer	SAT (SG) PTE LTD		

5a. Remarks

A)THE MARKET VALUE IS S\$------(EST. AVERAGE)
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.