

ASSIGNMENT

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt:

GIA / PR Seen:

Est. Repairs:

Lum Sum:

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Veh No: SJY 1726H

Yr Regn: 06/08/10

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or CA/

Make:

Colour:

Sp. Reading:

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal.

L/Bal.

D.O.A.

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?

1)

Date/Time, File Return to?

2)

Report Format:

Lump Sum / I.B.I. (\$)

Preli. Report

Final Report

Days Of Repair:

Resurvey No. of Trip:

Add Fee:

Site Insp (\$)

Interview (\$)

Tech. Invs (\$)

Weekend (\$)

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

We used 31-07-2030 LTA & 26114

11/11/22 1/5 @ 3250 in hand AH ying CPD @ 2668, 45%

SME MOTOR PTE LTD

1 Kaki Bukit Ave 6 #02-15, AutoBay @ Kaki Bukit, Singapore 417883

Tel: 6747 6106 (6 Lines) Fax: 6744 2368

Email: service@smemotor.com.sg Website: www.smemotor.com.sg

Co. & GST Reg. No: 201119451E

INSURER: Allianz Insurance Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	22/AL/OD-508 (10)
Policy No:	P000010884	Date of Loss:	15/10/2022
Vehicle Reg. No.:	SJY1726H	Driveable?	
Driver Age/Info:	/ MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	NUR HAFIZAH BTE ABDUL FATTAH	Contact No:	+6586068793
Driver:	MOHD SHAFARIN BIN AHMAD		

Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	06/08/2010
Vehicle Colour:	LIGHT BLUE		
Engine No:	2ZR0557450	Chassis No:	ZGE200052591
Odometer:	0 KM		

Paint Type:	
Total Loss?	NO
Est. Duration of Repair (day)	7

Present Location: SME MOTOR PTE LTD (KAKI BUKIT)

COST OF CLAIMS

	Amount
Parts	3,927.00
Miscellaneous Items	0.00
Labour	1,760.00
Paintwork Labour	0.00
Towing	0.00

Gross Total (\$\$)	5,687.00
+ GST 7.00% (\$\$)	398.09
Nett Amount (\$\$)	6,085.09

This claim is handled by: CHIA PEI YING

Generated using Merimen e-Claims Internet Estimation & Adjusting System

Not Authorized
 LK Auto
 20/10/22
 Excess \$2000
 1/5 \$3250
 take 2 hrs after repair
 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 19 Oct 2022)**Parts:** M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** SME Motor Pte Ltd/SJY1726H/19/10/2022 13:18**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRT BUMPER <i>DIS</i>	0.00	0.00	*275.00 F ✓
2	1		*FRT BUMPER RETAINER RH <i>one</i>	0.00	0.00	*35.00 F ✓
3	10		*FRT BUMPER CLIP <i>one</i>	0.00	0.00	*20.00 F ✓
4	1		*RH HEADLAMP <i>one</i>	0.00	0.00	*360.00 F ✓
5	1		*FRT RH FENDER <i>DIS</i>	0.00	0.00	*295.00 F ✓
6	1		*FRT RH FENDER INNER COWLING <i>DIS</i>	0.00	0.00	*95.00 F ✓
7	10		*INNER COWLING CLIP <i>one</i>	0.00	0.00	*20.00 F ✓
8	1		*WASHER TANK <i>one</i>	0.00	0.00	*60.00 F ✓
9	1		*WASHER TANK MOTOR <i>one</i>	0.00	0.00	*85.00 F ✓
10	1		*FRT RH SHOCK ABSORBER <i>one</i>	0.00	0.00	*195.00 F ✓
11	1		*FRT RH LOWER ARM <i>one</i>	0.00	0.00	*145.00 F ✓
12	1		*FRT RH LOWER ARM BALL JOINT <i>one</i>	0.00	0.00	*85.00 F ✓
13	1		*FRT RH KNUCKLE ARM <i>one</i>	0.00	0.00	*210.00 F ✓
14	1		*FRT RH KNUCKLE BEARING <i>one</i>	0.00	0.00	*65.00 F ✓
15	1		*STEERING RACK ASSY (NO STOCK) <i>one</i>	0.00	0.00	*800.00 F ✓
16	1		*STEERING CROSSMEMBER <i>one</i>	0.00	0.00	*750.00 F ✓
17	1		*ANTI ROLL BAR LINK RH <i>one</i>	0.00	0.00	*75.00 F ✓

F=Franchise part.

Sub Total (S\$) 3,570.00

+ Margin on L,N Items 10.00% (S\$) 357.00

Total Parts (S\$) 3,927.00

SME Motor Pte Ltd/SJY1726H/19/10/2022 13:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

2735
 P-2945
 102
 3239.50
 1440
 4679.50
 302
 3275

Estimates on Miscellaneous Items

There are no new miscellaneous items selected.

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	WIRE CHECKING	New	20 30.00
2	REMOVE & REFIX FRT UNDERCARRIAGE (WITH RACK AND CROSSMEMBER)	New	300 350.00
3	4 WHEEL ALIGNMENT	New	70 80.00 ✓
4	LABOUR CHARGE	New	450 600.00
5	SPRAY PAINTING	New	600 700.00
Gross Labour Cost (\$\$)			1,760.00

SME Motor Pte Ltd/SJY1726H/19/10/2022 13:18. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 04 Nov 2022)
Parts: M1-MPV TOYOTA WISH 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: SME Motor Pte Ltd/SJY1726H/04/11/2022 11:18
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FOG LAMP GARNISH RH (missin)	0.00	0.00	*65.00 F
2	1		*FRT BUMPER INNER SPONGE	0.00	0.00	*85.00 F
3	2		*ANTI ROLL BAR BUSH	0.00	0.00	*60.00 F
Sub Total (S\$)						210.00
+ Margin on L,N Items 10.00% (S\$)						21.00
Total Parts (S\$)						231.00

SME Motor Pte Ltd/SJY1726H/04/11/2022 11:18. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Stamford Tyres International Pte Ltd

23 Kaki Bukit Road 4
#01-12/13 Synergy@KB
Singapore 417801

Phone Number: 6702 3355

Fax Number: 6341 6993

Customer:		Date:	11/5/2022 12:59 PM
Company:		VIN	
License NO:	SJY1726H	Technician:	
Odometer:	205736KM	Order NO:	

VEHICLE ALIGNMENT REPORT

TOYOTA, WISH, 09-13, ZGE20G/ZGE21G (2WD)

Primary Angles			Initial	Specifications		Final
				Min.	Max.	
Front	Caster	Left	----	2°20'	3°50'	----
		Right	----	2°20'	3°50'	----
	Camber	Left	-0°24'	-1°20'	0°10'	-1°00'
		Right	-0°54'	-1°20'	0°10'	-1°00'
	Toe	Left	-0°39'	-0°05'	0°05'	0°00'
		Right	-0°51'	-0°05'	0°05'	0°00'
Total		-1°30'	-0°11'	0°11'	0°00'	
Rear	Camber	Left	-1°36'	-2°00'	-1°00'	-1°36'
		Right	-2°06'	-2°00'	-1°00'	-2°06'
	Toe	Left	-0°03'	0°00'	0°16'	-0°03'
		Right	-0°15'	0°00'	0°16'	-0°15'
		Total	-0°18'	0°00'	0°32'	-0°18'
	Max Thrust Angle		-0°06'	----		-0°06'
Secondary Angles			Initial	Specifications		Final
				Min.	Max.	
SAI	Left		----	11°25'	11°25'	----
	Right		----	11°25'	11°25'	----
Included Angle	Left		----	----	----	----
	Right		----	----	----	----
Toe Out On Turns	Left		----	----	----	----
	Right		----	----	----	----
Max Turn Inside	Left		----	----	----	----
	Right		----	----	----	----
Toe Curve Change	Left		----	----	----	----
	Right		----	----	----	----
Setback	Front		8mm	----	----	8mm
	Rear		-14mm	----	----	-14mm
Track Width Diff.			21mm			21mm
Wheel Base Diff.			22mm			22mm
Front Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Rear Ride Height	Left		----	----	----	----
	Right		----	----	----	----
Frame Angle						----