

**Note: This document has not been finalised.****LKK Auto Consultants Pte Ltd** (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park  
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: EQ Insurance Company Ltd  
5 Maxwell Road,#17-00 Tower Block  
MND Complex  
Singapore 069110From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Josephine Wong

Date: 06 Dec 2022

**Preliminary Advice**

Vehicle No	: SME8882M	Accident Date	: 07/10/2022
Make	: FERRARI F8 TRIBUTO	Policy No.	: DMPPHQ22-005606
Assignment Date	: 20/10/2022	Excess	: S\$15,000.00
Date of Inspection	: 21/10/2022	Est. Duration of Repair	:28
Inspection At	: OPTIMA WERKZ PTE LTD		

**Point of Impact / General Description of Damages**

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	334,210.50 (inclusive supp \$17,434.00)
Revised Amount	:S\$	323,859.00
Check Items (Estimated)	:S\$	0.00
Total	:S\$	323,859.00
Lump Sum Repair	:S\$	

**Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	1,400,000.00
COE / PARF Rebate	:S\$	528,595.00
Salvage Value	:S\$	
Margin for Repair	:S\$	871,405.00

**Remarks**

- ( x ) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- ( ) The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- ( x ) Other comments :Kindly approve on supplementary