



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile                       |  |  |                          |            |
|---|--|--|--------------------------|------------|
| MS FIRST CAPITAL INSURANCE LTD<br>36 ROBINSON ROAD<br>#16-01 CITY HOUSESINGAPORE 068877 |  |  | Ref: CS/FCI22010428/Ucy3 |            |
|   |  |  | Date: 20/10/2022         |            |
|   |  |  | Code: FCI2               |            |
| <b>1. Policy Particulars :- THIRD PARTY CLAIM</b>                                       |  |  |                          |            |
|   | Insured Veh.   | GZ 3385A   | Veh. Inspected           | GBF 8354X  |
|   | Policy No.   |  | Coverage (\$)            | 0.00       |
|   | Claim No.  | D22003251MCVP  | Excess (\$)              | 0.00       |
|   | Assign From  | CAROLINE CABRERA   | Assign Date              | 20/10/2022 |
| <b>2. Vehicle Particulars &amp; Condition</b>   |  |  |                          |            |
|   | Make & Model   |  | c.c                      | 0          |
|   | Engine No.   | HIDDEN   | Year of Reg.             |            |
|   | Chassis No.  |  | Colour                   |            |
|   | Odometer   | -  | Steering                 |            |
|   | Brakes   |  | Modification             |            |
|   | General  |  |                          |            |
| <b>3. Conditions of Tyres</b>   |  |  |                          |            |
|   |  | Size   | Make                     | Balance    |
|   | R/H Front Tyre   |  |                          | mm         |
|   | L/H Front Tyre   |  |                          | mm         |
|   | R/H Rear Tyre  |  |                          | mm         |
|   | L/H Rear Tyre  |  |                          | mm         |
| <b>4. Description of Damages</b>  |  |  |                          |            |
|   |  |  |                          |            |
| <b>5. General Information</b>   |  |  |                          |            |
|   | Accident Date  | 11/10/2022   | Inspection Date          | 20/10/2022 |
|   | Survey held at   | LIU'S BROTHER AUTO ENGINEERING WORKSHOP<br>1 KAKI BUKIT AVENUE 6 #01-01 AUTOBAY @ KAKI BUKIT<br>SINGAPORE 417883 |                          |            |
| <b>5a. Remarks</b>  |  |  |                          |            |
|   | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.<br>B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                          |            |