

# EUROKARS HABITAT PTE LTD 27A TANJONG PENJURU, SINGAPORE 609042



ESTIMATE COST OF REPAIRS

India International Insurance Pte Ltd

NAME:

WIP:

59824

64 Cecil Street #04-05

ADDRESS:

DATE IN:

EXCESS :

IOB Building

18-Oct-22

63310684

Singapore 04971

ATTN.:

**MOTOR CLAIMS** 

TEL:

FAX:

 VEH NO :
 SMW9860A

 CHASSIS NO :
 WMWXU520002N78937

MILEAGE: TYPE OF CLAIM:

THIRD PARTY

DEREK

MODEL: MINI One 5 Door RHD DATE REG.: 21-Dec-20 POLICY NO.:

## NATURE OF WORKS

**CONTACT PERSON:** 

s/no	Parts Description							
		QTY		1ST	SUPP	REVISED		PRICES
1	TAILGATE	1	M41.00.7.378.205				\$	1,422.01
2	TAILO GATE WEATHERSTRIP	1	M51.76.7.379.602				\$	181.22
3	TAILGATE LOCK	1	M51.24.7.337.576				\$	151.97
4	COVER LOCK	1	M51.24.9.878.934				\$	24.31
5	STRIKER	1	B51.24.7.248.076				\$	79.23
6	TRUNK LID GR "NEW LOGO" W/CAM CHROME	1	M51.13.7.489.757				\$	258.83
7	SUPPORTING LEDGE	1	M51.62.7.337.600				\$	30.36
8	BLIND RIVET	3	B51.24.8.226.003				\$	15.21
9	MOUNT RAIL LH	1	M51.13.7.375.109				\$	28.41
10	MOUNT RAIL RH	1	M51.13.7.328.384				\$	28.41
11	NUT	2	B51.12.7.020.321				\$	2.60
12	TAILGATE CHOME MOULDING	1	M51.13.7.328.385				\$	108.22
13	EMBLEM "ONE"	1	M51.14.2.755.615				\$	72.47
14	TAILGATE INNER TRIM	1	M51.49.7.318.942				\$	187.46
15	REAR BUMPER	1	M51.12.7.380.024	- 53			\$	999.31
16	COVER, TOW LH	1	M51.31.7.380.025				\$	50.77
17	COVER, TOW RH	1	M51.31.7.380.026				\$	50.77
18	REAR BUMPER LOWER SPOILER	1	M51.12.7.380.030				\$	290.29
19	COVER FOR POWER SOCKET	1	M51.12.7.382.306				\$	17.88
20	PDC HOLDER LH	1	M51.12.7.403.267				\$	56.42
21	PDC HOLDER RH	1	M51.12.7.403.266				\$	56.42
22	REAR BUMPER CHROME GARNISH	1	M51.12.7.365.737				\$	117.58
23	BREATHER COVER	1	M51.12.7.302.547				\$	103.87
24	GUIDE FOR BUMPER LH	1	M51.12.7.318.755				\$	191.43
25	GUIDE FOR BUMER RH	1	M51.12.7.318.756				\$	191.43
26	C-CLIP	6	B07.14.7.311.312				\$	8.58
27	CLIP	4	M07.14.2.754.954				\$	7.04
28	BLIND RIVET	4	M07.14.7.411.141				\$	15.60
29	REAR BUMPER REINFORCEMENT	1	M51.12.7.300.788				\$	609.18

30 WASHER	R-GASKET FOR REINFORCEMENT	2	B51.12.7.300.789	\$ 29.12
31 REAR EN	ND PANEL OUTER	1	M41.00.7.387.866	\$ 462.35
32 BLINDNI	ET N3	34	M83.19.0.301.421	\$ 24.48
33 ADHESI\	/E K5B 195ML	2	B83.19.5.A59.935	\$ 919.10
34 MINI CA	VITY WAX REMOVER 500ML	2	B83.12.0.390.086	\$ 47.98
35 CLEANEI	R R1	2	M83.19.2.211.217	\$ 68.00
36 PUNCH I	RIVET	53	B83.19.2.457.307	\$ 38.16
37 BOLT		14	M83.19.0.301.639	\$ 10.92
38 SEALAN	T D2	2	B83.42.5.A54.7B9	\$ 83.46
39 REAR EN	ID PANEL INNER	111	M41.00.7.402.473	\$ 315.25
40 REAR VE	NTILATION	1	M64.22.9.303.806	\$ 44.13
41 ULTRASO	ONIC SENSOR OUTER	2	M66.20.9.302.548	\$ 1,003.60
42 ULTRASO	ONIC SENSOR INNER	2	B66.20.9.274.428	\$ 660.54
43 SENSOR	GASKET	4	B66.20.9.283.203	\$ 27.56
44 TAIL LIG	HT LH	1	M63.21.7.435.133	\$ 526.04
45 TAIL LIG	HT RH	1	M63.21.7.435.134	\$ 526.04
46 CHROMI	E RING LH	1	M63.21.8.495.331	\$ 60.32
47 CHROM	E RING RH	1	M63.21.8.495.332	\$ 60.32
48 HEAT IN:	SULATION FOR REAR BUMPER	1	M51.48.7.375.659	\$ 91.72
49 REAR FE	NDER ARCH LH	1	M51.77.7.318.829	\$ 153.59
50 REAR FE	NDER ARCH RH	1	M51.77.7.318.830	\$ 153.59
51 BONNET		1	M41.00.8.499.868	\$ 1,433.70
52 HINGE R	н	1	M41.00.7.370.302	\$ 108.42
53 BONNET	DAMPER	1	M51.23.7.300.567	\$ 138.84
54 CATCH B	RACKET	2	M51.23.7.247.080	\$ 70.46
55 TWIST PI	ROTECTION	2	M51.23.7.300.579	\$ 17.04
56 TRIM RIM	NG, HEADLIGHT LH	1	M51.13.7.300.631	\$ 92.89
57 TRIM RIM	NG, HEADLIGHT RH	1	M51.13.7.300.632	\$ 92.89
58 TRIM RIN	NG CLIPS	12	M51.13.2.752.145	\$ 48.36
59 FRONT B	UMPER	1	M51.11.7.379.432	\$ 830.96
60 SUPPOR	T, FOGLAMP LH	1	M51.11.7.302.507	\$ 72.73
61 SUPPOR	T, FOGLAMP RH	1	M51.11.7.302.508	\$ 72.73
62 FRONT B	UMPER REINFORCEMENT	1	M51.11.7.301.577	\$ 457.99
63 FRONT B	UMPER SPONGE	1	M51.64.7.301.589	\$ 64.61
64 SUPPORT	T FOR BUMPER	2	M51.11.7.337.802	\$ 55.00
65 FRONT B	UMPER LOWER REINFORCEMENT	1	M51.11.7.301.578	\$ 178.29
66 LOWER F	REINFORCEMENT BRACKET LH	1	M51.11.7.301.587	\$ 104.72
67 LOWER F	REINFORCEMENT BRACKET RH	1	M51.11.7.301.588	\$ 104.72
68 REINFOR	CEMENT BRACKET LH	1	M51.11.7.406.389	\$ 123.31
69 REINFOR	CEMENT BRACKET RH	1	M51.11.7.406.390	\$ 123.31
70 FRONT G	RILLE	1	M51.13.7.335.529	\$ 284.57
71 FRAME F	OR GRILLE CHROME	1	M51.13.7.300.589	\$ 153.66
72 BUMPER	CENTER COVER	1	M51.11.7.337.790	\$ 148.07
73 TOWING	COVER	1	M51.11.7.302.479	\$ 42.64
74 CHROME	FRAME LOWER	1	M51.11.7.355.238	\$ 136.82
75 AIR INLE	Γ FINISHER LH	1	M51.11.7.355,239	\$ 91.45

76	FRONT BUMPER LOWER SPOILER	1		M51,11.7.301,622				\$	228.34
77	FRONT BUMPER LOWER GRILLE	1		M51.11.7.337.793				\$	116.42
78	HEADLIGHT, LH	1		M63.11.8.737.595				\$	2,728.96
79	HEADLIGHT RH	1		M63.11.8.737.596				\$	2,728.96
80	FOGLAMP LH	1		M63.11.7.497.767				\$	580.84
81	FOGLAMP RH	1		M63.11.7.497.768				\$	580.84
82	CROSSLINK, FRONT	1		B51.64.7.434.544				\$	168.35
83	SUPPORT LEFT	1		M51.64.7.307.873				\$	168.74
84	SUPPORT RIGHT	1		M51.64.7.307.874				\$	168.74
85	V-BRACE BAR	1		M51.64.7.435.400				\$	164.02
86	MINI EMBLEM	1		M51.14.9.447.805				\$	80.53
87	MINI BADGE REAR	11		M51.14.7.481.902				\$	80.14
88	LABEL, COOLANT	1		M71.23.6.992.810				\$	32.50
89		0		0				\$	9
		,							
				TOTAL PARTS				\$	23,539.11
				TOTAL PARTS COST				\$	23,539.11
		SUPI	PLEME	NTARY					
NO	DESCRIPTION		QTY	PARTS NO	1st	Supp	REVISED		PRICES
1									
2									
3									
	1	N 184			T				
	<u>Labour I</u>	Description						-	
1			NEL & A	LL ACCIDENT				\$	5.880.00
1	TO REMOVE & REPLACE TAILGATE, REAR BUMPER,	REAR END PA						\$	5,880.00
1		REAR END PA						\$	5,880.00
	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A	REAR END PA LL AREAS AFFE	CTED BY	THE ACCIDENT.					
	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A TO REMOVE & REPLACE BONNET, FRONT BUMPER	REAR END PA LL AREAS AFFE R, REINFORCEN	CTED BY	THE ACCIDENT				\$	
2	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A	REAR END PA LL AREAS AFFE R, REINFORCEN	CTED BY	THE ACCIDENT					
	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A TO REMOVE & REPLACE BONNET, FRONT BUMPER	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF	CTED BY	THE ACCIDENT.  ALL ACCIDENT  BY THE ACCIDENT.					3,360.00
2	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPER DAMAGE AREAS ON FRONT PORTION. TO REPAIR	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF	CTED BY	THE ACCIDENT.  ALL ACCIDENT  BY THE ACCIDENT.				\$	3,360.00
2	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPER DAMAGE AREAS ON FRONT PORTION. TO REPAIR	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL				\$	3,360.00 2,600.00
3	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPEF DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:  TO REPSPRAY DAMAGE AREAS ON FRONT PORTIO	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA N: BONNET, FF	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL				\$	2,600.00 1,800.00
3	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPEF DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA N: BONNET, FF	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL				\$	2,600.00 1,800.00
2	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPEF DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:  TO REPSPRAY DAMAGE AREAS ON FRONT PORTIO	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA N: BONNET, FF	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL				\$	2,600.00 1,800.00
3 4	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPER DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:  TO REPSPRAY DAMAGE AREAS ON FRONT PORTIO  TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CU  TO CARRY-OUT BODY CAVITY PRESERVATION.	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA N: BONNET, FF	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL			NETT	\$ \$	3,360.00 2,600.00 1,800.00 350.00
3 4 5 6	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPEF DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:  TO REPSPRAY DAMAGE AREAS ON FRONT PORTIO  TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CU	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA N: BONNET, FF	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL			NETT	\$ \$	3,360.00 2,600.00 1,800.00 350.00
3 4 5 6	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPER DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:  TO REPSPRAY DAMAGE AREAS ON FRONT PORTIO  TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CU  TO CARRY-OUT BODY CAVITY PRESERVATION.	REAR END PA LL AREAS AFFE R, REINFORCEN ALL AREAS AFF TAILGATE, REA N: BONNET, FF	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL			NETT	\$ \$	3,360.00 2,600.00 1,800.00 350.00 250.00
3 4 5 6 7	TO REMOVE & REPLACE TAILGATE, REAR BUMPER, DAMAGE AREAS ON REAR PORTION. TO REPAIR A  TO REMOVE & REPLACE BONNET, FRONT BUMPER DAMAGE AREAS ON FRONT PORTION. TO REPAIR  TO RESPRAY DAMAGE AREAS ON REAR PORTION:  TO REPSPRAY DAMAGE AREAS ON FRONT PORTIO  TO SUPPLY SPRAY TEROSTAT SEALANT ON THE CU  TO CARRY-OUT BODY CAVITY PRESERVATION.  TO TRANSFER THE TAILGATE MECHANISM.	REAR END PA LL AREAS AFFE  R, REINFORCEN ALL AREAS AFF  TAILGATE, REA N: BONNET, FF  TTING AREAS.	MENT & A	ALL ACCIDENT BY THE ACCIDENT. PER, REAR END PANEL				\$ \$ \$	5,880.00  3,360.00  2,600.00  1,800.00  250.00  420.00  120.00

10	TO SUPPLY & INSTALL THE TAILGATE, REAR FENDER LH, BONNET STIC	KER.	NETT		\$ 375.00
11	TO TRANSFER THE REVERSE SENSORS.				\$ 300.00
12	TO SUPPLY 2 PC NUMBER PLATE WITH CASING.		NETT		\$ 140.00
13	TO CHECK ELECTRICAL SYSTEM FOR PROPER FUNCTIONING.				\$ 250.00
14	TO REPROGRAMME AFTER THE ACCIDENT REPAIR WORKS.				\$ 350.00
15	SUNDRIES.		NETT		\$ 50.00
		TOTAL LABOUR	\$	2	\$ 16,805.00
	REMARKS:	TOTAL PARTS	\$	2	\$ 23,539.11
	THIS IS ONLY AN ESTIMATE FROM VISUAL INSPECTION AND SHOULD THERE	TOTAL	\$	2	\$ 40,344.11
	BE MORE DAMAGES FOUND DURING THE PROCESS OF REPAIRING, YOU WILL	LESS EXCESS	\$	Ę	\$
	BE INFORMED BEFORE THE REPAIRS ARE BEING CARRIED OUT.	TOTAL AFTER EXCESS	\$		
		GST 7%	\$	*	\$ 3#
	TAKE NOTE THAT SHOULD YOU DECIDE NOT TO PROCEED WITH THE REPAIRS, A	GRAND TOTAL	\$	8	\$ ( <del>e</del> )

QUOTATION FEE OF \$400.00 WILL BE APPLY AS ACCORDINGLY FOR MAN-HOURS INVOLVED IN SOURCING FOR PARTS PRICE AS WELL AS LABOUR CHARGES.



## SINGAPORE ACCIDENT STATEMENT

#### IMPORTANT NOTICE

1. Please report <u>correctly</u> the details of the accident to speed up the claims process.
 2. This Form must be <u>completed by the Policyholder and/or the Actual Driver</u>

3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or witholding of material facts may allow insurance companies to repudiate policy liability.

4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.

5. Any false reporting may be referred to the Police for investigation. 6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.

7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### **ACCIDENT STATEMENT**

Date of Submission 12/10/2022 20:23 (SGT) Reported by Date of Accident 11/10/2022 10:00 (SGT) Exact Location of Accident Singapore Additional Location Information PIE (PAYA LEBAR) Country/State of Loss Singapore

## **DETAILS OF OWN VEHICLE**

Vehicle Registration Number SMW9860A INSURED/POLICYHOLDER

Is company? No Name Of Registered Owner PHUAH PENG HOCK NRIC No SXXXX772I Email Address PHUAH.PH@GMAIL.COM Mobile Phone No (Phone) +65-96266828

Alternative Phone No

#### VEHICLE PARTICULARS

Manufacturer Mini Model ..... One Variant ..... Exact purpose for which vehicle was being used at time of Private use

accident Are you claiming under your own insurance policy for repair to

your vehicle? Vehicle Category

Transmission

#### INSURANCE COMPANY

Name of Insurance Company Policy Number / Cover Note Number

AIG Asia Pacific Insurance Pte. Ltd.

No - Claiming third party

Private car

Auto 1499

#### DRIVER

Name of Driver NRIC No. Date Of Birth Occupation

PHUAH KEN HAO SXXXX047B 29/12/1997 Indoor

Date Of Driving Pass 15/03/2018 Driving experience 4 YEARS AND 7 MONTHS Gender Male Mobile Number (Phone) +65-82882929 Alt. Phone Number Email Address KENHAO29@HOTMAIL.COM Address 63 TAMPINES AVE 1 #12-01 Address complement Postcode Is the driver the policyholder? Nο If No, Relationship of the Driver with the Insured Child Does Driver Own Other Vehicles? Nο Vehicle Registration Number of Other Vehicle Owned by Driver Insurance Company of Other Vehicle Owned by Driver GENERAL INFORMATION OF THE ACCIDENT Type of Accident .... Chain Collision Weather Conditions Clear Road Surface Dry OTHER INFORMATION Was any foreign vehicle involved in the accident? No Number of vehicles involved in the accident Was anybody injured in the Accident? No Was any injured conveyed to hospital by ambulance? Was any other vehicle or property damaged? Yes Number of Passengers (Including Driver) 1 Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?
Translator's name No Translator's ID Translator's phone number Translator's email Original language used in the statement DETAILS OF POLICE ACTION Was the accident reported to the police? No Was notice of intended Prosecution given? No If yes, against whom? CIRCUMSTANCES OF ACCIDENT REFER TO ATTACH ATTACHMENT(S) Are accident photos available for attachment? Yes Was there any video captured by Car Camera? Yes **DETAILS OF OTHER VEHICLE PROPERTY 1** Vehicle Registration Number SMG4727U Vehicle Manufacturer Mazda Vehicle Model

## Vehicle Variant Vehicle Colour

Vehicle Category Name of Driver NRIC No

3

Private car

ABDUL RAZAK BIN ABU BAKAR

SXXXX220E

1

## DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number  Vehicle Manufacturer	SJX8280K Mazda
Vehicle Model	5
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	HONG QIXIAN
NRIC No	SXXXX824C
Contact Number	(Phone) +65-96544995
Address	
Address complement	*
Postcode	2
Insurance Company Name	*
Nature Of Damage	-
Details of property damaged in accident	
No. Of Passenger (Including Driver)	1

## SKETCH PLAN

## IMPORTANT NOTICE

- 1. Please report correctly the details of the accident to speed up the claims process.
- 2. This Form must be completed by the Policyholder and/or the Authorised Driver.
- 3. Information provided must be as <u>truthful</u> and <u>accurate as possible</u>. Any wilful misrepresentation or withholding of material facts may allow insurance companies to <u>repudiate policy liability</u>.
- 4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
- 5. Any false reporting may be referred to the Police for investigation.
- 6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
- 7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
- 8. Consent under the Personal Data Protection Act (PDPA)

Lunderstand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

Policyholder's Signature

Date & Time: 12-10-12 0930

Driver's Signature


(If driver is not the policyholder)

Date & Time: 12-10-22 0930

Reporting Centre Personnel's Signature

Name: Deblik

NRIC/FIN No .: GXXX935W-



## DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

SET SMW9860A LICENSE PLATE NO: ACCIDENT DATE: 11-10-2012 82882929 CONTACT NUMBER: 10:00 AM EMAIL: Kenhau 29 @hotmail.com ACCIDENT TIME: LOCATION: PIÉ Front car had emergency brake because of the car in front, and general traffic. I followed suit and emergency brake, and subsequently was hit by the car behind. hit the front rar as well, as I was pushed forward causing my cons to

NOTE: PLEASE NOTE THAT YOUR INSURER MAY HAVE 14 DAYS TIME FRAME FOR YOU TO SUBMIT AN OWN DAMAGE CLAIMS UNDER YOUR OWN POLICY.

PLEASE CHECK YOUR POLICY FOR MORE INFORMATION

PLEASE STATE:

( ) CLAIM OWN POLICY

(/) CLAIM THIRD PARTY

( )REPORTING ONLY

## **DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature

Date & Time: 12-10-12 0130

Driver's Signature

(If driver is not the policyholder)

Date & Time: 12-10-22 0930

Reporting Centre Personnel's Signature

Debbie Name:

NRIC/FIN No .: GYXXX 936W

## > Back to OneMotoring

Land Transport Q Authority

Land Transport Authority 10 Sin Ming Drive Singapore 575701

GST Registration No.: M4-0006529-2

Print Date/Time:

12 Oct 2022 / 20:01:54

Receipt Date/Time # 12 Oct 2022 / 20:01:54

## Tax Invoice/Receipt

Receipt No.: ITNET-00000-221012-003693

Previous Receipt No.:

S/N Item Description/ Business Transaction Reference No.		Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Result of Insurance Enquiry - SMG4727U As at 11 Oct 2022/10:00:00 Insurance Co: INDIA INT'L INS PTE LTD Insurance Enquiry - SMG4727U				
Enquiry Fee 20221012200037086355		7.00	0.49	7.49
	Sub-Total	7.00	0.49	7.49
	<b>Total Before Rounding</b>	7.00	0.49	7.49
	Rounding Difference			0.04
	Total Amount Payable			7.45
0.00	Paid By			
nn 4860 A	454750XXXXXX9785	eNETS	Credit Card	7.45
	Total			7.45
	Cash Change			0.00
	Tendered Amount			7.45
	Excess Refundable Amount			0.00

#### THANK YOU AND HAVE A NICE DAY!

Please ensure that all payments to the Authority are good and promptly settled by the payment service provider / financial institution. Otherwise, the transaction and receipt is considered void and late fee may apply.