

SME MOTOR PTE LTD

Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883
 TEL: 6747 6106 (6 lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

TAIPIING INSURANCE (SINGAPORE) PTE
 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 63896111 FAX: 62247478
 Motor Claim Department

ESTIMATE

No : 22101901
 Date : 19/10/2022
 Policy No : 21-MU003263-R05
 Veh Reg No : SJL7561U
 Make / Model : HONDA JAZZ
 Your Ref No : 22/CN/TP-219(10)
 Claim Type : THIRT PARTY
 Accident Date : 19/10/2022
 TP Veh Reg No : SJP9527K

Not Authorised
 25/10/22
 1/5# 7300
 8 days
 2 hrs, 45 min

Discription	Quantity	Unit Price	Amount
LIST PRICE:			
1 REAR WINDSCREEN MOULDING <i>all</i>	2 PCS	\$58.00	\$116.00
2 REAR GATE <i>30/30</i>	1 PC		\$925.00
3 REAR GATE LOGO <i>all</i>	1 PC		\$60.00
4 REAR GATE "JAZZ" PLATE <i>all</i>	1 PC	35.00	\$75.00
5 REAR GATE LOCK <i>10/30</i>	1 PC	38.00	\$145.00
6 REAR GATE INNER RUBBER <i>7m</i>	1 PC		\$195.00
7 REAR GATE OUTER GARNISH <i>one</i>	1 PC		\$185.00
8 REAR GATE INNER TRIMBOARD <i>11</i>	1 PC		\$215.00
9 INNER TRIM BOARD CLIPS <i>11</i>	10 PCS	\$7.90	\$79.00
10 REAR BUMPER <i>dis</i>	1 PC		\$550.00
11 REAR BUMPER RETAINER <i>set</i>	2 PCS	\$28.00	\$56.00
12 REAR BUMPER CLIPS <i>all</i>	10 PCS	5.90	\$59.00
13 TAIL LAMP <i>one</i>	2 PCS	\$295.00	\$590.00
14 REAR END PANEL <i>30/30</i>	1 PC	296.60	\$350.00
15 REAR END PANEL TOP TRIM <i>7m</i>	1 PC		\$85.00
16 REAR SPARE TYRE FLOOR PANEL <i>all</i>	1 PC		\$810.00
17 SPARE TYRE BOARD COVER <i>woped</i>	1 PC		\$245.00
18 REAR EXHAUST BOX <i>all</i>	1 PC		\$435.00
19 FRT GRILLE <i>one</i>	1 PC		\$195.00
20 GRILLE LOGO <i>set</i>	1 PC		\$48.00
21 FRT BUMPER <i>7m</i>	1 PC		\$585.00
22 FRT BUMPER CLIPS <i>all</i>	10 PCS	\$5.50	\$55.00
23 FRT BUMPER RETAINER <i>set</i>	2 PCS	\$38.00	\$76.00
24 FRT BUMPER TOW COVER <i>all</i>	1 PC		\$35.00
25 FRT BUMPER REINFORCEMENT <i>30/30</i>	1 PC	185.80	\$335.00
26 FRT BUMPER LOWER GRILLE <i>7m</i>	1 PC		\$165.00
27 HEADLAMP <i>one</i>	2 PCS	\$590.00	\$1,180.00
28 HEADLAMP LOWER BRACKET <i>11</i>	2 PCS	\$45.00	\$90.00
29 AIRCON CONDENSER <i>set</i>	1 PC		\$655.00

TOTAL
 -20.00%
 \$8,594.00
 \$1,718.80
 \$6,875.20

6676.4

6953.6

202
 5562.88

SME MOTOR PTE LTD

Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883
 TEL: 6747 6106 (6 lines) Fax: 6744 2368
 Email: service@smemotor.com.sg Website: www.smemotor.com.sg
 Co. & GST Reg. No: 201119451E

From JIA TAIPING INSURANCE (SINGAPORE) PTE
 1 ANSON ROAD #16-00
 SPRINGLEAF TOWER
 SINGAPORE 079909
 63896111 FAX: 62247478
 Motor Claim Department

ESTIMATE
 No : 22101901
 Date : 19/10/2022
 Policy No : 21-MU003263-R05
 Veh Reg No : SJL7561U
 Make / Model : HONDA JAZZ
 Your Ref No : 22/CN/TP-219(10)
 Claim Type : THIRT PARTY
 Accident Date : 19/10/2022
 TP Veh Reg No : SJP9527K

Discription	Quantity	Unit Price	Amount
SPECIAL NET			
1 FRT NUMBER PLATE <i>but</i>	1 PC	\$40.00	\$40.00 ✓
2 REAR NUMBER PLATE <i>but</i>	1 PC	\$40.00	\$40.00 ✓
3 REAR WINDSCREEN GUM <i>nee</i>	1 PC	\$60.00	\$60.00 40
4 REAR GATE SEALANT <i>ni</i>	1 PC	\$40.00	\$40.00 X
5 REAR END PANEL SEALANT <i>ni</i>	1 PC	\$40.00	\$40.00 X
6 REAR FLOOR PANEL SEALANT <i>ni</i>	1 PC	\$40.00	\$40.00 X
7 REVERSE SENSOR <i>shud</i>	1 PC <i>1cef</i>	\$250.00	\$250.00 200
TOTAL			\$510.00

Labour			
1 WIRE CHECKING		\$40.00	30
2 REMOVE & REFIX AIRCON AND GAS		\$100.00	20
3 REMOVE & REFIX REAR WINDSCREEN		\$120.00	✓
4 REMOVE & REFIX REAR SENSOR		\$50.00	✓
5 REMOVE & REFIX REAR BOOT UPHOLSTERY		\$100.00	60
6 TRANSFER REAR GATE COMPONENTS		\$100.00	80
7 CAVITY PROTECTION ON AFFECTED AREAS		\$100.00	60
8 REMOVE & REFIX REAR EXHAUST BOX		\$100.00	X
9 LABOUR CHARGE (FRT)	11	\$600.00	400
10 SPRAY PAINTING (FRT)		\$600.00	500
11 LABOUR CHARGE (REAR)		\$1,200.00	900
12 SPRAY PAINTING (REAR)		\$1,100.00	900
TOTAL			\$4,210.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Amount Before Excess \$11,595.20
 Add GST @7% \$811.66
 Total Amount Payable \$12,406.86

SME MOTOR PTE LTD

SIGNED SIGNATURE

4816.96

1-5562.88

S.N-360

3200

9122.88

7298

SME MOTOR PTE LTD

Kaki Bukit Ave 6, #02-15@ Kaki Bukit, Singapore 417883
TEL: 6747 6106 (6 lines) Fax: 6744 2368

AGL, REG, #11

service@smemotor.com.sg Website: www.smemotor.com.sg
Co. & GST Reg. No: 201119451E

From: FAIPING INSURANCE (SINGAPORE) PTE

800-000-0000 ROAD #16-00

BRIDGELEAF TOWER

SINGAPORE 079909

63896111 FAX: 62247478
Motor Claim Department

SUPPLEMENTARY

No : 22101901
Date : 11/11/2022
Policy No : 21-MU003263-R05
Veh Reg No : SJL7561U
Make / Model : HONDA JAZZ
Your Ref No : 22/CN/TP-219(10)
Claim Type : THIRT PARTY
Accident Date : 19/10/2022
TP Veh Reg No : SJP9527K

Discription
LIST PRICE:

REAR FENDER INNER TRIM BOARD

Quantity

Unit Price

S\$

Amount

S\$

\$277.20

2 PCS

de/2017

\$277.20

TOTAL

\$55.44

-20.00%

\$221.76

Amount Before Excess

\$0.00

Add GST @7%

\$0.00

Total Amount Payable

\$0.00