



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL : NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS  
WORKSHOP : UBI ROAD 1  
CONTACT NO : 6366 2323  
FAX NO : 6841 1183  
REFERENCE : PA/OD/0905/2022/EQ  
DATE : 19-Oct-22  
WIP : 46478

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 19/10/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**  
78 SHENTON WAY  
#07-16 AIG BUILDING  
SINGAPORE 079120  
Attn: Motor Claims Dept  
Tel: **6880 4602** - Fax: **6880 4838**

OWNER'S NAME : MS KEK SIOW YEN ESTHER  
ADDRESS : 149 PASIR RIS GROVE  
#07-04  
SINGAPORE 518139  
TELEPHONE : HP +65 96933945  
TYPE OF CLAIM : OWN DAMAGE CLAIM  
POLICY NO :  
VEHICLE NO : **SLJ 2274 T**  
MODEL CODE : AUDI Q3 1.4 TFSI S-TRONIC  
MODEL YEAR : 30/11/2016  
ENGINE NO : CZD 250776  
CHASSIS NO : WAUZZZ8U1HR022697  
MILEAGE : -  
DATE IN : -  
ESTIMATED BY : JOHNNY BOO / ALLAN WU  
ACCIDENT DATE : 15-Oct-22  
PLACE OF ACCIDENT : U TURN OF BAIN ST



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLJ 2274 T**

S/N	NATURE OF JOBS		ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY.	S/N S	360.00	<del>X</del> <del>360</del> 360
2	TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N S	400.00	X
3	TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	S	2,400.00	1000
4	TO RESPRAY FRONT BUMPER AND LHS FRONT FENDER.	S	2,500.00	1100
5	TO CARRY OUT DIAGNOSTIC CHECK	S/N S	192.00	/
<b>TOTAL LABOUR CHARGES</b>			<b>\$ 5,852.00</b>	

# PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL : NORA.KHALI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

## MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLJ 2274 T

		DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER <i>X Repair</i>	1	\$ 2,376.00	
2	FRONT BUMPER AIR GUIDE GRILLE - LH <i>X Repair</i>	1	\$ 171.00	
3	FRONT BUMPER CLOSING ELEMENT - LOWER <i>X Repair</i>	1	\$ 196.00	
4	FRONT BUMPER SPOILER <i>X Repair</i>	1	\$ 426.00	340.80
5	FRONT FENDER - LH <i>X Repair</i>	1	\$ 1,014.00	
6	FRONT FENDER ATTACHMENT PARTS <i>X</i>	1	\$ 73.00	
7	FRONT FENDER BRACE - LH <i>X</i>	1	\$ 116.00	} <i>NN</i>
8	FRONT FENDER BRACKET - LH <i>X</i>	1	\$ 92.00	
9	FRONT FENDER RIVET <i>X</i>	7	\$ 27.00	
10	FRONT WHEEL HOUSING LINER - LH <i>X</i>	1	\$ 260.00	
11	FRONT WHEEL SPOILER - LH <i>X</i>	1	\$ 82.00	
12	HEADLIGHT MOUNTING - LH <i>X NN</i>	1	\$ 132.00	
13	HEADLIGHT RETAINING PLATE - LH <i>X NN</i>	1	\$ 97.00	
14	HEADLIGHT - LH <i>X NN</i>	1	\$ 8,294.00	
15	LIFT CYLINDER - LH <i>X</i>	1	\$ 231.00	
16	LIFT CYLINDER HOSE <i>X</i>	1	\$ 204.00	
17	FRONT WHEEL COVER - LH / RH <i>X NN</i>	2	\$ 544.00	435.20
18	RADIATOR AIR GUIDE - LH <i>X NN</i>	1	\$ 30.00	
19	SUNDRIES <i>X NN</i>		\$ 400.00	
<b>TOTAL SPARE PARTS</b>		:	\$ 14,785.00	
<b>TOTAL LABOUR CHARGES</b>		:	\$ 5,852.00	
<b>GRAND TOTAL</b>		:	\$ 20,617.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED  
 SPARE PARTS ARE SPECIAL NETT



55 UBI ROAD 1, SINGAPORE 408699  
TEL : 6366 2323 FAX : 6841 1183  
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

*4 Days.  
Good day  
refue parts  
20/10.*

NAME :  
SURVEYED DATE :  
AUTHORISED DATE :  
EXCESS COST :  
LIABILITY :  
REMARKS :

**PLEASE NOTE :** THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal repair work allowed
- Supplemental charges are payable and is subject to approval by the Insurance Company

Acknowledged by Repairer  
Signature:  
Date:

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT