

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATE** : ACCIDENT REPAIRS  
**WORKSHOP** : UBI ROAD 1  
**CONTACT NO** : 6366 2323  
**FAX NO** : 6841 1183  
**REFERENCE** : PA/OD/0909/2022/EQ  
**DATE** : 20-Oct-22  
**WIP** : 46489

**VEHICLE NOT IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/10/2022**

**AIG ASIA PACIFIC INSURANCE PTE LTD**

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

**Tel: 6880 4602 - Fax: 6880 4838**

**Hi Adrian**

**3 days - Johnny Boo**

**27-Feb-23**

**OWNER'S NAME** : MS FENG LIYUAN  
**ADDRESS** : 107 WEST COAST VALE  
#16-03  
SINGAPORE 126751  
**TELEPHONE** : HP +65 90372113  
**TYPE OF CLAIM** : OWN DAMAGE CLAIM  
**POLICY NO** :  
**VEHICLE NO** : **SNF 8122 G**  
**MODEL CODE** : AUDI Q5 2.0 TFSI QU S-TRONIC  
**MODEL YEAR** : 23/6/2022  
**ENGINE NO** : DGK 005631  
**CHASSIS NO** : WAUZZZF6M2089465  
**MILEAGE** : -  
**DATE IN** : -  
**ESTIMATED BY** : JOHNNY BOO / ALLAN WU  
**ACCIDENT DATE** : 16-Oct-22  
**PLACE OF ACCIDENT** : 277 ORCHARD ROAD, SINGAPORE 238858  
LEVEL 5 CARPARK

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SNF 8122 G**

| S/N                         | NATURE OF JOBS                                                                                                                                   |        | ESTIMATED<br>CHARGES | SURVEYOR'S<br>RECOMMENDATIONS |
|-----------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------|--------|----------------------|-------------------------------|
| 1                           | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID. | S/N \$ | 480.00               | \$ <b>480.00</b>              |
| 2                           | TO REMOVE AND TRANSFER LHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.                                                                            | S/N \$ | 400.00               |                               |
| 3                           | TO DISMANTLE AND RENEW FRONT BUMPER, LHS FRONT FENDER AND LHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.   | \$     | 2,400.00             | \$ <b>500.00</b>              |
| 4                           | TO RESPRAY FRONT BUMPER, LHS FRONT BUMPER LOWER SPOILER, LHS FRONT FENDER AND BOTH FRONT WHEEL ARCH TRIMS.                                       | \$     | 3,000.00             | \$ <b>1,000.00</b>            |
| 5                           | TO CARRY OUT DIAGNOSTIC CHECK                                                                                                                    | S/N \$ | 192.00               | \$ <b>192.00</b>              |
| <b>TOTAL LABOUR CHARGES</b> |                                                                                                                                                  | :      | <b>\$ 6,472.00</b>   | <b>\$ 2,172.00</b>            |

55 UBI ROAD 1, SINGAPORE 408699  
 TEL : 6366 2323 FAX : 6841 1183  
 EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 8122 G**

|                              |                                            |     | DAMAGED PARTS & PRICES |         |          |
|------------------------------|--------------------------------------------|-----|------------------------|---------|----------|
| S/N                          | PARTS DESCRIPTION                          | QTY | S/NETT                 | REMARKS |          |
| 1                            | FRONT BUMPER                               | 1   | \$ 1,705.00            | \$      | 1,160.80 |
| 2                            | FRONT BUMPER SECURING STRIP - LH           | 1   | \$ 42.00               |         |          |
| 3                            | FRONT BUMPER CLOSING ELEMENT - LH          | 1   | \$ 126.00              |         |          |
| 4                            | FRONT BUMPER GRILLE - CENTER               | 1   | \$ 298.00              |         |          |
| 5                            | FRONT PARKING AID SENSOR SUPPORT - LH / RH | 2   | \$ 66.00               |         |          |
| 6                            | FRONT BUMPER UNDERRUN BAR - CENTER         | 1   | \$ 968.00              |         |          |
| 7                            | FRONT BUMPER SPOILER - LH                  | 1   | \$ 252.00              | \$      | 201.20   |
| 8                            | FRONT BUMPER CLOSING ELEMENT               | 1   | \$ 471.00              |         |          |
| 9                            | FRONT BUMPER AIR GUIDE GRILLE - LH         | 1   | \$ 267.00              | \$      | 213.20   |
| 10                           | FRONT PARKING AID SENSOR SUPPORT - LH      | 1   | \$ 38.00               |         |          |
| 11                           | FRONT BUMPER TRIM - LH                     | 1   | \$ 179.00              |         |          |
| 12                           | FRONT PARKING AID SENSOR - INNER / OUTER   | 2   | \$ 531.00              |         |          |
| 13                           | FRONT PARKING AID SEAL RING                | 4   | \$ 10.00               |         |          |
| 14                           | HORN LOW TONE - LH                         | 1   | \$ 208.00              |         |          |
| 15                           | FRONT FENDER - LH                          | 1   | \$ 1,462.00            |         |          |
| 16                           | FRONT FENDER BRACE - LH                    | 1   | \$ 250.00              |         |          |
| 17                           | FRONT WHEEL HOUSING LINER - LH             | 1   | \$ 286.00              |         |          |
| 18                           | FRONT WHEEL SPOILER - LH                   | 1   | \$ 181.00              | \$      | 144.40   |
| 19                           | FRONT WHEEL COVER - LH / RH                | 2   | \$ 1,418.00            | \$      | 1,134.40 |
| 20                           | HEADLIGHT MOUNTING - LH                    | 1   | \$ 132.00              |         |          |
| <b>SUB TOTAL SPARE PARTS</b> |                                            | :   | \$ 8,890.00            | \$      | 2,854.00 |

ALL CHARGES ARE NOT INCLUSIVE OF GST  
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APROVED  
 SPARE PARTS ARE SPECIAL NETT.



55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)**MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SNF 8122 G**

|                             |                                 |            | DAMAGED PARTS & PRICES |           |                 |
|-----------------------------|---------------------------------|------------|------------------------|-----------|-----------------|
| S/N                         | PARTS DESCRIPTION               | QTY        | S/NETT                 | REMARKS   |                 |
|                             |                                 | <i>c/f</i> |                        | <i>\$</i> | <i>2,854.00</i> |
| 21                          | HEADLIGHT - LH                  | 1          | \$ 7,440.00            |           |                 |
| 22                          | LIFT CYLINDER - LH              | 1          | \$ 153.00              |           |                 |
| 23                          | LIFT CYLINDER HOSE              | 1          | \$ 145.00              |           |                 |
| 24                          | FRONT BUMPER GUIDE SECTION - LH | 1          | \$ 43.00               |           |                 |
| 25                          | SUNDRIES                        |            | \$ 400.00              |           |                 |
| <b>TOTAL SPARE PARTS</b>    |                                 | :          | <b>\$ 17,071.00</b>    | <b>\$</b> | <b>2,854.00</b> |
| <b>TOTAL LABOUR CHARGES</b> |                                 | :          | <b>\$ 6,472.00</b>     | <b>\$</b> | <b>2,172.00</b> |
| <b>GRAND TOTAL</b>          |                                 | :          | <b>\$ 23,543.00</b>    | <b>\$</b> | <b>5,026.00</b> |

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED

SPARE PARTS ARE SPECIAL NETT.

bl=14/02/23

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: [NORA.KHAI@PREMIUMAUTO.COM.SG](mailto:NORA.KHAI@PREMIUMAUTO.COM.SG) / [CLAIMS@PREMIUMAUTO.COM.SG](mailto:CLAIMS@PREMIUMAUTO.COM.SG)

**NAME** :  
**SURVEYED DATE** :  
**AUTHORISED DATE** :  
**EXCESS COST** :  
**LIABILITY** :  
**REMARKS** :

**PLEASE NOTE** : THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY.  
FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,  
PREMIUM AUTOMOBILES PTE LTD

JOHNNY BOO  
BODY REPAIR MANAGER

ALLAN WU  
CLAIMS CONSULTANT