

ASS. REC. BY:

REF:

C72 / 22010453/kw

C

Kenneth

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its

repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: GBJ1074D Yr Regn: 01, 19

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: Toy Dyna c.c. 2982

Colour: Silver A/C: Insured / Std / NI / NA

Sp. Reading: 144671 T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: JTFA 7354001C 212226

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: B.S 195R15X8

R: Yoko 155R12X8(10)

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or _____

Front _____ Rear _____

R/Bal. 9 mm R/Bal. 44 mm

L/Bal. 2 mm L/Bal. 22 mm

D.O.A. 19/10/22 D.O.I. 10/11/2022

Survey held at _____

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

<input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
N/S	O/S
<input type="checkbox"/>	<input type="checkbox"/>

Date / Time	Action / Instruction
16/2	3236.78 Cash @ 05 days (Red \$0/0%) - workshop using Audatex report as Estimate... Fair & Reasonable

[Signature]
20/2/2023

Date/Time, File Pass to?

20/02/2023

1) Typist

Date/Time, File Return to?

2)

: Prell. Report

: Final Report

Days Of Repair: 05

Resurvey No. of Trip: _____

Add Fee: : Site Insp (\$

: Interview (\$

: Tech Invs (\$

: Weekend (\$

Survey Fee:

Transportation:

S - RS. SI

Fees

Others

TOTAL

Report Format: OD claim

Lump Sum / I.B.I: (\$ P/P \$3,236.78)

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: DMCVSNW00003422202
Repairer Reference: 73103
Date calculated: 20/10/2022 4:33 PM

Full Report
Registration: GBJ 1074D
Printed: 20/10/2022 4:33 PM

Summary Information

Claim

Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMCVSNW00003422202	Date of Incident:	19/10/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle

Manufacturer: TOYOTA
 Model: DYNA
 Sub Model: 150
 Model Sheet Number: 70 1N 03
 Registration: GBJ 1074D
 VIN number:
 Odometer: 143150

Model Specs

AIR CONDITIONING	FROM 11.2017	FOG LAMPS	WHEELBASE 3350 MM
SINGLE CAB	3.0 LTR 80KW	TYRES 195/75 R15	TWO COAT METALLIC
PREPARE OFF VEHICLE			

*NOT authorized
 Return B4-pain
 Ex 8350/
 5 days*

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT PANEL		60.0	252.00
NO NUMBER	R + R BADGE		2.0	8.40
520011)	R + R FRONT BUMPER		4.0	16.80
520011)	RENEW FRONT BUMPER (REMOVED) INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT		2.0	8.40
751011	R + R RADIATOR GRILLE		3.0	12.60
810121Y)	R + R LEFT HEADLAMP (RADIATOR GRILLE REMOVED)		1.0	4.20
810121Y)	R + R RIGHT HEADLAMP (RADIATOR GRILLE REMOVED)		1.0	4.20
810151A	ADJUST HEADLAMPS		3.0	12.60
NO NUMBER	R + R L/F LOWER CLOSING PANEL		1.0	4.20
NO NUMBER	R + R R/F LOWER CLOSING PANEL		1.0	4.20
554011)	R + R WINDSCREEN INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS		14.0	58.80
670051)	R + R LEFT FRONT DOOR		6.0	25.20

Code	Description	WU	Price SGD
670051)	R + R RIGHT FRONT DOOR	6.0	25.20
NO NUMBER	RENEW FRONT CROSSMEMBER	25.0	105.00
743201)	DETACH + REFIT HEADLINING	4.0	16.80
	INCLUDES: R + R INSIDE MIRROR, PILLAR TRIMS AND SEAT BELTS		
NO NUMBER	R + R L/F LOWER DOOR SEAL	2.0	8.40
NO NUMBER	R + R R/F LOWER DOOR SEAL	2.0	8.40
870031)	R + R HEATING CPL	12.0	50.40
NO NUMBER	R + R EVAPORATOR	4.0	16.80
550451)	R + R INSTRUMENT PANEL	9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	4.20
850171)	R + R WIPER LINKAGE	1.0	4.20
002019)	DRAIN + REFILL COOLANT	3.0	12.60
441101	R + R STEERING WHEEL	2.0	8.40
002889 ZAX	DRAIN AND REFILL AIR CONDITIONING	7.0	29.40
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.80	178.0
Total of Labour			747.60

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
Paint Work SYSTEM AZT Time Basis 10 WU/h			
	FRONT BUMPER NEW PART PAINTING	12.0	
	L/F BUMPER BRACKET NEW PART PAINTING	6.0	
	R/F BUMPER BRACKET NEW PART PAINTING	6.0	
	FRONT LOWER PANEL NEW PART PAINTING	19.0	
	UPPER FRONT PANEL NEW PART PAINTING	8.0	
	L/F LOWER END PANEL SURFACE PAINT	4.0	
	R/F LOWER END PANEL SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	27.86
0293	L/F BUMPER BRACKET NEW PART PAINTING	1.55
0294	R/F BUMPER BRACKET NEW PART PAINTING	1.55
0414	FRONT LOWER PANEL NEW PART PAINTING	22.00
0418	UPPER FRONT PANEL NEW PART PAINTING	10.32
0889	L/F LOWER END PANEL SURFACE PAINT	0.75
0890	R/F LOWER END PANEL SURFACE PAINT	0.75

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		59.0	
Preparation Main Work Metal	2.50	25.0	105.00
Total	8.40	84.0	352.80

Material Cost - Paint

New Part Painting	63.28
Surface-/Blend Paint	1.50
Material-constant Metal Preparation	28.60
Total	93.38

Spare Parts

				prices as at 2015-06-01/01	
Code	Description	Part Number	Part Source	Price SGD	
0485	BADGE MODEL	75311 25100	Original	Nec ✓	25.00
0281	FRONT BUMPER	52101 37985	Original	n ✓	220.00
3010	FRONT CROSSMEMBER	51211 25100	Original	n ✓	100.00
0414	FRONT LOWER PANEL	55711 37110	Original	n ✓	450.00
0411	GRILLE	53111 37A01A0	Original	CM ✓	195.00
0293	L/F BUMPER BRACKET	52012 37070	Original	n ✓	100.00
0561	LEFT HEADLAMP ASSY	81170 37660	Original	m, CM ✓	300.00
0294	R/F BUMPER BRACKET	52011 37070	Original	n ✓	100.00
0562	RIGHT HEADLAMP ASSY	81130 37660	Original	m, CM ✓	300.00
0418	UPPER FRONT PANEL	55078 37110	Original	n ✓	130.00
1411	WINDSCREEN BOND KIT	PZ49I 00C1131			0.00
1410	WINDSCREEN SEAL	56121 25040	supplementary	Nec ✓	95.00 0.00
1001	FRONT PANEL CLIP	82597 23070	supplementary	Nec ✓	3.00
f: OEM Parts					0.00
n: Non-OEM Parts					1,920.00
u: Used parts					2,018
Savings					1,920.00
Subtotal					1,920.00
Total					1,920.00

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	n ✓ 25.00*
Total Extras		25.00

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

Final Calculation

	SGD	SGD
Parts	1,920.00	
Total Parts	2,018.00	1,920.00
Labour Time Base 10 WU/h		
Total 178.0 WU X 42.00 SGD/h	747.60	
Total of Labour		747.60
Total Of Extras		25.00
Paint Work Time Base 10 WU/h		
Labour Cost 84.0 WU X 42.00 SGD/h	352.80	
Material Cost	93.38	
Total Paint Including Material		446.18
Repair Cost Excludes GST	3,236.78	3,138.78
GST (+7.0%)		219.71
Repair Cost Included GST		3,358.49
Deductions (Excludes GST)		
Deduction For Excess	-350.00	
Total Of Deductions (Excludes GST)		-350.00
Grand Total Excludes GST		2,788.78
GST (+7.0%)		195.21
Grand Total Included GST		2,983.99

Comments

* - USER SUPPLIED DATA
NN - NO MANUFACTURERS CODE EXISTS
) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	19/10/2022 17:59 (SGT)
Reported by	Both
Date of Accident	19/10/2022 09:30 (SGT)
Exact Location of Accident	Tampines Rd, Singapore
Additional Location Information	-
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBJ1074D
INSURED/POLICYHOLDER	
Is company?	Yes
Name Of Registered Owner	SAFETECH ENGINEERING PTE LTD
Company Reg No	2XXXXX322C
Email Address	hoque.safetech@gmail.com
Mobile Phone No	(Phone) +65-87271633
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Toyota
Model	Dyna
Variant	-
Exact purpose for which vehicle was being used at time of accident	Employment
Are you claiming under your own insurance policy for repair to your vehicle?	Yes
Vehicle Category	Commercial vehicle
Transmission	Manual
CC	2982

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMCVSNW00003422202

DRIVER

Name of Driver	HOSSAIN MOHAMMAD SHAHADAT
Passport No/FIN	GXXXX606M
Date Of Birth	24/08/1978
Occupation	Outdoor

Date Of Driving Pass	02/06/2021
Driving experience	1 YEAR AND 4 MONTHS
Gender	Male
Mobile Number	(Phone) +65-91880523
Alt. Phone Number	-
Email Address	hoque.safetech@gmail.com
Address	C/O 464 Upper Serangoon Road
Address complement	-
Postcode	534794
Is the driver the policyholder?	No
If No, Relationship of the Driver with the Insured	Employee
Does Driver Own Other Vehicles?	No
Vehicle Registration Number of Other Vehicle Owned by Driver	-
Insurance Company of Other Vehicle Owned by Driver	-

GENERAL INFORMATION OF THE ACCIDENT

Type of Accident	Collision - Head to Rear
Weather Conditions	Raining
Road Surface	Wet

OTHER INFORMATION

Was any foreign vehicle involved in the accident?	No
Number of vehicles involved in the accident	2
Was anybody injured in the Accident?	No
Was any injured conveyed to hospital by ambulance?	-
Was any other vehicle or property damaged?	Yes
Number of Passengers (Including Driver)	1
Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance?	No
Translator's name	-
Translator's ID	-
Translator's phone number	-
Translator's email	-
Original language used in the statement	-

DETAILS OF POLICE ACTION

Was the accident reported to the police?	No
Was notice of intended Prosecution given?	No
If yes, against whom?	-

CIRCUMSTANCES OF ACCIDENT

Please refer to the sketch plan.

ATTACHMENT(S)

Are accident photos available for attachment?	Yes
Was there any video captured by Car Camera?	No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SLE2023C
Vehicle Manufacturer	-
Vehicle Model	-
Vehicle Variant	-
Vehicle Colour	-
Vehicle Category	Private car
Name of Driver	-
Contact Number	-

Address	-
Address complement	-
Postcode	-
Insurance Company Name	-
Nature Of Damage	-
Details of property damaged in accident	-
No. Of Passenger (Including Driver)	-

Motor Commercial

MZ300/C

R SN

AN0435A

Cov. Type:C

CERTIFICATE OF INSURANCE

Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189)
Motor Vehicles (Third-Party Risks and Compensation) Rules, 1960
Road Transport Act, 1987 (Malaysia)
Motor Vehicles (Third-Party Risks) Rules, 1959 (Malaysia)

CERTIFICATE No.	DMCVSNW00003422202	Engine No.: 1KD2836573	Cha. No.: JTFAT35Y00K212226
1. Index Mark and Registration Number of Vehicle	GBJ1074D	AUTOSAFE	*****
2. Name of Policy Holder	SAFETECH ENGINEERING PTE LTD		
3. Effective date of the Commencement of Insurance for the purposes of the Regulations, Ordinance or Enactment	02/01/2022 (00:00:00)	Excess Sect I	SS\$350.00
		EX ON WINDSCREEN	SS\$100.00
4. Date of Expiry of Insurance	01/01/2023		
5. Persons or Classes of Persons entitled to drive*	Any person who is driving on the Policyholder's order or with their permission. Provided that the person driving is permitted in accordance with the licensing or other laws or regulations to drive the Motor Vehicle or has been so permitted and is not disqualified by order of a Court of Law or by reason of any enactment or regulation in that behalf from driving the Motor Vehicle.		
6. Limitations as to use.*	<ul style="list-style-type: none"> (1) Use in connection with the Policyholder's business. (2) Use for the carriage of passengers (other than for hire or reward) in connection with the Policyholder's business. (3) Use for social, domestic or pleasure purposes. <p>The Policy does not cover</p> <ul style="list-style-type: none"> (1) Use for hire or reward or racing, pace-making, reliability trial or speed testing. (2) Use whilst drawing a trailer except the towing of any one disabled mechanically propelled vehicle. 		

* Limitations rendered inoperative by Section 8 of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Section 95 of the Road Transport Act 1987 (Malaysia), are not to be included under these headings.

I/We hereby Certify that the policy to which this Certificate relates is issued in accordance with the provisions of the Motor Vehicles (Third-Party Risks and Compensation) Act (Chapter 189) and Part IV of the Road Transport Act, 1987 (Malaysia).

Please see reverse

For CHINA TAIPING INSURANCE (SINGAPORE) PTE. LTD.

Issued By: YETTA INSURANCE AGENCY PTE LTD
Authorised Officer


Authorised Signatory

> Back to OneMotoring

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type:	Company
Owner ID:	322C

Vehicle Details

Vehicle No.:	GBJ1074D
Vehicle to be Exported:	Yes
Intended Deregistration Date:	19 Oct 2022
Vehicle Make:	TOYOTA
Vehicle Model:	DYNA 150 5MT
Primary Colour:	Silver
Manufacturing Year:	2018
Engine No.:	1KD2836573
Chassis No.:	JTFAT35Y00K212226
Maximum Power Output:	-
Open Market Value:	\$27,082.00
Original Registration Date:	02 Jan 2019
First Registration Date:	02 Jan 2019
Transfer Count:	0
Actual ARF Paid:	\$1,355.00

Intended PARF Rebate Details

PARF Eligibility:	No
PARF Eligibility Expiry Date:	-
PARF Rebate Amount:	\$0.00

Intended COE Rebate Details

COE Expiry Date:	01 Jan 2029
COE Category:	C - Goods Vehicle & Bus
COE Period(Years):	10
QP Paid:	\$27,001.00
COE Rebate Amount:	\$16,744.00
Total Rebate Amount:	\$16,744.00

The information contained herein is correct as at 19 Oct 2022

OK

Lai Huat (Meng Kee) Motor Pte Ltd
160 Sin Ming Drive, #04-01, #04-02 &
#07-03, Sin Ming Autocity
575722

Insurer Reference: **DMCVSNW00003422202**
 Repairer Reference: **73103**
 Date calculated: **20/12/2022 10:41 AM**

Full Report
Registration: GBJ 1074D
Printed: 20/12/2022 10:41 AM

Summary Information

Claim			
Location:	Singapore (SG)	Work Provider:	China Taiping Insurance (Singapore) Pte Ltd
Printed by:	Jenny Lim	Currency:	SGD
Claim Reference:	DMCVSNW00003422202	Date of Incident:	19/10/22
Estimated Repair Time:		Hire Car Start:	
Actual Repair Days:		Hire Car End:	

Vehicle Details

Vehicle			
Manufacturer:	TOYOTA		
Model:	DYNA		
Sub Model:	150		
Model Sheet Number:	70 1N 03		
Registration:	GBJ 1074D		
VIN number:			
Odometer:	143150		
Model Specs			
AIR CONDITIONING	FROM 11.2017	FOG LAMPS	WHEELBASE 3350 MM
SINGLE CAB	3.0 LTR 80KW	TYRES 195/75 R15	TWO COAT METALLIC
PREPARE OFF VEHICLE			

Labour

Code	Description	Time Base 10 WU/h	Price = 42.00 SGD/h	
			WU	Price SGD
NO NUMBER	RENEW FRONT PANEL		60.0	252.00
NO NUMBER	R + R BADGE		2.0	8.40
520011)	R + R FRONT BUMPER		4.0	16.80
520011)	RENEW FRONT BUMPER (REMOVED)		2.0	8.40
	INCLUDES: REQUIRED ATTACHED PARTS REMOVE AND REFIT			
751011	R + R RADIATOR GRILLE		3.0	12.60
810121Y)	R + R LEFT HEADLAMP (RADIATOR GRILLE REMOVED)		1.0	4.20
810121Y)	R + R RIGHT HEADLAMP (RADIATOR GRILLE REMOVED)		1.0	4.20
810151A	ADJUST HEADLAMPS		3.0	12.60
NO NUMBER	R + R L/F LOWER CLOSING PANEL		1.0	4.20
NO NUMBER	R + R R/F LOWER CLOSING PANEL		1.0	4.20
554011)	R + R WINDSCREEN		14.0	58.80
	INCLUDES: R + R SUN VISORS, UPPER FRONT PANEL AND A-PILLAR TRIMS			
670051)	R + R LEFT FRONT DOOR		6.0	25.20

Code	Description	WU	Price SGD
670051)	R + R RIGHT FRONT DOOR	6.0	25.20
NO NUMBER	RENEW FRONT CROSSMEMBER	25.0	105.00
743201)	DETACH + REFIT HEADLINING	4.0	16.80
	INCLUDES: R + R INSIDE MIRROR, PILLAR TRIMS AND SEAT BELTS		
NO NUMBER	R + R L/F LOWER DOOR SEAL	2.0	8.40
NO NUMBER	R + R R/F LOWER DOOR SEAL	2.0	8.40
870031)	R + R HEATING CPL	12.0	50.40
NO NUMBER	R + R EVAPORATOR	4.0	16.80
550451)	R + R INSTRUMENT PANEL	9.0	37.80
NO NUMBER	R + R INSTRUMENT PANEL CARRIER (REMOVED)	2.0	8.40
850161)	R + R WIPER MOTOR (WIPER UNIT REMOVED)	1.0	4.20
850171)	R + R WIPER LINKAGE	1.0	4.20
002019)	DRAIN + REFILL COOLANT	3.0	12.60
441101	R + R STEERING WHEEL	2.0	8.40
002889 ZAX	DRAIN AND REFILL AIR CONDITIONING	7.0	29.40
Labour Cost		Hrs	WU
Panel / Mechanical Labour		17.80	178.0
Total of Labour			747.60

Paint

Code	Description - TWO COAT METALLIC	WU	Price SGD
	FRONT BUMPER NEW PART PAINTING	12.0	
	L/F BUMPER BRACKET NEW PART PAINTING	6.0	
	R/F BUMPER BRACKET NEW PART PAINTING	6.0	
	FRONT LOWER PANEL NEW PART PAINTING	19.0	
	UPPER FRONT PANEL NEW PART PAINTING	8.0	
	L/F LOWER END PANEL SURFACE PAINT	4.0	
	R/F LOWER END PANEL SURFACE PAINT	4.0	

Paint Material Per Part

Code	Description	Price SGD
0281	FRONT BUMPER NEW PART PAINTING	27.86
0293	L/F BUMPER BRACKET NEW PART PAINTING	1.55
0294	R/F BUMPER BRACKET NEW PART PAINTING	1.55
0414	FRONT LOWER PANEL NEW PART PAINTING	22.00
0418	UPPER FRONT PANEL NEW PART PAINTING	10.32
0889	L/F LOWER END PANEL SURFACE PAINT	0.75
0890	R/F LOWER END PANEL SURFACE PAINT	0.75

Labour Cost - Paint

	Hrs	WU	Price SGD
Factor			42.00 SGD/h
Time Paint		59.0	
Preparation Main Work Metal	2.50	25.0	105.00
Total	10 WU/h	84.0	352.80

Material Cost - Paint
 New Part Painting
 Surface-/Blend Paint
 Material-constant Metal Preparation
Total

Price SGD
63.28
1.50
28.60
93.38

Spare Parts

Code	Description	Part Number	Part Source	prices as at 2015-06-01/01	Price SGD
0485	BADGE MODEL	75311 25100	Original	CL445753 (1)	25.00 ✓
0281	FRONT BUMPER	52101 37985	Original	CL445753 (3)	220.00 ✓
3010	FRONT CROSSMEMBER	51211 25100	Original	CL445753 (8)	100.00 ✓
0414	FRONT LOWER PANEL	55711 37110	Original	CL445842	450.00 ✓
1001	FRT PANEL CLIP	82597 23070	Supplementary	CL446588 Necessary	3.00
0411	GRILLE	53111 37A01A0	Original	CL445753 (2)	195.00 ✓
0293	L/F BUMPER BRACKET	52012 37070	Original	CL445753 (5)	100.00 ✓
0561	LEFT HEADLAMP ASSY	81170 37660	Original	CL445753 (6)	300.00 ✓
0294	R/F BUMPER BRACKET	52011 37070	Original	CL445753 (4)	100.00 ✓
0562	RIGHT HEADLAMP ASSY	81130 37660	Original	CL445753 (7)	300.00 ✓
0418	UPPER FRONT PANEL	55078 37110	Original	CL446598	130.00 ✓
1411	WINDSCREEN BOND KIT	PZ49I 00C1131			0.00
1410	WINDSCREEN SEAL	56121 25040	Supplementary	CL446547 Necessary	95.00
	Savings				0.00
	Subtotal				2,018.00
	Total				2,018.00

f: OEM Parts
 h: Non-OEM Parts
 u: Used parts

Extras

Code	Description	Price SGD
1000	FRONT NUMBER PLATE	25.00* ✓
	Total Extras	25.00

Parts - \$2,018.00
 Special Nets - \$25.00
 Sundry - 0
 Labour - \$1,193.78
 Sub Total - \$3,236.78
 (-) Excess - \$350.00
 Grand Total - \$2,886.78

7.45

Final Calculation

	SGD	SGD
Parts		
Total Parts	2,018.00	2,018.00 ^{Part}
Labour Time Base 10 WU/h		
Total 178.0 WU X 42.00 SGD/h	747.60	747.60 ^{Labour} ✓
Total of Labour		747.60 ✓
Total Of Extras		25.00 ✓
Paint Work Time Base 10 WU/h		
Labour Cost 84.0 WU X 42.00 SGD/h	352.80	
Material Cost	93.38	
Total Paint Including Material		446.18 ✓
Repair Cost Excludes GST		3,236.78
GST (+7.0%)		226.57
Repair Cost Included GST		3,463.35
Deductions (Excludes GST)		
Deduction For Excess	-350.00	
Total Of Deductions (Excludes GST)		-350.00
Grand Total Excludes GST		2,886.78
GST (+7.0%)		202.07
Grand Total Included GST		3,088.85

Comments

- * - USER SUPPLIED DATA
- NN - NO MANUFACTURERS CODE EXISTS
-) - WU PARTIAL INCL IN OTHER POSITIONS

Assessment Note

No assessment notes entered.



豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
UEN No.: 198301435R

NISSAN TOYOTA GENUINE & OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD/KIA
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997

NISSAN TOYOTA GENUINE & OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD/KIA
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997

AUTHORISED STOCKISTS:



INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

TAX INVOICE

TAX INVOICE NO.: CL446547
INVOICE DATE : 30/11/2022
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T56121-25040 F/W/STRIP		1 PCS	(SIN) 95.000
GBJ1074D (KDY231) VICTOR			(SIN) 95.00
GST Excl Amount :			95.00
Special Discount :			
GST @ 7 % :			6.65

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL 101.65

PRINT BY :
YKN 30/11/2022 10:52:17

AUTHORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
UEN No.: 198301435R

NISSAN TOYOTA GENUINE & OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD/KIA
TEL: 62935722
67420368


AIRCON/W/S GLASS
TEL: 62952336
67495997

NISSAN TOYOTA GENUINE & OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MAZDA/FORD/KIA
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997

AUTHORISED STOCKISTS:



INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

TAX INVOICE

TAX INVOICE NO.: CL446588
INVOICE DATE : 01/12/2022
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1

GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T81496-12060 GUIDE		1	(SIN) 3.000
GBJ1074D (KDY231) VICTOR			(SIN) 3.00
GST Excl Amount :			3.00
Special Discount :			
GST @ 7 % :			0.21

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL 3.21

PRINT BY :
YKN 01/12/2022 10:33:59

AUTHORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
UEN No.: 198301435R

NISSAN TOYOTA GENUINE & OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI
TEL: 62954551
67496954

HONDA/HYUNDAI/KIA
TEL: 62970688 64542288
67493588

MAZDA/FORD/KIA
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997



INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

TAX INVOICE

TAX INVOICE NO.: CL446598
INVOICE DATE : 01/12/2022
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1



GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T55078-37110 WIPER PANEL GBJ1074D (KDY231) VICTOR		1	(SIN) 130.000 ✓
			(SIN) 130.00 ✓
			GST Excl Amount : 130.00
			Special Discount :
			GST @ 7 % : 9.10

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL 139.10

PRINT BY :
YKN 01/12/2022 13:17:10

AUTHORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司

FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
Tel: 67494988, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
Fax: 62992158, 62942354, 62935021
UEN No.: 198301435R



NISSAN TOYOTA GENUINE & OEM PARTS
TEL: 67426889 62949832 67479292
67426878 62985333 67455824

MITSUBISHI
TEL: 62954551
67496954

HONDA/HYUNDAI/KIA
TEL: 62970688 64542288
67493588

MAZDA/FORD/KIA
TEL: 62935722
67420368

AIRCON/W/S GLASS
TEL: 62952336
67495997



INVOICE TO: LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1
160 SIN MING DRIVE
#04-01/#04-02 SIN MING AUTO CITY
SINGAPORE 575722

TAX INVOICE

TAX INVOICE NO.: CL445842
INVOICE DATE : 10/11/2022
CREDIT TERMS : 30 DAYS
SALES ORDER NO.:
SALESMAN : YKN
PAGE(S) : 1



GST Reg. No.: M2-0059747-8

DESCRIPTION	LOC.	QUANTITY	UNIT PRICE
T55700-37350 F/PANEL GBJ1074D (KDY231) VICTOR		1	(SIN) 450.000 ✓
			(SIN) 450.00 ✓
			GST Excl Amount : 450.00
			Special Discount :
			GST @ 7 % : 31.50

FONG TAT MOTOR CO. PTE. LTD. GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED


TOTAL 481.50

PRINT BY :
YKN 10/11/2022 09:44:45



豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62992158, 62942354, 62935021
 UEN No.: 198301435R



NISSAN TOYOTA GENUINE & OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824

MITSUBISHI
 TEL: 62954551
 67496954
HONDA/HYUNDAI/KIA
 TEL: 62970688 64542288
 67493588
MAZDA/FORD/KIA
 TEL: 62935722
 67420368
AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE

TAX INVOICE NO.: CL445753
 INVOICE DATE : 08/11/2022
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : YKN
 PAGE(S) : 1



INVOICE TO: **LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1**
 160 SIN MING DRIVE
 #04-01/#04-02 SIN MING AUTO CITY
 SINGAPORE 575722

GST Reg. No.: M2-0059747-8

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
T75311-25100	GRILLE EMBLEM		1	25.000	25.000	25.000✓
T53111-37A01-B1	GRILLE		1	195.000	195.000	195.000✓
T52101-37985	F/BUMPER		1	220.000	220.000	220.000✓
T52012-37070	F/BUMPER STAY		1 PCS	100.000	100.000	100.000✓
T52011-37070	F/BUMPER STAY		1	100.000	100.000	100.000✓
T81170-37660	HEADLAMP		1	300.000	300.000	300.000✓
T81130-37660	HEADLAMP		1	300.000	300.000	300.000✓
T51211-25100	CROSSMEMBER		1	100.000	100.000	100.000✓

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL


AUTHORISED SIGNATURE

SIGNATURE



豐達汽車私人有限公司
FONG TAT MOTOR CO. PTE. LTD.

Head Office: No. 3 Kallang Way 2A, FONG TAT Building Singapore 347493
 Tel: 67494998, 67479292 Fax: 67490980, 67477481 Website: www.fongtat.com
 Main Branch (Town): 355-357 Serangoon Road Singapore 218115 Tel: 62985333, 62949832
 Fax: 62992158, 62942354, 62935021
 UEN No.: 198301435R



NISSAN TOYOTA GENUINE & OEM PARTS
 TEL: 67426889 62949832 67479292
 67426878 62985333 67455824

MITSUBISHI
 TEL: 62954551
 67496954
HONDA/HYUNDAI/KIA
 TEL: 62970688 64542288
 67493588
MAZDA/FORD/KIA
 TEL: 62935722
 67420368
AIRCON/W/S GLASS
 TEL: 62952336
 67495997

TAX INVOICE

TAX INVOICE NO.: CL445753
 INVOICE DATE : 08/11/2022
 CREDIT TERMS : 30 DAYS
 SALES ORDER NO.:
 SALESMAN : YKN
 PAGE(S) : 2



INVOICE TO: **LAI HUAT (MENG KEE) MOTOR PTE LTD LHM1**
 160 SIN MING DRIVE
 #04-01/#04-02 SIN MING AUTO CITY
 SINGAPORE 575722

GST Reg. No.: M2-0059747-8

	DESCRIPTION	LOC.	QUANTITY	UNIT PRICE	(SIN)	(SIN)
GBJ1074D (KDY231)	VICTOR					
				GST Excl Amount :		1340.00
				Special Discount :		
				GST @ 7 % :		93.80

FONG TAT MOTOR CO. PTE. LTD.

GOODS SOLD ARE NOT RETURNABLE FOR CASH

GOODS RECEIVED

TOTAL

1433.80

PRINT BY :
 YKN 08/11/2022 13:49:12