

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

59 Loyang Drive
Singapore 508969
Tel: 6214 8300

TP INSURER: **Tokio Marine Insurance Singapore Ltd (HQ)**
CTPL

Singapore

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	20/10/2022
Vehicle Reg. No.:	SH2934A	Driveable?	NO
Party At Fault:	UNKNOWN		
Make/Model:	TOYOTA PRIUS TAXI, 1.8 (A)	Vehicle Reg. Date:	03/10/2017
Vehicle Colour:	BLUE	Gen Condition:	GOOD
Engine No:	2ZRS065892	Chassis No:	JTDKB3FU303564903
Odometer:	904404 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	10		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (LOYANG)		

COST OF CLAIMS

	Amount
Parts	15,580.84
Miscellaneous Items	11.00
Labour	3,410.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	19,001.84
+ GST 7.00% (S\$)	1,330.13
Nett Amount (S\$)	20,331.97

This claim is handled by: CHIANG LIAT CHOON

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 21 Oct 2022)

Parts: 144 TOYOTA PRIUS TAXI 1.8 (A) (Catalogue: Merimen Singapore 1.0)

Labour: Repairer's (Price-denominated Standard List)

Print Code: ComfortDelGro Engineering Pte Ltd/SH2934A/21/10/2022 09:55

Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page

Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*BONNET X	25.00	0.00	*1,117.93 FL
2	1		*Bonnet hinge LH X	25.00	0.00	*87.70 FL
3	1		*Bonnet hinge RH X	25.00	0.00	*87.70 FL
4	1		*Bonnet Rubber X	25.00	0.00	*35.50 FL
5	1		*Bonnet Lock X	25.00	0.00	*132.60 FL
6	1		*Bonnet lock panel X	25.00	0.00	*186.60 FL
7	1		*Radiator Grille X	25.00	0.00	*438.00 FL
8	1		*Radiator grille emblem X	25.00	0.00	*88.00 FL
9	1		*Radiator grille lower panel X	25.00	0.00	*193.18 FL
10	1		*Radiator Support Upper Panel X	25.00	0.00	*364.98 FL
11	1		*Radiator Support Lower Panel X	25.00	0.00	*145.90 FL
12	1		*Radiator Support RH Panel X	25.00	0.00	*278.68 FL
13	1		*Radiator Support LH Panel X	25.00	0.00	*278.68 FL
14	1		*Head Lamp LH Panel X	25.00	0.00	*240.10 FL
15	1		*Head LAMP LH	25.00	0.00	*2,637.60 FL
16	1		*FOG LAMP LH	25.00	0.00	*920.00 FL
17	1		*Front Bumper	25.00	0.00	*586.18 FL
18	1		*front bumper reinforcement -	25.00	0.00	*812.89 FL
19	10		*front bumper clips	25.00	0.00	*22.00 FL
20	2		*front bumper side retainer	25.00	0.00	*154.00 FL
21	1		*Front Bumper tow cover	25.00	0.00	*57.76 FL
22	1		*Front Fender Lh	25.00	0.00	*1,111.93 FL
23	1		*Front Fender Housing Lh X	25.00	0.00	*958.30 FL
24	1		*Front Fender Shield Lh	25.00	0.00	*198.50 FL
25	1		*Front Fender Hybrid emblem Lh	25.00	0.00	*86.50 FL
26	1		*Front Wheel alu Rim Lh	25.00	0.00	*1,570.00 FL
27	1		*Front Wheel Hub Bearing Lh	25.00	0.00	*560.10 FL
28	1		*Front Steering knuckle Lh	25.00	0.00	*580.80 FL
29	1		*Front Shock absorber Lh	25.00	0.00	*401.80 FL
30	1		*Front Steering ball joint Lh	25.00	0.00	*199.98 FL
31	1		*Front Steering Tie Rod Lh	25.00	0.00	*159.30 FL
32	1		*Front Drive Shaft Lh	25.00	0.00	*1,764.00 FL
33	1		*Front wing Mirror Assy Lh X	25.00	0.00	*1,728.70 FL
34	1		*Front wing Mirror Cover Lh X	25.00	0.00	*141.90 FL
35	1		*Front Door Lh	25.00	0.00	*1,264.00 FL
36	1		*Front Rocker Panel Lh	25.00	0.00	*576.00 FL
37	1		*Front door Comfort Logo Sticker	0	0.00	*75.00 FS
38	1		*Front door Advertisement	0	0.00	*100.00 FS
39	1		*Front Fender Advertisement	0	0.00	*100.00 FS
40	1		*Rear Door Advertisement	0	0.00	*100.00 FS
41	1		*Rear Door Comfort App sticker	0	0.00	*80.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)

20,622.79

- List Item Discount on L Items (\$\$)

5,041.95

ComfortDelGro Engineering Pte Ltd/SH2934A/21/10/2022 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer) ✓	11.00
Sub Total (\$\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	PANEL BEATING	New	1,750.00 60
2	SPRAY PAINTING	New	1,200.00 ✓
3	REMOVE/REFIX FRONT U/SUSPENSION	New	120.00 ?
4	REMOVE/ REFIX DOOR PART	New	90.00 60
5	CHECK WIRING & LIGHTING	New	80.00 30
6	RESET FRONT WHEEL ALIGNMENT	New	80.00 60
7	TUFF COATING	New	90.00 60
Gross Labour Cost (\$\$)			3,410.00

ComfortDelGro Engineering Pte Ltd/SH2934A/21/10/2022 09:55. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

6 Days.
L/S
Gmo Corp.
21/10
4pm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display vehicle at all times during resurvey
- For up to 3 days
- To keep vehicle in a safe place - "as is" basis
- No alterations to be made to the vehicle
- If alterations are made, the repairer must notify the consultant and obtain approval before proceeding

Acknowledged by: _____
Signature: _____
Date: _____