



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
STRIDES AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4SINGAPORE 757705			Ref: CS/SMR22010463/Eqy3m4	
			Date: 08/11/2022	
			Code: SMR	
<b>1. Policy Particulars :- THIRD PARTY CLAIM</b>				
Insured Veh.	SHB 1027L	Veh. Inspected	SMT 1847H	
Policy No.		Coverage (\$)	0.00	
Claim No.	TAX/05/22/2006	Excess (\$)	0.00	
Assign From	ASHLENE LEE	Assign Date	21/10/2022	
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model	SSANGYONG TIVOLI	c.c	1597	
Engine No.	HIDDEN	Year of Reg.	2020	
Chassis No.	KPT30A1USLP319749	Colour	BLACK	
Odometer	126340 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
<b>3. Conditions of Tyres</b>				
	Size	Make	Balance	
R/H Front Tyre	215/55 R17	BRIDGESTONE	4 mm	
L/H Front Tyre	215/55 R17	BRIDGESTONE	4 mm	
R/H Rear Tyre	215/55 R17	BRIDGESTONE	4 mm	
L/H Rear Tyre	215/55 R17	BRIDGESTONE	4 mm	
<b>4. Description of Damages</b>				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
<b>5. General Information</b>				
Accident Date	01/05/2022	Inspection Date	27/10/2022	
Survey held at	No. 4 Jalan Besut S(619557)			
Repairer	MOTORWAY CAR CARE CENTRE PTE LTD			
<b>5a. Remarks</b>				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
<b>5b. Estimate Days of Repair</b>				
ESTIMATED NORMAL PERIOD FOR REPAIR:			<b>4 Working Days</b>	