

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)
 51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
 Singapore 408933
 Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/AIG22010473/KPA3Q2
Date: 17/01/2023

REFERENCE

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	7210142500
Claimant Vehicle No :	SML6902R	Insured Vehicle No :	SLX7011D
Date of Loss:	13/10/2022	Nature of Claim:	TP
		Claim No:	8845066431SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SML6902R		
Make & Model:	HONDA SHUTTLE HYBRID, 1.5 (A)	Engine No:	LEB7101931
Reg. Date:	30/05/2019 (Man. Year: 2018)	Chassis No:	GP72001400
Colour:	Metallic Dark Blue	Odometer:	109713 km
Engine Capacity:	1496 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/60 R15	Rear Tyre Size:	185/60 R15
Front Left Side:	Dunlop 3 mm	Rear Left Side:	Continental 9 mm
Front Right Side:	Dunlop 3 mm	Rear Right Side:	Continental 9 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,240.56	2,724.00	2,516.56	48.02
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,120.00	715.00	1,405.00	66.27
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	7,360.56	3,439.00	3,921.56	53.28
Approved Total (Overridden) (S\$)		2,750.00		
	(S\$)	7,360.56	2,750.00	4,610.56
	+ GST 7.00/7.00% (S\$)	515.24	192.50	322.74
	Nett Amount (S\$)	7,875.80	2,942.50	4,933.30
	+ Loss of Use (3.0 x S\$60.00/day) (S\$)		180.00	
	+ Doc/Search Fee (S\$)		7.45	
	Nett Liability (S\$)		3,129.95	
	Global Sum Settlement (S\$)		3,100.00	

INSPECTION

Date of Assignment:	17/10/2022		
Date Inspected:	17/10/2022	Inspected At:	Hui Yang Motor Pte Ltd (HQ) 176 Sin Ming Drive #04-02, Sin Ming AutoCare Singapore 575721
Estimated Period of Repair:	3.0 days		

Adjuster: KENNETH KONG

Manager: CHEW HSIAO TONG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT LH HEADLAMP	Scratched	2,550.00 FL	*2,250.00 FL
2	1		*FRONT LH HEADLAMP LOWER BRACKET	Serviceable	68.00 FL	*- FL
3	1		*FRONT CENTRE GRILLE BASE	Serviceable	495.00 FL	*- FL
4	1		*FRONT CENTRE GRILLE OUTER GARNISH	Serviceable	325.50 FL	*- FL
5	1		*FRONT CENTRE GRILLE H LOGO	Not Necessary	58.50 FL	*- FL
6	1		*FRONT CENTRE GRILLE LOWER CHROME	Serviceable	215.00 FL	*- FL
7	1		*FRONT BUMPER	Buckled / Dented	1,150.50 FL	*1,050.00 FL
8	20		*FRONT BUMPER CLIP	Necessary (10 PCS ONLY)	100.00 FL	*50.00 FL
9	1		*FRONT BUMPER LH SIDE RETAINER	Distorted	55.00 FL	*55.00 FL
10	1		*FRONT BUMPER LH FOG LAMP	Serviceable	385.50 FL	*- FL
11	1		*FRONT BUMPER LH FOG LAMP GARNISH	Serviceable	185.50 FL	*- FL
12	1		*FRONT BUMPER LH FOG LAMP GARNISH TOP COVER	Serviceable	78.50 FL	*- FL
13	1		*FRONT LH FENDER	Repair	598.50 FL	*- FL
14	1		*FRONT LH FENDER INNER SHIELD	Serviceable	235.20 FL	*- FL
15	10		*FRONT LH FENDER INNER SHIELD CLIP	Not Necessary	50.00 FL	*- FL

F=Franchise part. L=ListItemDisc.

Sub Total (\$)	6,550.70	3,405.00
- List Item Discount on L Items 20.00/20.00% (\$)	1,310.14	681.00
Total Parts (\$)	5,240.56	2,724.00

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	WIRING	New	60.00	15.00
2	TUFFKOTE	New	60.00	0.00
3	SPRAY PAINTING	New	1,000.00	400.00
4	LABOUR CHARGES	New	1,000.00	300.00
			Gross Labour Cost (\$)	2,120.00
				715.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >