

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

	Reg. No. 19900/196R GS1 Reg. No. 19-900/196-R					
Affiliated to Federation Internationale Des Experts En Automobile						
	AUTO & GENERA	L INSURANCE (S) PL	R	ef:	CS/AGI22010486/Dny3e2	
	(BUDGET DIRECT 190 CLEMENCEAI SINGAPORE SHO 239924	INSURANCE) J AVENUE #03-01 PPING CENTRESINGAPORE	D	ate:	30/01/2023	
			C	ode:	AGI	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMW 7189T	Veh. Inspected		SHD 9622E	
	Policy No.	P10647625R00	Coverage (\$)		0.00	
	Claim No.	C10018036/CH	Excess (\$)		0.00	
	Assign From	SALIZAWATI HAIZAR	Assign Date		21/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	TOYOTA PRIUS	c.c		1798	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	JTDKB3FU603079655	Colour		RED	
	Odometer	301046 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		SPORTS RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Front Tyre	195/65 R15	WEST LAKE		5 mm	
	R/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
	L/H Rear Tyre	195/65 R15	WEST LAKE		5 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	13/10/2022	Inspection Date		25/10/2022	
	Survey held at	TRANS-CAB AUTO SERVICES PTE LTD				
		NO.2 ANG MO KIO ST 63 SINGAPORE 569111				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.	Estimate Days of Repair					

1 Working Days

ESTIMATED NORMAL PERIOD FOR REPAIR: