

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0907/2022/EQ
DATE : 19-Oct-22
WIP : 46713

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 20/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

OWNER'S NAME : MR CHONG MINGYONG
ADDRESS : BLK 167C SIMEI LANE
#07-28
SINGAPORE 523167
TELEPHONE : HP +65 90181837
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO :
VEHICLE NO : **SLU 7364 B**
MODEL CODE : AUDI A3 SEDAN 1.0 TFSI 8V
MODEL YEAR : 12/12/2017
ENGINE NO : CHZ 584011
CHASSIS NO : WAUZZZ8V9J1024727
MILEAGE : -
DATE IN : -
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 18-Oct-22
PLACE OF ACCIDENT : PIE (TOWARDS TUAS), AFTER STEVENS EXIT,
LAMP POST 929

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - FRONTAL

| S/N | NATURE OF JOBS | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|---|----------------------|----------------------------|
| 1 | TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY. | S/N \$ 360.00 ✓ | |
| 2 | TO REMOVE AND TRANSFER BOTH HEADLIGHT'S CONTROL UNIT AND POWER MODULE. | S/N \$ 700.00 250 | |
| 3 | TO REMOVE AND RENEW AIRCON CONDENSER, CHARGE AIR COOLER AND RADIATOR. CHECK ELECTRICAL FANS AND CONTROL UNIT. PRESSURISE COOLING SYSTEM. TO CARRY OUT VACUUM AND REGAS. | S/N \$ 1,400.00 ? | |
| 4 | TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIM. TO REMOVE AND REINSTALL LHS WING MIRROR ASSY TO FACILITATE RESPRAY OF LHS FRONT DOOR. | S/N \$ 280.00 ✓ | |
| 5 | TO RENEW FRONT WINDSCREEN. | S/N \$ 480.00 ? | |
| TOTAL LABOUR CHARGES | | : \$ 3,220.00 | |

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - FRONTAL

| S/N | NATURE OF JOBS | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|-----------------------|----------------------------|
| 6 | TO INSTALL SOLAR FILM FOR ALL AFFECTED GLASSES. | S/N \$ 400.00 | ? |
| 7 | TO CARRY OUT WATER SEEPAGE TEST FOR ALL THE AFFECTED WINDSCREEN. | S/N \$ 200.00 | ? |
| 8 | TO DISMANTLE AND RENEW FRONT BUMPER, BONNET, BOTH FRONT FENDERS AND BOTH HEADLIGHT. TO RENEW FRONT LOCK CARRIER AND ALIGN TO POSITION. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 5,600.00 | 1500. |
| 9 | TO RESPRAY FRONT BUMPER, BOTH FRONT FENDERS, BONNET, HINGES, LHS FRONT DOOR AND LHS UPPER A-PILLAR. | \$ 5,500.00 | 2300 |
| TOTAL LABOUR CHARGES | | : \$ 14,920.00 | |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

| S/N | NATURE OF JOBS | | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|--------|----------------------|-------------------------------|
| 1 | TO CARRY OUT FIRST MEASUREMENT TEST ON CAR O-LINER. | S/N \$ | 800.00 | 2 pmt. |
| 2 | TO REMOVE AND TRANSFER REAR PARKING AID. CHECK FUNCTION. | S/N \$ | 280.00 | ✓ |
| 3 | TO RENEW RHS 1/4 GLASS AND REAR WINDSCREEN TO FACILLITATE FENDER RENEWAL. | S/N \$ | 600.00 | X |
| 4 | TO REMOVE AND REINSTALL REAR LID'S CONVENIENCE LOCK SYSTEM AND WIRE HARNESS FOR TAIL LIGHTS. | S/N \$ | 280.00 | ✓ |
| 5 | TO DISLODGE AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. | S/N \$ | 1,400.00 | ✓ 1400 |
| TOTAL LABOUR CHARGES | | : | \$ 6,580.00 | |

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

| S/N | NATURE OF JOBS | | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|-----------------------------|--|--------|----------------------|-------------------------------|
| 6 | TO REMOVE AND REINSTALL REAR SEAT, BACK REST, HAT TRAY, ABCD PILLAR TRIMS LUGGAGE COMPARTMENT TRIMS. DISLODGE ROOF LINER AND DISENGAGE CURTAIN AIRBAG ETC. | S/N \$ | 1,400.00 | ? |
| 7 | TO DISMANTLE AND REINSTALL CENTER CONSOLE. RENEW AIRBAG CONTROL UNIT AND BOTH FRONT SEATBELT. | S/N \$ | 1,800.00 | ✓ 1,800.00 |
| 8 | TO REMOVE AND REINSTALL EXHAUST SYSTEM AND REAR SUSPENSION ASSEMBLY. RENEW ACCORDINGLY. | S/N \$ | 2,800.00 | ? |
| 9 | TO REMOVE AND REINSTALL FUEL TANK ASSY. | S/N \$ | 600.00 | ? |
| 10 | TO SETUP VEHICLE ON CAR-O-LINER FOR REPAIR. | S/N \$ | 2,400.00 | ? photos |
| TOTAL LABOUR CHARGES | | : | \$ 12,220.00 | |

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SLU 7364 B - REAR

| S/N | NATURE OF JOBS | ESTIMATED CHARGES | SURVEYOR'S RECOMMENDATIONS |
|--|--|-----------------------|----------------------------|
| 11 | TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. CUT OUT AND WELD REAR END PANELLING, SPARE WHEEL HOUSING AND RHS REAR FENDER. RE-ALIGN RHS REAR CHASSIS FRAME INTO POSITION. REPAIR LHS REAR FENDER. RE-ORGANIZE REAR CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED. | \$ 11,900.00 | 2500 |
| 12 | TO CARRY OUT STONE CHIP PRIMER WORK ON REAR PANELLING AND SPARE WHEEL HOUSING. | S/N \$ 780.00 | ✓ |
| 13 | <i>LH fender</i> TO RESPRAY REAR BUMPER, REAR LID, HINGES, BOTH REAR FENDER, RHS SILL PANEL, DRAIN PANEL, ROOF CHANNEL, DOOR ENTRANCES, END PANELLING AND SPARE WHEEL HOUSING. TO CARRY OUT STONE CHIP TREATMENT, CAVITY PRESERVATION AND JOINT SEALER WORKS. | \$ 7,500.00 | 2850 |
| 14 | TO CARRRY OUT WHEEL ALIGNEMENT. | S/N \$ 240.00 | ? |
| 15 | TO CARRY OUT PRE/POST DIAGNOSTIC CHECK. | S/N \$ 384.00 | ✓ |
| TOTAL LABOUR CHARGES - FRONT & REAR | | : \$ 57,744.00 | |

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|---|------|------------------------|---------------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 1 | FRONT BUMPER | 1 \$ | 2,432.00 | de ✓ |
| 2 | FRONT BUMPER FIXING PARTS | 1 \$ | 195.00 | X |
| 3 | FRONT BUMPER GUIDE SECTION - LH / RH | 2 \$ | 86.00 | ? |
| 4 | FRONT BUMPER GRILLE - CENTER | 1 \$ | 179.00 | ? |
| 5 | FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE | 1 \$ | 571.00 | ? |
| 6 | FRONT BUMPER CLOSING ELEMENT - LH / RH | 2 \$ | 636.00 | ? |
| 7 | FRONT BUMPER TRIM COVER - LH / RH | 2 \$ | 364.00 | ? |
| 8 | FRONT WHEEL HOUSING LINER ADAPTER - LH / RH | 2 \$ | 84.00 | X |
| 9 | RADIATOR GRILLE | 1 \$ | 1,578.00 | car ✓ |
| 10 | RADIATOR GRILLE CLOSING ELEMENT | 1 \$ | 210.00 | ? |
| 11 | FRONT BUMPER AIR GUIDE GRILLE - LH / RH | 2 \$ | 420.00 | ? |
| 12 | FRONT BUMPER REINFORCEMENT BEAM | 1 \$ | 847.00 | ? |
| 13 | FRONT BUMPER FOAM FILLER PIECE | 1 \$ | 211.00 | de ✓ |
| 14 | FRONT BUMPER REINFORCEMENT BEAM COVER | 1 \$ | 136.00 | de ✓ |
| 15 | HORN HIGH TONE - LH | 1 \$ | 213.00 | ? |
| 16 | HORN LOW TONE - RH | 1 \$ | 213.00 | ? |
| 17 | AIR CONDITIONER STICKER | 1 \$ | 9.00 | de ✓ |
| 18 | CAUTION SIGN STICKER | 1 \$ | 16.00 | de ✓ |
| 19 | FRONT FENDER - LH / RH | 2 \$ | 1,908.00 | LH bt ✓, RH X |
| 20 | FRONT FENDER ATTACHMENT PARTS | 1 \$ | 75.00 | ? |
| SUB TOTAL SPARE PARTS | | : | \$ 10,383.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
TEL : 6366 2323 FAX : 6841 1183
EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|--|-----|------------------------|-----------------------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 21 | FRONT FENDER BRACKET - LH / RH | 2 | \$ RHX 92.00 | LM bt - |
| 22 | FRONT FENDER RIVET | 11 | \$ 42.00 | net - |
| 23 | FRONT FENDER BRACE | 1 | \$ 107.00 | ? |
| 24 | FRONT WHEEL HOUSING LINER - LH / RH | 2 | \$ 366.00 | ? |
| 25 | FRONT WHEEL HOUSING LINER ATTACHMENT PARTS | 1 | \$ 93.00 | ? |
| 26 | BONNET | 1 | \$ 3,348.00 | bt - |
| 27 | BONNET ATTACHMENT PARTS | 1 | \$ 172.00 | X |
| 28 | BONNET HINGE - LH / RH | 2 | \$ 136.00 | bt - photo. |
| 29 | BONNET EDGE PROTECTION | 1 | \$ 31.00 | net - |
| 30 | BONNET CATCH HOOK | 1 | \$ 100.00 | ? |
| 31 | BONNET STRIKER - LH / RH | 2 | \$ 246.00 | ? |
| 32 | BONNET SIDE SEAL - LH | 1 | \$ 46.00 | ? |
| 33 | BONNET CATCH HOOK | 1 | \$ 71.00 | ? |
| 34 | BONNET LOCK - LH / RH | 2 | \$ 455.00 | ? |
| 35 | BONNET BOWDEN CABLE - CENTER | 1 | \$ 64.00 | ? |
| 36 | BONNET BOWDEN CABLE COVER | 1 | \$ 11.00 | ? |
| 37 | BONNET LOCK CABLE | 1 | \$ 82.00 | ? |
| 38 | EXHAUST SOUND ABSORBER | 1 | \$ 244.00 | ? |
| 39 | PLENUM CHAMBER COVER | 1 | \$ 199.00 | art - |
| 40 | HEADLIGHT - LH / RH | 2 | \$ 11,758.00 | RH - ? LM - alt photo |
| SUB TOTAL SPARE PARTS | | : | \$ 17,663.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - FRONT

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|------------------------------------|------|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 41 | LIFT CYLINDER - LH / RH | 2 \$ | 312.00 | ? |
| 42 | LIFT CYLINDER HOSE | 1 \$ | 78.00 | ? |
| 43 | LOCK CARRIER | 1 \$ | 806.00 | ? |
| 44 | OUTSIDE TEMPERATURE SENSOR BRACKET | 1 \$ | 21.00 | ? |
| 45 | A/C CONDENSER | 1 \$ | 570.00 | ? |
| 46 | A/C CONDENSER REFRIGERATN LINE | 1 \$ | 500.00 | ? |
| 47 | A/C CONDENSER REFRIGERANT LINE | 1 \$ | 570.00 | ? |
| 48 | A/C CONDENSER REFRIGERANT LINE | 1 \$ | 623.00 | ? |
| 49 | RADIATOR ADDITIONAL COOLER | 1 \$ | 961.00 | ? |
| 50 | RADIATOR | 1 \$ | 1,064.00 | ? |
| 51 | READY-MIX COOLANT | 6 \$ | 297.00 | ? |
| 52 | RADIATOR FAN WITH FAN RING | 1 \$ | 1,617.00 | ? |
| 53 | RADIATOR AIR GUIDE - LH / RH | 2 \$ | 56.00 | ? |
| 54 | RADIATOR OUTER SEAL - RH | 1 \$ | 9.00 | ? |
| 55 | RADIATOR AIR GUIDE - UPPER CENTRE | 1 \$ | 14.00 | ? |
| 56 | RADIATOR COVER | 1 \$ | 30.00 | ? |
| 57 | RADIATOR AIR GUIDE | 1 \$ | 59.00 | ? |
| 58 | RADIATOR WATER DRAINAGE HOSE | 1 \$ | 37.00 | ? |
| 59 | RADIATOR AIR GUIDE | 1 \$ | 21.00 | ? |
| 60 | RADIATOR AIR GUIDE | 1 \$ | 69.00 | ? |
| SUB TOTAL SPARE PARTS | | : | \$ 7,714.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B

| | | | DAMAGED PARTS & PRICES | |
|----------------------------------|---------------------------------------|--------|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 61 | RADIATOR AIR FILTER | 1 \$ | 337.00 ? | |
| 62 | RADIATOR INTAKE MANIFOLD | 1 \$ | 788.00 ? | |
| 63 | FRONT WINDSCREEN | 1 \$ | 1,206.00 ? | |
| 64 | FRONT WINDSCREEN RAIN SENSOR GEL FOIL | 1 \$ | 131.00 ? | |
| 65 | SPRING CLIP | 1 \$ | 23.00 ? | |
| 66 | WINDSCREEN PRIMER | 1 \$ | 22.00 ? | |
| 67 | WINDSCREEN WATER DEFLECTOR STRIP - LH | 1 \$ | 104.00 de ✓ | |
| 68 | WINDOW SLOT SEAL TRIM STRIP - LH | 1 \$ | 346.00 ? | |
| 69 | WINDOW GUIDE TRIM STRIP - LH | 1 \$ | 287.00 X | |
| 70 | FRONT NO PLATE | S/N \$ | 60.00 bt - | |
| 71 | FRONT WINDSCREEN SEALANT | S/N \$ | 200.00 ? | |
| TOTAL SPARE PARTS - FRONT | | : | \$ 39,264.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|--|------|------------------------|------------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 1 | REAR BUMPER | 1 | \$ 2,317.00 | de ✓ |
| 2 | REAR BUMPER FIXING PARTS | 1 | \$ 201.00 | X |
| 3 | REAR WHEEL HOUSING LINER ADAPTER - LH / RH | 2 | \$ LHX 84.00 | RH de ✓ |
| 4 | REAR BUMPER GUIDE SECTION - LH / RH | 2 | \$ LHX 36.00 | RH mis ✓ |
| 5 | REAR BUMPER LOCKING MECHANISM - LH / RH | 2 | \$ LH? 67.00 | RH na ✓ |
| 6 | REAR BUMPER SPOILER | 1 | \$ 264.00 | de ✓ |
| 7 | REAR BUMPER REFLECTOR - LH / RH | 2 | \$ RH? 92.00 | LH - con ✓ |
| 8 | REAR OUTER TAIL LIGHT - LH / RH | 2 | \$ RHX 1,948.00 | LH cut ✓ |
| 9 | REAR OUTER TAIL LIGHT TRIM - LH / RH | 2 | \$ 68.00 | cut ✓ |
| 10 | REAR INNER TAIL LIGHT - LH / RH | 2 | \$ 1,948.00 | ? |
| 11 | REAR INNER TAIL LIGHT TRIM - LH / RH | 2 | \$ 68.00 | ? |
| 12 | REAR LICENCE PLATE LIGHT - LH / RH | 2 | \$ 210.00 | X |
| 13 | REAR BUMPER REINFORCEMENT BEAM | 1 | \$ 642.00 | bt photo. |
| 14 | REAR BUMPER BRACKET - LH / RH | 2 | \$ 63.00 | buo ✓ |
| 15 | REAR BUMPER GUIDE SECTION - LH / RH | 2 | \$ 149.00 | ? |
| 16 | REAR PARKING AID SENSOR - INNER / OUTER | 2, 4 | \$ 1,062.00 | mis ✓ |
| 17 | REAR PARKING AID SEAL RING | 4 | \$ 10.00 | na ✓ |
| 18 | REAR BUMPER WIRING SET | 1 | \$ 572.00 | ? |
| 19 | REAR BUMPER AERIAL KEY ACCESS | 1 | \$ 79.00 | ? mis ✓ |
| 20 | REAR LID | 1 | \$ 3,657.00 | bt ✓ |
| SUB TOTAL SPARE PARTS | | : | \$ 13,537.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

| | | | DAMAGED PARTS & PRICES | | |
|------------------------------|------------------------------------|-----|------------------------|---------|--|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS | |
| 21 | REAR LID ATTACHMENT PARTS | 1 | \$ 308.00 | ? | |
| 22 | REAR LID HINGE - LH / RH | 2 | \$ 570.00 | dt ✓ | |
| 23 | REAR LID FLAP GASKET | 1 | \$ 229.00 | de ✓ | |
| 24 | REAR LID LOCK STRIKER | 1 | \$ 56.00 | ? | |
| 25 | REAR LID LOCK | 1 | \$ 211.00 | ? | |
| 26 | REAR LID LOCK COVER | 1 | \$ 8.00 | int ✓ | |
| 27 | REAR LID LOCK ACTUATOR PUSH BUTTON | 1 | \$ 1,478.00 | X | |
| 28 | REAR LID LOCK ACTUATOR COVER | 1 | \$ 18.00 | X | |
| 29 | PACKING ADHESIVE | 1 | \$ 21.00 | ng ✓ | |
| 30 | AUDI EMBLEM | 1 | \$ 144.00 | ner ✓ | |
| 31 | "A3" INSCRIPTION | 1 | \$ 104.00 | ner ✓ | |
| 32 | "TFSI" INSCRIPTION | 1 | \$ 104.00 | ner ✓ | |
| 33 | REAR SIDE PANEL - RH | 1 | \$ 4,445.00 | X | |
| 34 | REAR WINDOW | 1 | \$ 905.00 | X | |
| 35 | REAR QUARTER WINDOW - RH | 1 | \$ 635.00 | X | |
| 36 | WINDOW PRIMER | 2 | \$ 44.00 | X | |
| 37 | REAR FUEL POCKET | 1 | \$ 100.00 | X | |
| 38 | REAR FUEL POCKET HOSE | 1 | \$ 20.00 | X | |
| 39 | REAR WHEEL HOUSING LINER - LH / RH | 2 | \$ 520.00 | ? | |
| 40 | REAR VENT TRIM | 1 | \$ 75.00 | X | |
| SUB TOTAL SPARE PARTS | | : | \$ 9,995.00 | | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

| | | | DAMAGED PARTS & PRICES | |
|------------------------------|---|------|------------------------|------------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 41 | REAR CROSS PANEL | 1 \$ | 379.00 | bt ✓ |
| 42 | REAR CROSS PANEL REINFORCEMENT | 1 \$ | 773.00 | ? |
| 43 | REAR CROSS PANEL CONNECTING PLATE - LH / RH | 2 \$ | 322.00 | ? |
| 44 | REAR CROSS PANEL BOTTOM PLATE | 1 \$ | 737.00 | ? |
| 45 | REAR CROSS PANEL MOUNT BRACKET | 1 \$ | 91.00 | ? |
| 46 | REAR CROSS PANEL TRIM | 1 \$ | 171.00 | de ✓ |
| 47 | REAR LUGGAGE COMPARTMENT FLOOR COVERING | 1 \$ | 602.00 | zua ✓ |
| 48 | REAR LUGGAGE COMPARTMENT TRIM - RH | 1 \$ | 841.00 | ? |
| 49 | REAR LID TRIM PANEL | 1 \$ | 345.00 | th ✓ |
| 50 | REAR STOWAGE COMPARTMENT | 1 \$ | 105.00 | ? |
| 51 | REAR SILENCER | 1 \$ | 825.00 | X |
| 52 | EXHAUST SYSTEM RETAINER | 2 \$ | 95.00 | X |
| 53 | EXHAUST HEAT SHIELD | 1 \$ | 180.00 | ? |
| 54 | THREE-POINT AUTOMATIC SEAT BELT - LH / RH | 2 \$ | 2,454.00 | act ✓ |
| 55 | SEAT BELT HEIGHT ADJUSTER - LH / RH | 2 \$ | 430.00 | ? plus to. |
| 56 | AIRBAG CONTROL UNIT | 1 \$ | 1,923.00 | neu ✓ |
| 57 | REAR FUEL POCKET | 1 \$ | 100.00 | X |
| 58 | REAR FUEL POCKET HOSE | 1 \$ | 20.00 | X |
| 59 | REAR WHEEL HOUSING LINER - LH / RH | 2 \$ | 520.00 | X |
| 60 | REAR VENT TRIM | 1 \$ | 75.00 | X |
| SUB TOTAL SPARE PARTS | | : | \$ 10,988.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SLU 7364 B - REAR

| | | | DAMAGED PARTS & PRICES | |
|--|-------------------------|--------|------------------------|---------|
| S/N | PARTS DESCRIPTION | QTY | S/NETT | REMARKS |
| 61 | REAR NO PLATE | S/N \$ | 60.00 | int ✓ |
| 62 | REAR WINDSCREEN SEALANT | S/N \$ | 200.00 | X |
| 63 | ACRYLIC SEALANT | S/N \$ | 180.00 | na ✓ |
| 64 | CAVITY WAX | S/N \$ | 140.00 | na ✓ |
| 65 | STONE CHIP | S/N \$ | 180.00 | na ✓ |
| 66 | METAL FILLER POWDER | S/N \$ | 280.00 | na ✓ |
| 67 | SUNDRIES | \$ | 1,000.00 | ? |
| TOTAL SPARE PARTS - FRONT & REAR | | : | \$ 75,824.00 | |
| TOTAL LABOUR CHARGES - FRONT & REAR | | : | \$ 57,744.00 | |
| GRAND TOTAL | | : | \$ 133,568.00 | |

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

NAME :
SURVEYED DATE :
AUTHORISED DATE :
EXCESS COST :
LIABILITY :
REMARKS :

Taufik 97495749
Wp Not Authorise Ex: to be advise
taufik@khairto.com.
17 days.
Resurvey before paint
4 21/10/27 @ 330pm.

PLEASE NOTE :

THIS ESTIMATE IS BASED ON VISUAL INSPECTION OF THE AFFECTED VEHICLE. SHOULD WE REQUIRE FURTHER LABOUR CHARGES AND SPARE PARTS IN THE PROGRESS OF REPAIR, WE SHALL INFORM YOU ACCORDINGLY. FOR INSPECTION OF VEHICLE, PLEASE REFER TO MS. NORAH KHAI AT TEL: 6768 9828 / 6768 9911 FOR APPOINTMENT.

YOURS FAITHFULLY,
PREMIUM AUTOMOBILES PTE LTD

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

JOHNNY BOO
BODY REPAIR MANAGER

ALLAN WU
CLAIMS CONSULTANT



SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

| | |
|---------------------------------|---|
| Date of Submission | 18/10/2022 15:04 (SGT) |
| Reported by | Both |
| Date of Accident | 18/10/2022 08:10 (SGT) |
| Exact Location of Accident | PIE, Singapore |
| Additional Location Information | PIE (TOWARDS TUAS), AFTER STEVENS EXIT, LAMP POST 929 |
| Country/State of Loss | Singapore |

DETAILS OF OWN VEHICLE

| | |
|-----------------------------|----------|
| Vehicle Registration Number | SLU7364B |
|-----------------------------|----------|

INSURED/POLICYHOLDER

| | |
|--------------------------|----------------------|
| Is company? | No |
| Name Of Registered Owner | CHONG MINGYONG |
| NRIC No | SXXXX528I |
| Email Address | CMINGYONG@YAHOO.COM |
| Mobile Phone No | (Phone) +65-90108531 |
| Alternative Phone No | - |

VEHICLE PARTICULARS

| | |
|--|-------------------|
| Manufacturer | Audi |
| Model | A3 |
| Variant | SEDAN 1.0 TFSI 8V |
| Exact purpose for which vehicle was being used at time of accident | Private use |
| Are you claiming under your own insurance policy for repair to your vehicle? | Yes |
| Vehicle Category | Private car |
| Transmission | Auto |
| CC | 999 |

INSURANCE COMPANY

| | |
|-----------------------------------|--------------------------------------|
| Name of Insurance Company | AIG Asia Pacific Insurance Pte. Ltd. |
| Policy Number / Cover Note Number | - |

DRIVER

| | |
|----------------|----------------|
| Name of Driver | CHONG MINGYONG |
| NRIC No | SXXXX528I |
| Date Of Birth | 28/07/1983 |



| | |
|--|----------------------------|
| Occupation | Indoor |
| Date Of Driving Pass | 18/02/2004 |
| Driving experience | 18 YEARS AND 8 MONTHS |
| Gender | Male |
| Mobile Number | (Phone) +65-90108531 |
| Alt. Phone Number | - |
| Email Address | CMINGYONG@YAHOO.COM |
| Address | BLK 167C SIMEI LANE #07-28 |
| Address complement | - |
| Postcode | 523167 |
| Is the driver the policyholder? | Yes |
| If No, Relationship of the Driver with the Insured | - |
| Does Driver Own Other Vehicles? | No |
| Vehicle Registration Number of Other Vehicle Owned by Driver | - |
| Insurance Company of Other Vehicle Owned by Driver | - |

GENERAL INFORMATION OF THE ACCIDENT

| | |
|--------------------------|-----------------|
| Type of Accident | Chain Collision |
| Weather Conditions | Clear |
| Road Surface | Wet |

OTHER INFORMATION

| | |
|---|-----|
| Was any foreign vehicle involved in the accident? | No |
| Number of vehicles involved in the accident | 3 |
| Was anybody injured in the Accident? | Yes |
| Was any injured conveyed to hospital by ambulance? | No |
| Was any other vehicle or property damaged? | Yes |
| Number of Passengers (Including Driver) | 4 |
| Has the driver been approached by unknown person(s) soliciting/offering accident claims assistance? | No |
| Translator's name | - |
| Translator's ID | - |
| Translator's phone number | - |
| Translator's email | - |
| Original language used in the statement | - |

PASSENGER 1

| | |
|--------------|-----------------------|
| Name | THUM MAY CHENG JOANNA |
| Gender | Female |

PASSENGER 2

| | |
|--------------|------------------------|
| Name | CHONG QING YUE REBECCA |
| Gender | Female |

PASSENGER 3

| | |
|--------------|---------------------|
| Name | CHONG QING EN EMILY |
| Gender | Female |

DETAILS OF POLICE ACTION

| | |
|---|----|
| Was the accident reported to the police? | No |
| Was notice of intended Prosecution given? | No |
| If yes, against whom? | - |

CIRCUMSTANCES OF ACCIDENT

Was travelling along PIE, after Stevens Road exit. Due to traffic build up, was starting to slow down the car, when the car behind banged into my car rear. The impact caused the car to move forward, hitting the front car.

ATTACHMENT(S)

Are accident photos available for attachment? Yes
Was there any video captured by Car Camera? No

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SMA3018X
Vehicle Manufacturer Hyundai
Vehicle Model Elantra
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver ISAAC CHNG YONG LUN
Contact Number (Phone) +65-91557125
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) 1

DETAILS OF OTHER VEHICLE PROPERTY 2

Vehicle Registration Number SMG6622A
Vehicle Manufacturer BMW
Vehicle Model -
Vehicle Variant -
Vehicle Colour -
Vehicle Category Private car
Name of Driver PUAN REN WEI
Contact Number (Phone) +65-96384676
Address -
Address complement -
Postcode -
Insurance Company Name -
Nature Of Damage -
Details of property damaged in accident -
No. Of Passenger (Including Driver) 1

INJURED PERSONS DETAILS

INJURED 1

Name of injured person JOANNA THUM
Gender Female
Phone No (Phone) +65-97801762
Address -
Address Complement -
Post Code -
Approximate Age Years Old 39
Injuries Sustained -
Injured person in which vehicle? SLU7364B
Were seat belts worn? -
Was this injured conveyed to hospital by ambulance? No

INJURED 2

Name of injured person CHONG MINGYONG
Gender Male
Phone No (Phone) +65-90108531
Address BLK 167C SIMEI LANE #07-28
Address Complement -
Post Code 523167
Approximate Age Years Old 39
Injuries Sustained -
Injured person in which vehicle? SLU7364B

| | |
|---|------------------------|
| Were seat belts worn? | - |
| Was this injured conveyed to hospital by ambulance? | No |
| INJURED 3 | |
| Name of injured person | CHONG QING YUE REBECCA |
| Gender | Female |
| Phone No | - |
| Address | - |
| Address Complement | - |
| Post Code | - |
| Approximate Age Years Old | - |
| Injuries Sustained | - |
| Injured person in which vehicle? | - |
| Were seat belts worn? | - |
| Was this injured conveyed to hospital by ambulance? | - |
| INJURED 4 | |
| Name of injured person | - |
| Gender | - |
| Phone No | - |
| Address | - |
| Address Complement | - |
| Post Code | - |
| Approximate Age Years Old | 9 |
| Injuries Sustained | - |
| Injured person in which vehicle? | SLU7364B |
| Were seat belts worn? | - |
| Was this injured conveyed to hospital by ambulance? | No |
| INJURED 5 | |
| Name of injured person | CHONG QING EN EMILY |
| Gender | Female |
| Phone No | - |
| Address | - |
| Address Complement | - |
| Post Code | - |
| Approximate Age Years Old | 7 |
| Injuries Sustained | - |
| Injured person in which vehicle? | SLU7364B |
| Were seat belts worn? | - |
| Was this injured conveyed to hospital by ambulance? | No |

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**
I understand, acknowledge, agree and consent that :
(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
(ii) investigating the accident and/or my claims;
(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
(collectively the "Purposes")
(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Sketch Plan

A: SLV 7364 B
B: SMA 3018 X
C: SMC 6622-A




Describe Circumstances of the Accident

Was travelling along PIE, after Stivers Road exit. ~~When~~ Due to traffic build up, was starting to slow down the car, when the car behind braked into ^{my} car rear. The impact caused the car to move forward, hitting the front car.

Declaration

We declare the foregoing particulars are true in every respect.

 13/10/22
Policyholder's Signature / Date & Time

Driver's Signature (If driver is not the policyholder) / Date & Time

 
Witnessed by Reporting Centre Personnel