

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile					
	INCOME INSURAN	ICE LTD	Ref:	CS3/INC22008478/Acy3m4-1	
	75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557		Date:	30/11/2022	
	ATTN: EILEEN LEI	≣	Code:	INC	
1.	Policy Particulars :- THIRD PARTY CLAIM				
	Insured Veh.	GX 1206H	Veh. Inspected	SGK 4124J	
	Policy No.		Coverage (\$)	0.00	
	Claim No.	MT/1186228-002	Excess (\$)	0.00	
	Assign From		Assign Date	25/10/2022	
2. Vehicle Particulars & Condition					
	Make & Model	KIA FORTE K3	c.c	1591	
	Engine No.	HIDDEN	Year of Reg.	2015	
	Chassis No.	KNAFX411MF5471648	Colour	GREY	
	Odometer	210439 KM	Steering	IN ORDER	
	Brakes	IN ORDER	Modification	SPORTS RIM	
	General	GOOD			
3.	3. Conditions of Tyres				
		Size	Make	Balance	
	R/H Front Tyre	205/55 R16	PIRELLI	6 mm	
	L/H Front Tyre	205/55 R16	PIRELLI	6 mm	
	R/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
	L/H Rear Tyre	205/55 R16	PIRELLI	6 mm	
4.	Description of Damages				
	THE VEHICLE SUSTAINED DAMAGES AT THE O/S BODY & UNDERCARRIAGE.				
	DAMAGES SEE DETAILS.				
5.	General Information				
	Accident Date	28/08/2022	Inspection Date	31/08/2022	
	Survey held at	QMO ENGINEERING			
	10 KAKI BUKIT ROAD 2, #03-18, FIRST EAST CENTRE, SINGAPORE 417868				
5a.	Remarks				
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b.	Estimate Days of Repair				
	ESTIMATED NORMAL PERIOD FOR REPAIR: 9 Working Days				