

View Sent Message

This mail is associated with :

SMH5851G (SNM22D207552/C01/LEEPG)

OD

Oct 20 2022 11:00PM

[EDMUND TAN YONG SIANG]

Ding Auto Pte Ltd

[Resend](#) [View Recipients](#) [Print Message](#) [Delete Message](#) [Forward](#)

From LKK Auto Consultants Pte Ltd (LKK_HQ), sent on **10/11/2022 17:19 PM.**
To sur@lkkauto.com; assignments@lkkauto.com; CHINA_TAIPING
CC cecilia.lee@sg.cntaiping.com
Subject **Re: SMH5851G (SNM22D207552/C01/LEEPG)**

Dear Cecilia,

1) list of modified parts and if the parts required LTA's approval
- Exhaust filter, front strut bar and after market front bumper.

2) whether the modified parts is/are the proximate cause of accident
- No

Best Regards,

Huey Yon | case handler

LKK Auto Consultants Pte.Ltd.

Phone: 6256-3561 Fax: 62564315 email: hueyyon@lkkauto.com

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, Singapore 408933

<-- Original Message -->

From: CHINA_TAIPING

To: LKK_HQ; sur@lkkauto.com; assignments@lkkauto.com

CC: cecilia.lee@sg.cntaiping.com

Sent On: 10/11/2022 03:19 PM

Subject: SMH5851G (SNM22D207552/C01/LEEPG)

Hi LKK

Please refer to our earlier conversation.

Please let us have the following:

1) list of modified parts and if the parts required LTA's approval
2) whether the modified parts is/are the proximate cause of accident

We look forward to hearing from you soon.

Thanks & Regards

Cecilia Lee

DOCUMENTS SUMMARY

There are no documents.

