

# AH LIM MOTOR COMPANY

176 Sin Ming Drive #05-12 Sin Ming Autocare Singapore 575721  
TEL: 6456 3637 FAX: 6456 3686 Email: admin@almsm.com.sg  
GST:M9-0009639-E RCB NO:06470300B

SURVEYOR COPY

M/S : TAN CHOON HUAT ALLAN  
BLK 407A FERNVALE ROAD  
#15-15  
SINGAPORE 791407

Estimate No: MCS1900740  
Date: 19 Oct 2022  
Policy No: D22MTPV0101  
Veh Reg No: SLS3377B  
Make/Model: BMW 520I

ATTN: Motor Claim Department  
Your Ref No: SLS3377B  
Claim Type: Third Party  
Accident Date: 18/10/2022  
TP Veh Reg No: YP8157Z

TP Sampo.

Xiao Chen.

## Estimate Repair Cost to Vehicle No : SLS3377B

| Description                                                                            | U/Price | Quantity | Cost<br>SS  | Amount<br>SS |
|----------------------------------------------------------------------------------------|---------|----------|-------------|--------------|
| <b>SPARE PARTS</b>                                                                     |         |          |             |              |
| 1 REAR BUMPER                                                                          |         | 1 PC     | 1,550.00    | ✓            |
| 2 REAR BUMPER CENTRE CHROME MOULDING                                                   |         | 1 PC     | 175.00      | ✓            |
|                                                                                        |         |          | 1,725.00    |              |
|                                                                                        | 1725    | Add 25%  | 431.25      | 2,156.25     |
| <b>LABOUR</b>                                                                          |         |          |             |              |
| 3 TO CHECK WIRING                                                                      |         | 1 PC     | 20.00       | ✓            |
| 4 TO DISMANTLE AND REPLACE DAMAGE PARTS, TO KNOCK, ALIGN AND REPAIR REAR AFFECTED AREA |         | 1 PC     | 350.00      | 200          |
| 5 TO SPRAY REAR BUMPER                                                                 | 470     | 1 PC     | 300.00      | 250          |
|                                                                                        |         |          |             | 670.00       |
| Repair Amount                                                                          |         |          | SS 2,826.25 |              |
| Add GST @ 7%                                                                           |         |          |             | 197.84       |
| Total Amount payable                                                                   |         |          |             | SS 3,024.09  |

TOTAL: SINGAPORE DOLLAR THREE THOUSAND TWENTY FOUR AND CENTS NINE ONLY

For AH LIM MOTOR COMPANY

\* should be discount instead cost +  
\* resurvey photo - reforward



AUTHORISED SIGNATURE

total: 2626.25 Admin Lg  
A/S: 2.1K H/S 25/10/22  
02 Days  
96893735

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: