

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATE : ACCIDENT REPAIRS
WORKSHOP : UBI ROAD 1
CONTACT NO : 6366 2323
FAX NO : 6841 1183
REFERENCE : PA/OD/0910/2022/EQ
DATE : 20-Oct-22
WIP : 46928

VEHICLE IN WORKSHOP. KINDLY ARRANGE FOR SURVEY ON 21/10/2022

AIG ASIA PACIFIC INSURANCE PTE LTD

78 SHENTON WAY

#07-16 AIG BUILDING

SINGAPORE 079120

Attn: Motor Claims Dept

Tel: 6880 4602 - Fax: 6880 4838

Hi Guo Qiang
4 days - ok - Johnny Boo
29-Nov-22

OWNER'S NAME : MR ZHANG QUN
ADDRESS : 46 FABER WALK
#04-24, WATERFRONT @ FABER
SINGAPORE 128992
TELEPHONE : HP +65 83868708
TYPE OF CLAIM : OWN DAMAGE CLAIM
POLICY NO : 1900018296-01
VEHICLE NO : **SMJ 465 K**
MODEL CODE : AUDI A4 SEDAN 2.0 TFSI 8W
MODEL YEAR : 20/2/2019
ENGINE NO : CVK 075692
CHASSIS NO : WAUZZZF48KN006725
MILEAGE : 7,064
DATE IN : 19-Oct-22
ESTIMATED BY : JOHNNY BOO / ALLAN WU
ACCIDENT DATE : 19-Oct-22
PLACE OF ACCIDENT : 60 CHESTNUT AVENUE

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SMJ 465 K

S/N	NATURE OF JOBS		ESTIMATED CHARGES		SURVEYOR'S RECOMMENDATIONS
1	TO REMOVE, CHECK AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS, HORNS, OUTSIDE TEMPERATURE SENSOR, HEADLIGHT WASHER ASSY AND FRONT PARKING AID.	S/N \$	480.00	\$	480.00
2	TO REMOVE AND TRANSFER RHS HEADLIGHT'S CONTROL UNIT AND POWER MODULE.	S/N \$	350.00	\$	250.00
3	TO DISMANTLE AND RENEW FRONT BUMPER, RHS FRONT FENDER AND RHS HEADLIGHT. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$	2,100.00	\$	1,000.00
4	TO RESPRAY FRONT BUMPER AND RHS FRONT FENDER.	\$	2,000.00	\$	1,100.00
5	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$	192.00	\$	192.00
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$	3,022.00

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	FRONT BUMPER	1	\$ 2,377.00	\$ 1,901.60
2	FRONT BUMPER FIXING PARTS	1	\$ 612.00	
3	FRONT BUMPER SECURING STRIP - LH / RH	2	\$ 79.00	
4	FRONT BUMPER GRILLE - CENTER	1	\$ 219.00	
5	FRONT BUMPER CLOSING ELEMENT - LOWER CENTRE	1	\$ 254.00	\$ 203.20
6	FRONT BUMPER AIR GUIDE - RH	1	\$ 72.00	\$ 57.20
7	RADIATOR GRILLE	1	\$ 1,478.00	
8	FRONT BUMPER AIR GUIDE GRILLE - RH	1	\$ 151.00	\$ 120.40
9	FRONT BUMPER GUIDE SECTION - RH	1	\$ 41.00	\$ 32.24
10	FRONT BUMPER FOAM FILLER PIECE	1	\$ 139.00	
11	FRONT BUMPER REINFORCEMENT BEAM	1	\$ 899.00	
12	FRONT BUMPER TOP COVER	1	\$ 143.00	
13	CAUTION SIGN STICKER	1	\$ 16.00	
14	AIR CONDITIONER STICKER	1	\$ 9.00	
15	FRONT BUMPER BRACKET	1	\$ 154.00	
16	FRONT BUMPER SUPPORT - LH / RH	2	\$ 64.00	
17	FRONT PARKING AID SENSOR - INNER / OUTER	2	\$ 531.00	
18	FRONT PARKING AID SEAL RING	4	\$ 10.00	
19	HORN LOW TONE - RH	1	\$ 139.00	
20	HORN BRACKET - RH	1	\$ 33.00	
SUB TOTAL SPARE PARTS		:	\$ 7,420.00	\$ 2,314.64

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES		
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS	
		C/F		\$	2,314.64
21	FRONT FENDER - RH	1	\$ 861.00	\$	688.80
22	FRONT FENDER ATTACHMENT PARTS	1	\$ 225.00		
23	FRONT FENDER CLOSING ELEMENT - RH	1	\$ 81.00	\$	64.24
24	FRONT FENDER BRACKET - RH	1	\$ 41.00	\$	32.72
25	FRONT FENDER RIVET	7	\$ 27.00	\$	21.28
26	FRONT FENDER DEFORMATION ELEMENT BRACKET - RH	1	\$ 55.00		
27	FRONT FENDER BRACE - RH	1	\$ 132.00	\$	105.20
28	FRONT WHEEL HOUSING LINER - RH	1	\$ 262.00	\$	209.60
29	FRONT WHEEL SPOILER	1	\$ 82.00	\$	65.12
30	FRONT BUMPER SPOILER - RH	1	\$ 40.00	\$	32.00
31	FRONT FENDER LEDGE COVER - RH OUTER	1	\$ 35.00		
32	FRONT FENDER LEDGE COVER - RH	1	\$ 26.00	\$	20.16
33	HEADLIGHT - RH	1	\$ 8,294.00	\$	6,635.20
34	HEADLIGHT HOSE - RH	1	\$ 42.00		
35	LIFT CYLINDER - RH	1	\$ 231.00		
36	LIFT CYLINDER BRACKET	1	\$ 7.00		
37	LIFT CYLINDER CORRUGATED PIPE	1	\$ 107.00		
38	LIFT CYLINDER CORRUGATED PIPE	1	\$ 45.00		
39	OUTSIDE TEMPERATURE SENSOR BRACKET	1	\$ 21.00		
40	RADIATOR AIR GUIDE - RH INNER	1	\$ 32.00		
SUB TOTAL SPARE PARTS		:	\$ 10,646.00	\$	10,188.96

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699

TEL : 6366 2323 FAX : 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SMJ 465 K

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
		C/F		\$ 10,188.96
41	RADIATOR AIR GUIDE - RH OUTER	1	\$ 14.00	
42	RADIATOR AIR GUIDE - UPPER CENTER	1	\$ 19.00	
43	RADIATOR AIR GUIDE - LH OUTER	1	\$ 14.00	
44	FRONT NO PLATE	S/N	\$ 60.00	
45	SUNDRIES		\$ 400.00	
TOTAL SPARE PARTS		:	\$ 18,573.00	\$ 10,188.96
TOTAL LABOUR CHARGES		:	\$ 5,122.00	\$ 3,022.00
GRAND TOTAL		:	\$ 23,695.00	\$ 13,210.96

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.
 BL-29/11/22