



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
AUTO & GENERAL INSURANCE (S) PL (BUDGET DIRECT INSURANCE) 190 CLEMENCEAU AVENUE #03-01 SINGAPORE SHOPPING CENTRESINGAPORE 239924			Ref: CS/AGI22010513/Evy3q2 Date: 01/12/2022	Code: AGI
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SKA 6557K	Veh. Inspected	SJF 6279Z	
Policy No.	P10658606R00	Coverage (\$)	0.00	
Claim No.	C10018089/JY	Excess (\$)	0.00	
Assign From	SALIZAWATI HAIZAR	Assign Date	21/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA STREAM	c.c	1799	
Engine No.	HIDDEN	Year of Reg.	2008	
Chassis No.	RN61061439	Colour	BLACK	
Odometer	179336 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/45 R17	WEST LAKE	5 mm	
L/H Front Tyre	215/45 R17	WEST LAKE	5 mm	
R/H Rear Tyre	215/45 R17	WEST LAKE	5 mm	
L/H Rear Tyre	215/45 R17	WEST LAKE	5 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR N/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	15/10/2022	Inspection Date	25/10/2022	
Survey held at	XINYA AUTO SERVICES PTE LTD BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			4 Working Days	