

XINYA AUTO SERVICES PTE LTD

Address: BLK 1002 BUKIT MERAH LANE 3 #01-75 SINGAPORE 159719

E-mail : xinyaauto@gmail.com

Tel: 6270 3481 Fax: 6278 7522

Date : 21.10.2022

Address : AUSTIN LUCKY TAN LAN SIONG
BLK 93A TELOK BLANGAH ST.31
#30-151
SINGAPORE 101093

Reference : TP 1328/10/22
Vehicle No : SJF6279Z
Make/Model : HONDA STREAM
Insurance Co. : ETIQA

RE : QUOTATION REPAIRS TO SJF 6279Z FOR THIRD PARTY CLAIMS.

PARTS REQUIRED	QTY	AMT \$
1) REAR ABSORBER LH ? ✓ BT	1	\$ 270.60 ✓
2) REAR ABSORBER SPRING X NN	1	\$ 231.60 X
3) REAR ABSORBER MOUNTING X ✓ NEC	1	\$ 21.80 ✓
4) REAR ABSORBER STOPPER X NN	1	\$ 24.50 X
5) REAR ABSORBER COVER X ? X NN	1	\$ 21.80 X
6) KNUCKLE ✓ BT	1	\$ 316.70 ✓
7) WHEEL HUB BEARING ? ✓ NEC	1	\$ 367.10 ✓
8) REAR LH LOWER ARM ? ✓ BT (Upper arm rear RH)	1	\$ 437.50 188 ✓
9) REAR CROSSMEMBER ? (Trailing arm rear RH) ✓ BT	1	\$ 823.60 399.50 ✓

LIST PRICE TOTAL \$ 2,515.20
LESS DISCOUNT 20% \$ 503.04
LIST PRICE TOTAL AFTER LESS \$ 2,012.16

10) TYRE RIM ✓ CUT \$ 250.00 ✓
NETT PRICE TOTAL \$250.00

TOTAL PARTS COST **\$2,262.16**

LABOUR AND MISCELLANEOUS CHARGES

- 1) TO PANEL BEAT REAR LH DOOR & FENDER & BUMPER \$ 400.00 ✓
(5 DAYS)
- 2) TO PUTTY & SPRAY PAINT REAR LH DOOR, FENDER AND BUMPER REAR \$ 600.00 ✓
(3 PANELS)
- 3) TO REMOVE & REPLACE UNDERCARRIDGE PARTS @ KNUCKLE, ABSORBER, LOWER ARM.... \$ 600.00 200
- 4) TO PUMP WHEEL BEARING \$ 120.00 30
- 5) TO COMPUTERISE WHEEL ALIGNMENT \$ 80.00 ✓

LABOUR TOTAL

\$ 1,800.00

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

4062.16

1563.70
-20%
1250.96

1310

2810.96

L/S - 2248.76
= 2250