

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|--|----------------|-------|---------------------|--|
| | | | | Ref: | CS/UOI22010525/Evy3 | |
| | | | | Date: | 25/10/2022 | |
| | | | | Code: | UOI | |
| 1. Policy Particulars :- OWN DAMAGE | | | | | | |
| | Insured Veh. | | Veh. Inspected | k | GBG 499J | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | | Excess (\$) | | 0.00 | |
| | Assign From | KATIE LEE | Assign Date | | 25/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | - | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. General Information | | | | | | |
| | Accident Date | 30/09/2022 | Inspection Dat | te | 26/10/2022 | |
| | Survey held at | GUAN LEE SENG MOTOR | | | | |
| | | BLK 3 PIONEER ROAD NORTH #01-20 SINGAPORE 628457 | | | | |
| 5a. Remarks | | | | | | |
| | A)THE MARKET VALUE IS S\$(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS. | | | | | |