



Your Ref : M11D00052210

Date: 01st Dec 2022

Our Ref : CS4/UOI22010525/Evy3m4

M/s United Overseas Insurance Ltd

146 Robinson Road

#02-01 Uoi Building

Singapore 068909

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE GBG 499J
ACCIDENT ON 30/09/2022**

Instruction was received to inspect the vehicle Reg. No. GBG 499J. The inspection was conducted on 26/10/2022 at the premises of M/s Guan Lee Seng Motor, Blk 3 Pioneer Road North, #01-20, Singapore 628457.

The following vehicle information was recorded:


Registration Number	: GBG 499J
Make/Model	: Nissan Nv200 1.5MT Abs Airbag 2WD 6DR E5 W/RC
Year of Registration	: 2017
Body Colour	: White
Chassis Number	: VSKYBAM20Z0139979
Engine Capacity	: 1461 cc

The vehicle caught fire. The cause of fire probably due to electrical short circuit. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 41,000.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 14,049.00)
Nett Liability	<u>S\$ 26,951.00</u> =====

Vehicle Inspected By:



CHEN TSUE YEE
Automotive Assessor



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.