



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
LONPAC INSURANCE BHD 300 BEACH ROAD #17-04/07 THE CONCOURSESINGAPORE 199555		Ref: CS3/LPC22007119/Tvy3m4-1 Date: 02/11/2022 Code: LPC2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	GBE 9357L	Veh. Inspected	SDD 8328J
Policy No.		Coverage (\$)	0.00
Claim No.	22/22/22/VC05/026034	Excess (\$)	0.00
Assign From	ENG HUEY NI	Assign Date	25/10/2022
2. Vehicle Particulars & Condition			
Make & Model	HONDA STREAM	c.c	1799
Engine No.	HIDDEN	Year of Reg.	2008
Chassis No.	RN61084363	Colour	SILVER
Odometer	358158 KM	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	215/55 R17	KAPSEN	6 mm
L/H Front Tyre	215/55 R17	KAPSEN	6 mm
R/H Rear Tyre	215/55 R17	KAPSEN	6 mm
L/H Rear Tyre	215/55 R17	KAPSEN	6 mm
4. Description of Damages			
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.			
5. General Information			
Accident Date	14/07/2022	Inspection Date	27/07/2022
Survey held at	1 STOP GARAGE PTE. LTD. 25 KAKI BUKIT ROAD 4 #01-52 SYNERGY @ KB SINGAPORE 417800		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		8 Working Days	