



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.
(A Member of the Oriental Holdings Berhad)

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022
255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

Customer:	CU0081564 / ALLIANZ	Document No:	SVO22048734
Chassis No:	MRHFC5650GT000939	Printed By:	IVANTEO
License No:	SJG523C	Order Date:	2. November 2022
Mileage:	94439	Order Time:	12:42:19 PM
Engine No:	R16B21601216	Service Advisor:	IVAN TEO BOON KIAT

ITEM	DESCRIPTION	QTY	UNIT PRICE	DISC %	AMOUNT	7% GST Amount	Amount incld GST
	TP DIRECT SETTLEMENT (J/NO:) OWNER: ONG HONG SENG OWNER INSURER: GREAT EASTERN ACC DATE: 21/10/2022 SURVEYED BY: DATE: REF NO: TP INSURER: ALLIANZ TP VEH: SMK9555U SUPPLEMENTARY PART						
71500-TEC-Q00ZZ	FACE ASSY,RR.BUMPER	1	617.20	25	462.90	32.40	495.30
71502-TEX-Y00	GARNISH,RR.BUMPER LOWER	1	42.00	25	31.50	2.21	33.71
71530-TEA-T00ZZ	BEAM COMPRR.BUMPER	1	190.10	25	142.57	9.98	152.55
71593-TEA-T01	SPACERR.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
71598-TEA-T01	SPACERL.RR.BUMPER SIDE	1	11.50	25	8.62	0.60	9.22
91505-TM8-003	CLIP,BUMPER	7	2.30	25	12.07	0.84	12.91
68500-TEA-305ZZ	LID COMP,TRUNK	1	724.70	25	543.52	38.05	581.57
74865-TEA-T01	WEATHERSTRIPTRUNK LID	1	70.00	25	52.50	3.68	56.18
75722-TBA-A00	EMBLEM SETRR.	1	13.60	25	10.20	0.71	10.91
75725-TEA-T01	EMBLEMRR.	1	12.70	25	9.52	0.67	10.19
66100-TEC-307ZZ	PANEL SETRR.	1	280.70	25	210.52	14.74	225.26
66154-TBA-A00ZZ	STIFFENERL.RR.PANEL SIDE (supplementary)	1 BT	30.80	25	23.10	1.62	24.72 ✓
	SUM PARTS:				1,515.64	106.10	1,621.74
BOSUN		1	50.00		50.00	3.50	53.50
	SUNDRIES						
BML02I		1	280.00		280.00	19.60	299.60
	INSPECT RR LIGHTING MECHANISMS. PERFORM WATER TEST.(N)						
BA02R		1	280.00		280.00	19.60	299.60
	REMOVE & RENEW REVERSE SENSORS-4 PCS (N)						
BC012R		1	500.00		500.00	35.00	535.00
	RESET VEHICLE SMART ENTRY SYSTEM						
BC011R		1	500.00		500.00	35.00	535.00
	REMOVE INSTALL & CALIBRATE REAR VIEW CAMERA						
BKTRR		1	480.00		480.00	33.60	513.60
	REMOVE & TRANSFER ITEMS TO NEW TRUNK LID ADJUST & ALIGN.						
BOJSE		1	120.00		120.00	8.40	128.40
	BODY JOINT SEALANT END PANEL						
BKRP02S	0671	1	3,250.00		3,250.00	227.50	3,477.50
	STRAIGHTEN ALIGN RR PANEL & RENEW DAMAGE PARTS.						
BP05R	1847	1	2,600.00		2,600.00	182.00	2,782.00
	SPRAY PAINTING ON REPAIRED OR REPLACED AREAS.(5P)						
BOBC		1	350.00		350.00	24.50	374.50



SERVICE PRE-INVOICE

KAH MOTOR CO. SDN. BHD.

(A Member of the Oriental Holdings Berhad)

370 Ubi Road 3 Singapore 408651. Tel: +65 6841 3883 Fax: +65 6741 5022

255 Alexandra Road Singapore 159937. Tel: +65 6471 5458 Fax: +65 6471 5460

GST Reg No.: M200050223
Company Ref. No.: S60FC1380G

Customer:	CU0081564 / ALLIANZ	Document No:	SVO22048734
Chassis No:	MRHFC5650GT000939	Printed By:	IVANTEO
License No:	SJG523C	Order Date:	2. November 2022
Mileage:	94439	Order Time:	12:42:19 PM
Engine No:	R16B21601216	Service Advisor:	IVAN TEO BOON KIAT

BODY UNDERSIDE COATING (N)

SUM LABOUR:	8,410.00	588.70	8,998.70
TOTAL SGD	9,925.64	694.80	10,620.44

Total Payable (SGD) 10,620.44

GST Amount is calculated from individual line(s)