



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (S) PTE LTD 4 SHENTON WAY #21-01 SGX CENTRE 2 SINGAPORE 068807		Ref: CS3/MSG22010552/Svy3 Date: 26/10/2022 Code: MSG	
1. Policy Particulars :- (THIRD PARTY CLAIM)			
Insured Veh.	SKM 871D	Veh. Inspected	SJC 3921M
Policy No.		Coverage (\$)	0.00
Claim No.	288136	Excess (\$)	0.00
Assign From	JOWYN TAY (MERIMEN)	Assign Date	26/10/2022
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	19/10/2022	Inspection Date	26/10/2022
Survey held at	PROVIDENCE MOTOR PTE LTD 11 KAKI BUKIT ROAD #03-08 EUNOS TECHNOLINK SINGAPORE 415939		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.			