

## VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation

Non binding - Preview

Page 1/3

Company  
ALLIANZ  
INSURANCE SINGAPORE PTE. LTD.  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897

Customer Details:  
Ms.  
NG  
SAN SAN  
267 TAMPINES STREET 21  
#11-17  
Singapore 520267

Document no.  
Document date  
Customer no.  
Customer GST-ID  
Dealer  
Job order number  
Job order date  
Service Advisor

25-10-2022  
5211052769  
201903913C  
30001  
2022031069/ 1  
25-10-2022  
SHU SHI TANG

| License plate | Model code | First registration | VIN              | Model                    | Mileage |
|---------------|------------|--------------------|------------------|--------------------------|---------|
| SJL1749K      | 5G13HZ     | 26-01-2017         | WWWZZZAUZH121987 | Golf 1.4 CLBM 92 TSI D7F | 105,315 |

| Position no.     | Description                                    | Quantity | Unit | Unit price<br>excl. GST | Tax code | Total amount<br>excl. GST | Total amount<br>incl. GST |
|------------------|------------------------------------------------|----------|------|-------------------------|----------|---------------------------|---------------------------|
| 9801B004         | B&P CHECK SHORT CIRCUIT / HARNESS REPAIR       |          |      |                         | #1       | 200.00                    | 214.00                    |
| 9801B005         | B&P DIAGNOSIS AND PROGRAMMING                  |          |      |                         | #1       | 360.00                    | 385.20                    |
| 9801B001         | R&R FRT SEAT BELT                              |          |      |                         | #1       | 560.00                    | 599.20                    |
| 5G4857705N RAA   | Three-Point Automatic Sea SEAT BELT LH         | 1        | pcs. | 1,054.64                | 28.00%   | 759.34                    | 812.49                    |
| 5G4857706N RAA   | Three-Point Automatic Sea SEAT BELT RH         | 1        | pcs. | 1,054.64                | 28.00%   | 759.34                    | 812.49                    |
| WHT003682        | Bolt With Polygon Socket                       | 2        | pcs. | 7.21                    | 28.00%   | 10.38                     | 11.11                     |
| N 98924301       | Socket Hd. Screw With Pol                      | 2        | pcs. | 7.34                    | 28.00%   | 10.57                     | 11.31                     |
| N 98926001       | Socket Hd. Screw With Pol                      | 2        | pcs. | 6.63                    | 28.00%   | 9.55                      | 10.22                     |
| 8V0857819 (fth)  | Seat Belt Height Adjuster                      | 2        | pcs. | 124.00                  | 28.00%   | 178.56                    | 191.06                    |
| N 10572403       | Bolt                                           | 2        | pcs. | 4.35                    | 28.00%   | 6.26                      | 6.70                      |
| 5G6827025AA      | Rear Trunk Lid                                 | 1        | pcs. | 2,550.09                | 28.00%   | 1,836.06                  | 1,964.58                  |
| D 169300M2       | 1k Window Adhesive                             | 2        | pcs. | 51.44                   | 28.00%   | 74.07                     | 79.25                     |
| D 00940104       | All Purpose Cleaner                            | 1        | pcs. | 102.88                  | 28.00%   | 74.07                     | 79.25                     |
| D 00920002       | Primer                                         | 1        | pcs. | 30.27                   | 28.00%   | 21.79                     | 23.32                     |
| D 181802M1       | Activator                                      | 1        | pcs. | 26.27                   | 28.00%   | 18.91                     | 20.23                     |
| D 00950025       | Applicator                                     | 2        | pcs. | 11.16                   | 28.00%   | 16.07                     | 17.19                     |
| 5G6827505B 9B9   | Hood Latch Satin Black BOOT LID LOCK           | 1        | pcs. | 266.89                  | 28.00%   | 192.16                    | 205.61                    |
| 5G6827705E       | Gasket                                         | 1        | pcs. | 299.42                  | 28.00%   | 215.58                    | 230.67                    |
| 5G0827469F FOD   | BOOT LID WETHERSTRIP                           | 1        | pcs. | 2,107.78                | 28.00%   | 1,517.60                  | 1,623.83                  |
| 510827861A       | Oper.Mechan.With Micro Sw Water Drain Hose     | 1        | pcs. | 9.54                    | 28.00%   | 6.87                      | 7.35                      |
| 5G6867605E 82V   | Trim Panel For Hatch Gate BOOT LID TRIM COVER  | 1        | pcs. | 188.91                  | 28.00%   | 136.02                    | 145.54                    |
| 5G0853687 2ZZ    | Inscription Bright Chrome NAME PLATE - GOLF    | 1        | pcs. | 89.77                   | 28.00%   | 64.63                     | 69.15                     |
| 5G0853675AT2ZZ   | Inscription Bright Chrome NAME PLATE - 230 TSI | 1        | pcs. | 81.11                   | 28.00%   | 58.40                     | 62.49                     |
| 5G0945087B (fth) | Additional Brake Light Wi 3RD BRAKELIGHT       | 1        | pcs. | 183.08                  | 28.00%   | 131.82                    | 141.05                    |
| 5G0945093AD      | Taillight LHS TAILLIGHT INNER                  | 1        | pcs. | 317.12                  | 28.00%   | 228.33                    | 244.31                    |
| 5G0945094AD      | Taillight With Rear Fog L RHS TAILLIGHT INNER  | 1        | pcs. | 317.12                  | 28.00%   | 228.33                    | 244.31                    |
| 5G6807417APGRU   | Cover For Bumper Primed                        | 1        | pcs. | 1,417.50                | 28.00%   | 1,020.60                  | 1,092.04                  |
| 5G0998492 GRU    | 1 Set Sensor Brackets Pri                      | 1        | pcs. | 25.72                   | 28.00%   | 18.52                     | 19.82                     |
| 5G0919491        | Sensor Bracket                                 | 2        | pcs. | 16.92                   | 28.00%   | 24.36                     | 26.07                     |
| 5G0919491A       | Sensor Bracket                                 | 1        | pcs. | 16.92                   | 28.00%   | 12.18                     | 13.03                     |
| 5G0919492A       | Sensor Bracket                                 | 1        | pcs. | 16.92                   | 28.00%   | 12.18                     | 13.03                     |
| 5Q0919275B GRU   | Sensor Primed                                  | 2        | pcs. | 190.18                  | 28.00%   | 273.86                    | 293.03                    |
| 5Q0919133 9B9    | Seal Ring Satin Black                          | 2        | pcs. | 1.46                    | 28.00%   | 2.10                      | 2.25                      |
| D 180KU2A1       | 2k-Plastic Adhesive                            | 1        | pcs. | 85.94                   | 28.00%   | 61.88                     | 66.21                     |

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



Quotation  
Non binding - Preview

Page 2/3

Company  
ALLIANZ  
INSURANCE SINGAPORE PTE. LTD.  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897

Customer Details:  
Ms.  
NG  
SAN SAN  
267 TAMPINES STREET 21  
#11-17  
Singapore 520267

Document no. 25-10-2022  
Document date 5211052769  
Customer no. 201903913C  
Customer GST-ID 30001  
Dealer 2022031069/ 1  
Job order number 25-10-2022  
Job order date SHU SHI TANG  
Service Advisor

| License plate | Model code | First registration | VIN              | Model                    | Mileage |
|---------------|------------|--------------------|------------------|--------------------------|---------|
| SJL1749K      | 5G13HZ     | 26-01-2017         | WVWZZZAUZH121987 | Golf 1.4 CLBM 92 TSI D7F | 105,315 |

| Position no.   | Description                                                  | Quantity | Unit | Unit price<br>excl. GST | Tax code  | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------------|--------------------------------------------------------------|----------|------|-------------------------|-----------|---------------------------|---------------------------|
| D 822150A1     | Bonding Agent For Plastic                                    | 1        | pcs. | 68.85                   | 28.00% #1 | 49.57                     | 53.04                     |
| 5G6807568D 9B9 | Rear Diffusor Satin Black                                    | 1        | pcs. | 361.39                  | 28.00% #1 | 260.20                    | 278.41                    |
| WHT005263      | Rivet                                                        | 4        | pcs. | 1.32                    | 28.00% #1 | 3.80                      | 4.07                      |
| 5G0807305D     | Bumper                                                       | 1        | pcs. | 750.84                  | 28.00% #1 | 540.60                    | 578.44                    |
| 5G6807863C     | REINFORCEMENT<br>Attachment Strip                            | 1        | pcs. | 73.18                   | 28.00% #1 | 52.69                     | 56.38                     |
| 5G6807393A     | BUMPER CTR BRACKET<br>Guide Piece                            | 1        | pcs. | 43.33                   | 28.00% #1 | 31.20                     | 33.38                     |
| 5G6807394A     | LHR BUMPER BRACKET (UPPER)<br>Guide Piece                    | 1        | pcs. | 43.33                   | 28.00% #1 | 31.20                     | 33.38                     |
| 5G6807393      | RHR BUMPER BRACKET (UPPER)<br>Guide Piece                    | 1        | pcs. | 43.33                   | 28.00% #1 | 31.20                     | 33.38                     |
| 5G6807394      | LHR BUMPER BRACKET (SIDE)<br>Guide Piece                     | 1        | pcs. | 43.33                   | 28.00% #1 | 31.20                     | 33.38                     |
| 1K8943021      | RHR BUMPER BRACKET (SIDE)<br>License Plate Light             | 2        | pcs. | 44.37                   | 28.00% #1 | 63.89                     | 68.36                     |
| 8K0973702      | Flat Contact Housing With<br>NUMBER PLATE LIGHT WIRE HOUSING | 2        | pcs. | 12.39                   | 28.00% #1 | 17.84                     | 19.09                     |
| 5G0945105      | Reflector                                                    | 1        | pcs. | 81.02                   | 28.00% #1 | 58.33                     | 62.41                     |
| 5G0945106      | LH<br>Reflector                                              | 1        | pcs. | 81.02                   | 28.00% #1 | 58.33                     | 62.41                     |
| 5G6813301D     | RH<br>Rear Apron                                             | 1        | pcs. | 827.48                  | 28.00% #1 | 595.79                    | 637.50                    |
| 5G6807126B     | REAR END PANEL INNER<br>Bracket For Bumper                   | 1        | pcs. | 14.74                   | 28.00% #1 | 10.61                     | 11.35                     |
| 5G6813309      | End Plate<br>END PANEL OUTER                                 | 1        | pcs. | 212.15                  | 28.00% #1 | 152.75                    | 163.44                    |
| D 007500A2     | Zinc Spray                                                   | 1        | pcs. | 72.86                   | 28.00% #1 | 52.46                     | 56.13                     |
| D 180003M2     | 2k-Body Adhesive                                             | 1        | pcs. | 469.52                  | 28.00% #1 | 338.05                    | 361.71                    |
| D 476KD1M2     | Sealant Can Be Sprayed                                       | 1        | pcs. | 66.78                   | 28.00% #1 | 48.08                     | 51.45                     |
| WHT005560      | Speed Nut                                                    | 5        | pcs. | 1.80                    | 28.00% #1 | 6.48                      | 6.93                      |
| N 91017602     | Weld Stud                                                    | 8        | pcs. | 1.14                    | 28.00% #1 | 6.57                      | 7.03                      |
| 5G6863459K 82V | Cover For Lock Carrier Ti<br>END PANEL TRIM COVER            | 1        | pcs. | 141.51                  | 28.00% #1 | 101.89                    | 109.02                    |
| 5G6858855F CA9 | Cargo Platform Black<br>SPARE WHEEL COVER                    | 1        | pcs. | 443.33                  | 28.00% #1 | 319.20                    | 341.54                    |
| 5G6858831 82V  | Mounting Titanium Black<br>SPARE WHEEL COVER BRACKET LH      | 1        | pcs. | 59.88                   | 28.00% #1 | 43.11                     | 46.13                     |
| 5G6858832 82V  | Mounting Titanium Black<br>SPARE WHEEL COVER BRACKET RH      | 1        | pcs. | 59.88                   | 28.00% #1 | 43.11                     | 46.13                     |
| 1K0803899D     | Bolt For Spare Wheel Moun                                    | 1        | pcs. | 24.34                   | 28.00% #1 | 17.52                     | 18.75                     |
| 5Q0825701E     | Heat Shield For Exhaust M<br>LABOUR                          | 1        | pcs. | 164.55                  | 28.00% #1 | 118.48                    | 126.77                    |
|                | SPRAY PAINT                                                  | 8        | pcs. | 560.00                  | 28.00% #1 | 4,480.00                  | 4,793.60                  |
|                | R&R REAR W/SCREEN                                            | 5        | pcs. | 530.00                  | 28.00% #1 | 4,240.00                  | 4,536.80                  |
|                | TRANSFER BOOT LID MECHANISM                                  | 1        | pcs. | 560.00                  | 28.00% #1 | 560.00                    | 599.20                    |
|                | R&R REAR LUGGAGE TRIM                                        | 1        | pcs. | 560.00                  | 28.00% #1 | 560.00                    | 599.20                    |

\* End part order + 4 days

# VOLKSWAGEN CENTRE SINGAPORE

247 Alexandra Road  
Singapore 159934  
Biz. Reg. No.: 199101494Z  
GST No.: M200985052



## Quotation Non binding - Preview

Page 3/3  
Document no.  
Document date 25-10-2022  
Customer no. 5211052769  
Customer GST-ID 201903913C  
Dealer 30001  
Job order number 2022031069/ 1  
Job order date 25-10-2022  
Service Advisor SHU SHI TANG

Company  
ALLIANZ  
INSURANCE SINGAPORE PTE. LTD.  
79 ROBINSON ROAD  
#09-01  
SINGAPORE 068897

Customer Details:  
Ms.  
NG  
SAN SAN  
267 TAMPINES STREET 21  
#11-17  
Singapore 520267

| License plate | Model code | First registration | VIN               | Model                    | Mileage |
|---------------|------------|--------------------|-------------------|--------------------------|---------|
| SJL1749K      | 5G13HZ     | 26-01-2017         | VWVZZZAUZHW121987 | Golf 1.4 CLBM 92 TSI D7F | 105,315 |

  

| Position no. | Description                                                     | Quantity | Unit | Unit price<br>excl. GST | Tax code | Total amount<br>excl. GST | Total amount<br>incl. GST |
|--------------|-----------------------------------------------------------------|----------|------|-------------------------|----------|---------------------------|---------------------------|
|              | R&R REAR EXHAUST PIPE                                           | 1        | pcs. | 560.00                  | #1       | 560.00                    | 599.20                    |
|              | REAR WATER LEAK TEST                                            | 1        | pcs. | 100.00                  | #1       | 100.00                    | 107.00                    |
|              | RAER NUMBER PLATE                                               | 1        | pcs. | 80.00                   | #1       | 80.00                     | 85.60                     |
|              | ALLIANZ OD/RECOVERY<br>DOA: 22/10/2022<br>EXCESS:<br>SURVEY BY: |          |      |                         |          |                           |                           |

Quotation valid till 01-11-2022

| Tax Code | Labour   | Material  | Material Discount | GST % | GST      | Total Discount | Total amount<br>excl. GST | Total amount<br>incl. GST |
|----------|----------|-----------|-------------------|-------|----------|----------------|---------------------------|---------------------------|
| #1       | 1,120.00 | 22,204.54 | 4,302.93          | 7%    | 1,632.72 | 4,302.93       | 23,324.54                 | 24,957.26                 |
|          |          | 22,204.54 | 4,302.93          |       | 1,632.72 | 4,302.93       | 23,324.54                 | 24,957.26                 |

STER CLKK)  
26/10/22, 1.00pm  
OD-LI AL  
Excess ?

Customer

Service Advisor

VISIT OUR WEBSITE: aftersales.vw.com.sg (for online service appointments) and volkswagen.com.sg and www.skoda.com.sg (for additional services, products and promotions).

8 days (not incld end of 4 day)

Total - 12 days

All invoices are denominated in SGD, unless otherwise stated.