



FALCON - AIR

LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES012492

Date : 26/10/2022

Vehicle Num. : GBC 9608Z

Make/Model : RENAULT KANGOO II EXPRESS-2013/2

Chassis/Eng# : VF1FW1UBA50248383

Accident Date : 21/10/2022

Claim No. :

Reference : O/D

Policy No. : Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
PARTS PURCHASED :				
1.	1 PC	REAR BUMPER		380.00
2.	1 PC	TAILLAMP LOWER GARNISH		250.00
3.	1 PC	RH REAR WHEEL HUB CAP		120.00
4.	1 PC	RH SLIDING DOOR		750.00
5.	1 PC	RH SLIDING DOOR PROTECTOR PAD		115.00
6.	1 PC	RH SLIDING DOOR OUTER HANDLE		135.00
7.	1 PC	RH FRONT DOOR		1,800.00
8.	1 PC	RH FRONT DOOR PILLAR A		1,300.00
9.	1 PC	RH FRONT DOOR HINGE (TOP)		200.00
10.	1 PC	RH FRONT DOOR HINGE (BOTTOM)		200.00
11.	1 PC	RH FRONT DOOR PROTECTOR PAD		130.00
12.	1 PC	RH FRONT DOOR OUTER HANDLE		140.00
13.	1 PC	RH FRONT DOOR INNER LOCK		430.00
14.	1 PC	RH FRONT DOOR GLASS		380.00
15.	1PC	RH FRONT DOOR GLASS OUTER MOULDING		280.00
16.	1 PC	RH FRONT DOOR GLASS CHANNEL RUBBER		280.00
17.	1 PC	RH SIDE MIRROR BASE		380.00
18.	1 PC	RH SIDE MIRROR GLASS		130.00
19.	1 PC	RH SIDE MIRROR BACK COVER		170.00
20.	1 PC	RH FRONT FENDER		345.00
21.	1 PC	RH FRONT FENDER LAMP		160.00
22.	1 PC	RH FRONT FENDER UNDERSHIELD		180.00

CONTINUE / ...



FALCON - AIR AUTO SERVICES PTE LTD

Co. Reg. No.: 199501140D
GST Reg. No.: 199501140D**FALCON - AIR**LONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES012492

Date : 26/10/2022

Vehicle Num. : GBC 9608Z

Make/Model : RENAULT KANGOO II EXPRESS-2013/2

Chassis/Eng# : VF1FW1UBA50248383

Accident Date : 21/10/2022

Claim No. :

Reference : O/D

Policy No. : Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
23.	1 PC	RH FRONT STEEL RIM		240.00
24.	1 PC	RH FRONT WHEEL HUB CAP		120.00
25.	1 PC	RH FRONT SHOCK ABSORBER		155.00
26.	1 PC	RH FRONT SHOCK ABSORBER TOP MOUNTING		70.00
27.	1 PC	RH FRONT SHOCK ABSORBER TOP BEARING		60.00
28.	1 PC	RH FRONT SHOCK ABSORBER COVER		65.00
29.	1 PC	RH FRONT KNUCKLE ARM		750.00
30.	1 PC	RH FRONT WHEEL BEARING HUB		130.00
31.	1 PC	RH FRONT LOWER ARM		200.00
32.	1 PC	RH FRONT STABILIZER BAR		380.00
33.	1 PC	RH FRONT STABILIZER BAR LINK		155.00
34.	1 PC	RH HEADLAMP		550.00
35.	1 PC	RADIATOR SUPPORT PANEL		550.00
36.	1 PC	RH REAR FENDER		2,000.00
Total Parts Purchased S\$:				13,680.00
15.00% Of The Above Parts S\$:				2,052.00
Based On Cost Plus S\$:				15,732.00
SPECIAL NETT ITEMS :				
1.	1 PC	RH FRONT DOOR COMPANY NAME STICKER		50.00
2.	1 PC	RH FRONT TYRE		140.00
3.	1 PC	SEALANT		45.00

CONTINUE / ...

**FALCON - AIR AUTO SERVICES PTE LTD**Co. Reg. No.: 199501140D
GST Reg. No.: 199501140DLONPAC INSURANCE BHD
300 BEACH ROAD #17-04/07
THE CONCOURSE - 199555
ATTENTION: GERALD POH

Attention : Motor Claim Department

Contact : 62507388 Fax No. : 62962706

Estimate : ES012492Date : 26/10/2022
Vehicle Num. : GBC 9608Z
Make/Model : RENAULT KANGOO II EXPRESS-2013/2
Chassis/Eng# : VF1FW1UBA50248383
Accident Date : 21/10/2022
Claim No. :
Reference : O/D
Policy No. : Z22VC05010613

S/N	Quantity	Particular	Unit Price	Amount S\$
4.	10 PCS	RH FRONT FENDER CLIP	8.00	80.00
5.	1 SET	ASSORTED CLIPS		80.00
Special Nett Total S\$:				395.00
LABOUR :				
TO REMOVE/REFIT RH SLIDING DOOR GLASS				100.00
TO CHECK WIRING AND RE-FOCUS HEADLAMP				50.00
COMPUTERISE WHEEL ALIGNMENT				120.00
TO TRANSFER FRONT DOOR MECHANISM				100.00
TO TRANSFER REAR DOOR MECHANISM				100.00
TO TRANSFER TYRE TO NEW RIM AND BALANCING				50.00
TO VACUUM, RE-OIL AND RE-GAS AIR CON				120.00
TO REMOVE/REFIX TRIM BOARD, CARPETS, GARNISHES TO FACILITATE REPAIRS				280.00
TO REMOVE/REPLACE UNDERCARRIAGE PARTS				400.00
TO CUT OUT/RE-WELD RH REAR FENDER, RH FRONT DOOR PILLAR				
REPAIR RH WINDSCREEN PILLAR, RH FRONT DOOR PILLAR, CENTRE PANEL INCLUDING REPLACEMENT OF PARTS				1,800.00
TO SPRAY PAINT RH FRONT FENDER, RH FRONT DOOR PILLAR, RH FRONT DOOR, RH SLIDING DOOR, RH REAR FENDER, RH ROCKER PANEL, RH CENTRE PANEL, RH WINDSCREEN PILLAR				2,000.00
Labour Total S\$:				5,120.00
E. & O.E.			Total S\$:	21,247.00

for FALCON AIR AUTO SERVICES PTE LTD

The quotation was prepared from visual inspection. Further materials and labour charges may be required when repair commences. We will advise you accordingly.