



Your Ref : CMTD2203825/THE

Date: 03rd November 2022

Our Ref : CS/SMO22010591/Uqcm4

M/s Sompo Insurance Singapore PL

50 Raffles Place #03-03

Singapore Land Tower

Singapore 048623

(The Motor Claims Department)

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SJD 3585U
INSURED VEHICLE: SJU 5572D
ACCIDENT ON 20/10/2022**

Instruction was received to inspect the vehicle Reg. No. SJD 3585U. The inspection was conducted on 26/10/2022 at the premises of M/s Zoom Autowerks Pte Ltd, Blk 15 Kaki Bukit Road 4, Bartley Biz Centre, #01-53, Singapore 417808.

The following vehicle information was recorded:

Registration Number	: SJD 3585U
Make/Model	: Mitsubishi Lancer 1.5 Mivec GLS 4A/T
Year of Registration	: 2008
Body Colour	: Blue
Chassis Number	: JMYSRCY2A8U004135
Engine Capacity	: 1499 cc

The vehicle sustained damages at the front portion. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$ 4,500.00 (est)
Less: LTA Reimbursement Value (RV)	(S\$ 2,873.00)
Nett Liability	<u>S\$ 1,627.00</u> =====

Vehicle Inspected By:



CHUA KANG SENG
Licensed Appraiser



K.K.LAU
MSc(Eng M), B Eng(Hons), PEng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCI Ard, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.