



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details			Account No.		Customer Details				
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925				
			Document No. 0						
			Document Date 02/11/2022						
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0432J	0	18171	75/DS/SLU0432J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU703576293		2ZR8255805	60	Ng Mei Yen	26/10/2022 8.00		02/11/2022 18.00		
L	Cd	Job/Parts Description	Qty	Unit Price	Disc %	Amount			
1	Z	BP-GRAB-DS SUNDRIES - FLASH ARRIVE: DD/MM/YY 0000HR TP VEH NO.:GBK5233E ACC DATE:23/10/22 TOW IN:23/10/22 DATE-IN: DATE SURVEY:16/10/22 NO OF REPAIR DAYS:7 DAY BY:STEVE LKK				50.00			
2	B	BP-LAB2 CHECK WIRING AND CONDUCT LEAK TEST	BP09			180.00			
3	B	BP-ECU2 TO RESET ECU AND REPROGRAMME	BP61			180.00			
4	B	BP-LAB2 DRILL HOLE AND INSTALL REVERSE SENSOR	BP09			180.00			
5	Z	BP-SLANT SUPPLY SEALANT (NETT)				100.00			
6	L	BP-LPO SUPPLY FRONT REGN PLATE (PO#)	0263			80.00			
7	B	BP-LAB2 REPL ACC AFF AREA (REAR PORTION) STRAIGHTEN & PANEL BEAT ACC AFF AREA	BP09			720.00			
8	B	BP-RES2 RESPRAY ACC AFF AREA (REAR PORTION)	*			1180.00			
9	B	BP-LAB2 REPL ACC AFF AREA (FRONT PORTION) STRAIGHTEN & PANEL BEAT ACC AFF AREA	BP09			1080.00			
10	B	BP-RES2 RESPRAY ACC AFF AREA (FRONT PORTION)	*			1180.00			
11	1	U52159-47913 COVER, RR BUMPER	1.00	478.90		478.90			
12	2	U52023-47030 REINFORCEMENT	1.00	360.10		360.10			
13	3	U52453-47010 GUARD, RR BUMPER,	1.00	623.50		623.50			
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total		
<div style="border-bottom: 1px solid black; width: 100%; height: 20px;"></div>			<div style="border-bottom: 1px solid black; width: 100%; height: 20px;"></div>		<div style="border-bottom: 1px solid black; width: 100%; height: 20px;"></div>		Less		
								Please acknowledge receipt of vehicle	Parts Labour Sublet Lubrication/Fluid Others

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE

Account Details				Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept				S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
				Document No. 0					
				Document Date 02/11/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks		
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0432J	0	18171	75/DS/SLU0432J		
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On		
JTDKB3FU703576293		2ZR8255805	60	Ng Mei Yen	26/10/2022	8.00	02/11/2022	18.00	
L	Cd	Job/Parts Description				Qty	Unit Price	Disc %	Amount
14	4	U52565-47900 FILLER, RR BUMPER				1.00	133.60		133.60
15	5	U52169-47020 COVER, RR BUMPER,				1.00	16.70		16.70
16	6	S52161-0K040 PIECE, RR BUMPER				10.00	4.50		45.00
17	7	U76801-47110 A1 GARNISH SUB-ASSY,				1.00	1004.70		1004.70
18	8	U75441-47130 PLATE, LUGGAGE COMPT				1.00	59.10		59.10
19	9	U75403-48010 EMBLEM SUB-ASSY,				1.00	77.40		77.40
20	0	U75442-47130 PLATE, LUGGAGE COMPT				1.00	59.10		59.10
21	1	U52119-47962 COVER, FR BUMPER				1.00	560.30		560.30
22	2	U52114-47190 BRACKET, FR BUMPER				1.00	111.80		111.80
23	3	U53112-47240 GRILLE, RADIATOR,				1.00	183.90		183.90
24	4	S52161-0K040 PIECE, RR BUMPER				10.00	4.50		45.00
25	5	U52611-47140 ABSORBER, FR BUMPER				1.00	85.90		85.90
26	6	U53101-47081 GRILLE SUB-ASSY,				1.00	374.40		374.40
27	7	SPC507-47001 00 BACK SENSOR(PRIMER FOR TAXI)PR				1.00	163.60		163.60
28	8	U52021-47110 REINFORCEMENT				1.00	773.90		773.90
For & on behalf of		Customer's Signature		Charge Summary			Total 10,086.90		
Borneo Motors (Singapore) Pte Ltd		Please acknowledge receipt of vehicle		Parts 5,156.90			GST 7.00% 706.08		
Labour 4,850.00									
Sublet 80.00				Less 0.00					
Lubrication/Fluid 0.00									
Others 0.00				Amount Due 10,792.98					

Customer Copy



Borneo Motors

Inchcape

Co. Reg No. : 196700086Z
GST Reg No. : MR-8500000-9
No. 2 PANDAN CRESCENT
SINGAPORE 128462, Tel no.: 6631 1188



TOYOTA

ESTIMATE (supplementary)

Account Details			Account No.		Customer Details			
MS First Capital Insurance Ltd 36 Robinson Road #16-01 City House Singapore 068877 Attn: Motor Claims Dept			S1000005 / ICFIC1		M/S Grab Rentals Pte Ltd 3 Media Close #01-03/06 Singapore 138498 Work: 65703925			
			Document No. 0					
			Document Date 02/11/2022					
Year	Model	Variant	Reg. Date	Reg. No.	Kilometers	Wip No.	Order No. / Remarks	
2017	ZVW50R	AHXEBW Q2	21/11/2017	SLU0432J	0	18171	75/DS/SLU0432J	
Chassis No.		Engine No.	Terms	SA / Counter	Vehicle In		Collected On	
JTDKB3FU703576293		2ZR8255805	60	Ng Mei Yen	26/10/2022 8.00		02/11/2022 18.00	
L	Cd	Job/Parts Description			Qty	Unit Price	Disc %	Amount
1	1	U52021-47110 REINFORCEMENT BT			1.00	773.90		773.90 ✓
For & on behalf of Borneo Motors (Singapore) Pte Ltd			Customer's Signature		Charge Summary		Total 773.90	
<div style="border-bottom: 1px solid black; height: 20px; width: 100%;"></div>			<div style="border-bottom: 1px solid black; height: 20px; width: 100%;"></div>		Parts 773.90		GST 7.00% 54.17	
					Labour 0.00			
					Sublet 0.00		Less 0.00	
					Lubrication/Fluid 0.00			
					Others 0.00		Amount Due 828.07	

Customer Copy