

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|--|----------------|-------|--------------------|--|
| | STRIDES AUTOMO | OTIVE SERVICES PTE LTD | | Ref: | CS/SMR22010594/Tvc | |
| | 60 WOODLANDS I E4SINGAPORE 75 | NDUSTRIAL PARK 7705 | | Date: | 26/10/2022 | |
| | | | | Code: | SMR | |
| 1. | Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | SMB 1533H | Veh. Inspected | | SJW 6668U | |
| | Policy No. | | Coverage (\$) | | 0.00 | |
| | Claim No. | | Excess (\$) | | 0.00 | |
| | Assign From | HUA YEN | Assign Date | | 26/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer | Steering | | | | |
| | Brakes | Modification | | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. | | Information | | | | |
| | Accident Date | 20/10/2022 | Inspection Dat | е | 26/10/2022 | |
| | Survey held at | LM AUTO SOLUTION PTE LTD | | | | |
| | | BLK 10 SIN MING INDUSTRIAL ESTATE SECTOR C | | | | |
| | | #01-12, SINGAPORE 575645 | | | | |
| 5a. Rei | | | marks | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |