

Section A - Accident Details

Registration Number	SHB1773R
Case Reference Number	TAX/10/22/2071
Registration Date	30/11/2021
Company Type	Strides Taxi Pte Ltd
Make	MORRISGARAGES
Model	MG5
Name of Driver	RAKESH DEV SINGH S/O SUKHDEV SINGH
Type of Accident	Side Swipe
Accident Date and Time	23/10/2022 2:41 PM
Accident Reported Date and Time	25/10/2022 9:15 AM
Is Surveyor Required?	Yes
Survey by	
Vehicle is Towed Back?	No
Towed Back Date and Time	
Replacement Vehicle issued?	No
Job Card Number	24116666
Special Instruction to ARC, if any	DROVE IN / RIGHT PORTION / AXA
Prepared Date and Time	25/10/2022 1:26 PM
Chassis Number	
Mileage	
Work Shop	
Repair Completion Date and Time	

Section B - Summary of Repair Estimates

Summary of Repair Estimates		
	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Cost	\$2,400.00	\$400.00
Total Spray Cost	\$2,172.00	\$1,180.00
Total Spare Part Cost	\$7,558.13	\$1,618.05
Total Other Cost	\$1,360.00	\$430.00
TOTAL COST	\$13,490.13	\$3,628.05 (P/P)
Lump Sum Total	\$0.00	\$0.00
Number of Repair Days	8.0	4.0
Prepared / Adjusted By	Boon Chew Tay	STEVE CHEN (LKK) / AXA
ARC / Surveyor Sign Off Date	26/10/2022 8:39 AM	25/10/2022 5:16 PM
Signature		
Remarks	PART BY PART / BEFORE PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL SURVEYOR Steve Chen (LKK) / HP : 8322 8813 & Email: stevechen@lkkauto.com / steveppy@gmail.com	

Section C - Quotation and Accident Invoice Details

Quotation Number	QN-2211-0318	Invoice Number	
Quotation Date	22.11.2022	Invoice Date	
Invoice Amount		Prepared Date	

Section D - Details of Repair Estimates

Part 1 - Labour Works		
Job Scope	Quotation from AR	Adjusted by Surveyor, if applicable
TO REPAIR RH PORTION	\$2,400.00	\$400.00
Total Labour	\$2,400.00	\$400.00

Part 2 - Spray Painting & Panel Beating Related Works		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO RESPRAY RIM	\$230.00	\$150.00
TO RESPRAY FRONT DOOR RH	\$428.00	\$220.00
TO RESPRAY ROCKER PANEL MOULDING	\$230.00	\$150.00
TO RESPRAY RH REAR DOOR	\$428.00	\$220.00
TO RESPRAY REAR FENDER RH	\$428.00	\$220.00
TO RESPRAY REAR BUMPER	\$428.00	\$220.00
Total Spray Painting & Panel Beating	\$2,172.00	\$1,180.00

Part 3 - Other Costs - Accident and Accident Repair Related Expense		
Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO DO WHEEL ALIGNMENT / TYRE BALANCING	\$120.00	\$60.00
TO WASH AND VACUUM	\$60.00	\$0.00
TO CHECK WIRING AND SYSTEM FUNCTION	\$120.00	\$0.00
TO APPLY RUST-PROOFING ON AFFECTED AREA	\$100.00	\$20.00
TO TRANSFER DOOR MECHANISM	\$120.00	\$30.00
TO TEST AND REFIX REVERSE SENSOR SYSTEM	\$120.00	\$0.00
TO REMOVE & REFIT REAR QUARTER GLASS RH	\$120.00	\$0.00
TO REPLACE SUNDRY PARTS	\$100.00	\$20.00
TO CHECK & RESET SYSTEM FUNCTION	\$350.00	\$150.00
ISOLATED OF (EV) (NET)	\$150.00	\$150.00
Total Other Costs	\$1,360.00	\$430.00

Part 4 - Spare Parts / Material Usage									
Part Number	Portion	Stock Number	Part Name	Quantity	List Price (\$)	Discount (%)	Final Price (\$)	Estimator Approved	Surveyor Approved
		10169204-SEPP	DOOR ASM-FRT SI - RH	1.00	\$2,338.44	100.00	\$0.00	Replace	Repair
			STICKER STRIDES TAXI (DOOR)	1.00	\$60.00	0.00	\$60.00	Replace	Replace
		10380138-SEPP	DOOR ASM-RR SI -RH	1.00	\$2,185.04	30.00	\$1,529.53	Replace	Replace
		10364952-SEPP	HINGE ASM-RR S/D UPR-RH	0.00	\$46.90	0.00	\$0.00	Replace	Not Given
		10383922	CHECK ASM-RR S/D -RH	0.00	\$21.00	0.00	\$0.00	Replace	Not Given

 R
 ✓
 ✓
 X
 X

STRIDES Accident Vehicle Repair Estimates

STRIDES Automotive Services Pte Ltd
60 Woodlands Industrial Park E4, Singapore 757705
FAX Number : 63685592
Estimator Telephone Number : 68662623
Accident Reporting Number : 68662672

Date Generated : 04/12/2022

User ID : PohSuan

		10364954-SEPP	HINGE ASM-RR S/D LWR-RH	0.00	\$47.22	0.00	\$0.00	Replace	Not Given	X
		10760960	REGULATOR ASM-RR S/D WDO-RH	0.00	\$265.30	0.00	\$0.00	Replace	Check	X
		10297708	LATCH ASM-RR S/D -RH	0.00	\$139.98	0.00	\$0.00	Replace	Not Given	X
		10720690-SEPP	PANEL-BODY SI OTR - RH	1.00	\$1,434.89	100.00	\$0.00	Replace	Repair	R
			STICKER ELECTRIC (LOGO	1.00	\$21.60	0.00	\$21.60	Replace	Replace	√
		10626941	LINER ASM-RR W/H PNL -RH	0.00	\$85.48	0.00	\$0.00	Replace	Not Given	X
		10369261-SPRP	FASCIA-RR BPR	1.00	\$758.48	100.00	\$0.00	Replace	Repair	R
		10751490	FASCIA-RR BPR LWR	0.00	\$230.68	0.00	\$0.00	Replace	Not Given	X
		10326371	BRACKET-RR BPR FASCIA SI MTG - RH	0.00	\$46.08	0.00	\$0.00	Replace	Check	X
		10317983	WHEEL	1.00	\$618.07	100.00	\$0.00	Replace	Repair	R
		10509505	BEARING ASM-RR WHL	0.00	\$335.40	0.00	\$0.00	Replace	Not Given	X
		10751826	BEAM ASM-RR SUSP EQLZR	0.00	\$1,649.54	0.00	\$0.00	Replace	Not Given	X
		10393841	FILM-RR S/D FRM - RH	1.00	\$9.88	30.00	\$6.92	Replace	Replace	√
		10374913	MOLDING ASM-RR S/D WDO UPR RVL - RH	0.00	\$54.50	0.00	\$0.00	Replace	Not Given	X
		10393843	FILM-RR S/D FRM - RH	0.00	\$9.88	0.00	\$0.00	Replace	Not Given	X
		10321425	WEATHERSTRIP ASM-RR S/D (BODY SI) - RH	0.00	\$74.46	0.00	\$0.00	Replace	Not Given	X
		10321421	WEATHERSTRIP ASM-RR S/D (DR SI) - RH	0.00	\$71.76	0.00	\$0.00	Replace	Not Given	X
		10321441	WEATHERSTRIP ASM-RR S/D WDO INR - RH	0.00	\$27.98	0.00	\$0.00	Replace	Not Given	X
		10321433	WEATHERSTRIP ASM-RR S/D WDO OTR - RH	0.00	\$69.26	0.00	\$0.00	Replace	Not Given	X
		10589667	BAR-RR S/D WDO DIV - RH	0.00	\$44.72	0.00	\$0.00	Replace	Check	X
Total					\$10,646.54		\$1,618.05			

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Stock Number	Part Name	Quantity	List Price \$	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check
Total									

1,618.05
 + 400.00
 + 1610.00
 3,628.05