

PREMIUM AUTOMOBILES

55 Ubi Road 1, Singapore 408699
Tel : 6366 2323 Fax : 6841 1183

Email: Nora.khai@premiumauto.com.sg / claims@premiumauto.com.sg



Supplementary Estimate-1

GST Reg No. 19-9902271-W

AIG Asia Pacific Insurance Pte Ltd
78 Shenton Way
#07-16 AIG Building
Singapore 079120
Attn: Mr. Adrian Ling - Motor Claims Dept
Tel: 6841 0055 / Fax: 6256 4315

Estimate No.
Date
Service Advisor
Pages
Regn No
Model No

PA/OD/0916/2022/EQ
12-Dec-22
CHANG
1 of 1
SJU 9895 X
AUDI Q3 SPORTBACK 1.4 TFSI

Quantity	Description	Unit Price	Amount
Labours			
1	TO DISLodge AND REINSTALL REAR WIRE HARNESS FOR LIGHTS, BATTERY MANAGER, FUSE AND RELAY TRAYS, ELECTRICAL AND AUDIO EQUIPMENT. INSPECT FOR DAMAGE AND RENEW WHERE NECESSARY. S/N	\$ 1,600.00	✓
2	TO CUT OUT AND WELD REAR END OUTER PANEL. TO REPAIR REAR END INNER PANEL AND REAR FENDER CONNECTING PLATE.	\$ 2,400.00 1500.	
Parts			
1	REAR END PANEL - OUTER <i>Dented</i>	\$ 445.00	✓
2	REAR LID BUNG <i>xtc new</i>	\$ 133.00	✓
3	ACRYLIC SEALER <i>3 per</i>	\$ 180.00	✓
4	CAVITY WAX	\$ 140.00	✓
5	STONE CHIP	\$ 180.00	✓
6	METAL FILLER POWDER <i>1 per</i>	\$ 280.00	✓
GRAND TOTAL		\$ 5,358.00	

For Premium Automobiles Pte Ltd



Authorised Signature

Adrian Ling
Slip - Penang

PREMIUM AUTOMOBILES



55 UBI ROAD 1, SINGAPORE 408699
 TEL: 6366 2323 FAX: 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE SJU 9895 X

S/N	NATURE OF JOBS	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATIONS
6	TO DISMANTLE AND RENEW REAR BUMPER AND REAR LID. TO REPAIR RHS TAILLAMP PANEL AND REAR END PANELLING. RE-ORGANIZE CRASH MANAGEMENT COMPONENTS. REINSTALL ALL PARTS REMOVED.	\$ 3,200.00 1500.	1000 550x2 = 1100.
7	TO RESPRAY REAR BUMPER, REAR LID, RHS TAILLAMP PANEL, REAR END PANELLING AND BOTH REAR WHEEL ARCH TRIMS.	\$ 4,500.00	wheel dic x2 = 400 +550 H.S.
8	TO CARRY OUT DIAGNOSTIC CHECK.	S/N \$ 192.00	
TOTAL LABOUR CHARGES		\$ 9,812.00	

+ 3 days repair day.

Adrian Li
 Resurveyed.
 H.S.

To add 3 days for
 the replacement
 of rear end panel and
 reshaping of taillamp
 panel and spare
 tyre panel.
 H.S.

Car-in

5/12/22 wip: 46935

★ PREMIUM AUTOMOBILES

Benz:



55 UBI ROAD 1, SINGAPORE 408699

TEL: 6366 2323 FAX: 6841 1183

EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SIU 9895 X

1729- Achran
- 4 days

DAMAGED PARTS & PRICES

S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
1	REAR BUMPER <i>Del'd</i>	1	\$ 1,738.00 ✓	
2	REAR BUMPER SPOILER <i>Del'd</i>	1	\$ 510.00 ✓	
3	REAR BUMPER GRILLE - RH <i>Del'd</i>	1	\$ 170.00 ✓	
4	REAR PARKING AID SENSOR SUPPORT - RH ?	1	\$ 28.00 ?	
5	REAR BUMPER ADAPTER - RH ?	1	\$ 95.00 ?	
6	REAR BUMPER BRACKET ?	1	\$ 53.00 ?	
7	REAR BUMPER REFLECTOR - RH <i>Amhd</i>	1	\$ 46.00 ✓	
8	REAR OUTER TAIL LIGHT - RH <i>Amhd</i>	1	\$ 1,030.00 ✓	
9	REAR OUTER TAIL LIGHT TRIM - RH <i>* Amhd</i>	1	\$ 34.00 ✓	
10	REAR INNER TAIL LIGHT - RH <i>Amhd</i>	1	\$ 1,030.00 ✓	
11	REAR INNER TAIL LIGHT TRIM - RH <i>Missing</i>	1	\$ 34.00 ✓	
12	REAR BUMPER REINFORCEMENT BEAM <i>new</i>	1	\$ 693.00 +	
13	REAR BUMPER SHOCK ABSORBER ?	1	\$ 95.00 ?	
14	REAR BUMPER HOLDING STRAP - LH / RH ?	2	\$ 64.00 ?	
15	REAR BUMPER GUIDE SECTION - RH ?	1	\$ 71.00 ?	
16	REAR PARKING AID SENSOR - INNER / OUTER <i>new</i>	2	\$ 531.00 +	
17	REAR PARKING AID SEAL RING <i>new</i>	4	\$ 10.00 ✓	
18	REAR BUMPER WIRING SET <i>new cut</i>	1	\$ 449.00 ✓	
19	REAR UNDERBODY TRIM - RH <i>new</i>	1	\$ 58.00 +	
20	REAR LID <i>Del'd</i>	1	\$ 3,728.00 ✓	

SUB TOTAL SPARE PARTS

: \$ 10,467.00

ALL CHARGES ARE NOT INCLUSIVE OF GST

LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
SPARE PARTS ARE SPECIAL NETT.

55 UBI ROAD 1, SINGAPORE 408699
 TEL : 6366 2323 FAX : 6841 1183
 EMAIL: NORA.KHAI@PREMIUMAUTO.COM.SG / CLAIMS@PREMIUMAUTO.COM.SG

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO. SIU 9895 X

			DAMAGED PARTS & PRICES	
S/N	PARTS DESCRIPTION	QTY	S/NETT	REMARKS
21	PACKING ADHESIVE <i>mer</i>	1 \$	21.00 ✓	
22	REAR LID FLAP GASKET <i>mer</i>	1 \$	229.00 +	
(23)	REAR LID STOP BUFFER - LH / RH <i>mer Dmd.</i>	2 \$	61.00 ✓	<i>865</i>
24	AUDI EMBLEM <i>mer</i>	1 \$	144.00 ✓	
25	"Q3" INSCRIPTION <i>mer</i>	1 \$	104.00 ✓	
26	REAR WINDSCREEN <i>mer</i>	1 \$	1,064.00 ✓	
27	WINDSCREEN PRIMER <i>mer</i>	1 \$	22.00 ✓	
28	REAR SPOILER - LH / RH <i>mer</i>	2 \$	470.00 ✓	
29	REAR VENT TRIM <i>mer</i>	1 \$	79.00 +	
30	REAR WHEEL COVER - LH / RH <i>mer</i>	2 \$	1,132.00 ✓	
31	REAR WINDSCREEN SEALANT <i>mer</i>	S/N \$	200.00 ✓	
32	SUNDRIES ?	\$	500.00 ?	
TOTAL SPARE PARTS		:	\$ 14,493.00	
TOTAL LABOUR CHARGES		:	\$ 9,812.00	
GRAND TOTAL		:	\$ 24,305.00	

ALL CHARGES ARE NOT INCLUSIVE OF GST
 LEGEND: REMARKS (OK) = APPROVED, REMARKS (X) = NOT APPROVED
 SPARE PARTS ARE SPECIAL NETT.