

SPEEDWERKZ PRIVATE LIMITED

1 Kaki Bukit Avenue 6, #01-73, Autobay, Singapore 417883

Tel: 96195936 / info@speedwerkz.biz

Not Authorized
 27/10/22
 1/3 \$ 3500 /
 3 days.

VEHICLE NUMBER: SMU3821M
 MAKE & MODEL: TOYOTA WISH
 DOA: 25.10.2022
 CLAIM TYPE: TP CLAIM

ESTIMATION QUOTE

PARTS	QTY	PRICE (\$)	REMARKS
FRONT BUMPER	1	\$855.90	De/Toa ✓
FRONT BUMPER SIDE RETAINER LH	1	\$65.90	one ✓
FRONT BUMPER LOWER LIP	1	\$1,500.00	one ✓
FRONT BUMPER INNER SPONGE	1	\$95.10	11x
FRONT BUMPER REINFORCEMENT	1	\$195.80	11x
FRONT BUMPER HEAD LAMP LH	1	\$781.90	11x
FRONT BUMPER HEADLAMP PANEL LH	1	\$101.20	11x
FRONT FENDER LH	1	\$751.20	11x
FRONT FENDER INNER SHIELD LH	1	\$165.20	11x
FRONT BUMPER FOG LAMP LH	1	\$469.90	11x
FRONT BUMPER FOG LAMP COVER LH	1	\$252.10	11x
FRONT ABSORBER LH	1	\$325.80	11x
FRONT HUB BEARING LH	1	\$192.60	11x
FRONT KNUCKLE ARM LH	1	\$501.20	11x
FRONT LOWER ARM LH	1	\$431.40	11x
FRONT STAB LINK LH	1	\$101.40	11x
FRONT BEARING HUB LH	1	\$264.00	11x
ENGINE CROSS MEMBER	1	\$852.30	11x
STEERING RACK AND PINION	1	\$1,862.40	11x
STEERING TIE ROD END	1	\$82.70	11x
FRONT DOOR LH	1	\$1,230.50	11x

Less 25 % \$11,078.50
 Sub Total \$2,769.63
 \$8,308.88

SPECIAL NETT ITEMS	QTY	PRICE (\$)	REMARKS
FRONT SPORT RIM LH	1	\$1,200.00	wheel 500 s/n
FRONT TYRE LH	1	\$500.00	11x

Sub Total \$1,700.00

LABOUR CHARGE	QTY	PRICE (\$)	REMARKS
TO CHECK WIRING		\$200.00	20
TUFF KOTE		\$200.00	30
TO REMOVE AND REPLACE UNDERCARRIAGE		\$550.00	120
TO REMOVE AND REPLACE SPARE PARTS AND PANEL BEATING		\$1,200.00	380
TO SPRAY PAINTING AND ETC		\$1,100.00	600
CHECK WHEEL ALIGNMENT		\$120.00	80

Sub Total \$3,370.00

Grand Total \$13,378.88

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

2-3532.60
 253
 2649.45
 500
 1230
 4379.45
 3503.