

ASS. REC. BY:

REF:

LPC / 22010622/kp

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

810K

IDAC Accident Report:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

05

days

Res.: Yes or No

Lum Sum:

20

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

04/23

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

STL 41716

Yr Regn:

11, 08

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Honda Freed

c.c

1496

Colour

M. Brown

A/C:

Insured / Std / NI / NA

Sp. Reading

290173

T/Radio:

Insured / Std / NI / NA

Eng/No:

C/No:

GB3

1025009

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Mod: Nil / SRIm / STD A/Rim or

Tyre Size:

F:

Rapid 195/55R15

R: Goodridge

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

7

mm

R/Bal.

4

mm

L/Bal.

7

mm

L/Bal.

4

mm

D.O.A.

21/10/22

D.O.I.

27/10/2022

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

Date/Time, File Pass to?



: Prell. Report



: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

Add Fee:



: Site Insp (\$



: Interview (\$



Tech Invs (\$



Weekend (\$

) S - RS. \$

) P. 125

) Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

SJL4171G
TP/Lonpac

M/S : LONPAC INSURANCE BERHAD
300 BEACH ROAD
#17-04/07 THE CONCOURSE
SINGAPORE 199555

TEL: 62507388
ATTN: Motor Claim Department

FAX: 62963767

Estimate No: ES2291098/WS
Date: 25 Oct 2022
Policy No: DMPCSNW00105002201
Veh Reg No: SJL4171G
Make/Model: HONDA HONDA FREED
1.5G A

WS Ref: TP/LONPAC
Claim Type: Third Party
Accident Date: 21/10/2022
TP Veh Reg No: YP1980J

Chassis No: GB31025009
Engine No: L15A2325316
Reg. Date: 26/11/2008

Estimate Repair Cost to Vehicle No :SJL4171G

PAGE:1/1

Description	U/Price	Quantity	List Price SS	Amount SS
List Price				
1 REAR BUMPER	490.30	1 PC	490.30	✓
2 REAR BUMPER BEAM	56.20	1 PC	56.20	✓
3 REAR BUMPER CLIPS	3.90	6 PCS	23.40	✓
4 REAR TAILGATE	1,282.50	1 PC	1,282.50	✓
5 TAILGATE LOGO	29.40	1 PC	29.40	✓
6 TAILGATE EMBLEM (FREED)	48.30	1 PC	48.30	✓
7 TAILGATE INNER LOCK	189.50	1 PC	189.50	✓
8 TAILGATE INNER RUBBER	95.00	1 PC	95.00	✓
9 TAILGATE OUTER CENTRE GARNISH	287.30	1 PC	287.30	✓
10 TAILLAMPS	402.30	2 PCS	804.60	✓
11 REAR WINDSCREEN GLASS	1,144.60	1 PC	1,144.60	✓
12 REAR WINDSCREEN GLASS MOULDING	131.80	1 PC	131.80	✓
13 REAR PANEL	342.90	1 PC	342.90	✓
14 REAR WIPER ARM	45.00	1 PC	45.00	✓
15 REAR WIPER MOTOR	280.80	1 PC	280.80	✓
			5,251.60	
		Less 20%	1,050.32	4,201.28
Special Net				
16 REAR WINDSCREEN GLASS SEALANT	40.00	1 PC	40.00	✓
17 REVERSE SENSOR	200.00	1 SET	200.00	✓
			240.00	240.00
Labour				
18 REMOVE AND REFIX REAR WINDSCREEN GLASS	100.00	1 LA	100.00	✓
19 REMOVE & REFIX REAR BUMPER ASSY, TAILLAMPS, TAILGATE, LOCK ASSY, REAR WIPER ASSY, KNOCK & REPAIR REAR PANEL, TAILLAMP PANEL AND REALIGN THE SAME	600.00	1 LA	600.00	✓
20 PUTTY & RESPRAY ON REAR BUMPER, TAILGATE, REAR PANEL AND REAR AFFECTED AREAS	650.00	1 LA	650.00	800.00
21 REMOVE & REFIX REVERSE CAMERA & SENSOR AND RESET SYSTEM	40.00	1 LA	40.00	✓
22 RUSTPROOFING	30.00	1 LA	30.00	✓
			1,420.00	1,420.00
			Total	SS 5,861.28
			Add GST @ 7%	410.29
			Total Amount Payable	SS 6,271.57

LKK Auto Consultants hence notify
 the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification(s) is allowed
 • Supplementary item(s) must be resurveyed and
 is subject to final approval from Insurance Company
 Acknowledged by Repairer
 Signature:
 Date:

For Cheng Hoe Motor Pte Ltd

AUTHORISED SIGNATURE

007 / CHENG HOE MOTOR PTE LTD[768761]
DATE & TIME: 25/10/2022 11:37 (SGT)
REPORTED BY: CHIONG BENG CHOON
ON: 1 (25/10/2022 11:37 (SGT))

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Actual Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date of Submission	25/10/2022 11:37 (SGT)
Reported by	Driver
Date of Accident	21/10/2022 21:50 (SGT)
Exact Location of Accident	Singapore
Additional Location Information	BLK 624 YISHUN RING OPPOSITE WORKSITE
Country/State of Loss	Singapore

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJL4171G
INSURED/POLICYHOLDER	
Is company?	No
Name Of Registered Owner	BHAVA MOHAIDEEN MOHAMED MEERAN MUBIN SAHIB
NRIC No	SXXXX498J
Email Address	mdmubinme@gmail.com
Mobile Phone No	(Phone) +65-90281737
Alternative Phone No	-

VEHICLE PARTICULARS

Manufacturer	Honda
Model	FREED 1.5G A
Variant	-
Exact purpose for which vehicle was being used at time of accident	Private use
Are you claiming under your own insurance policy for repair to your vehicle?	No - Claiming third party
Vehicle Category	Private car
Transmission	Auto
CC	1496

INSURANCE COMPANY

Name of Insurance Company	China Taiping Insurance (Singapore) Pte. Ltd.
Policy Number / Cover Note Number	DMPCSNW0010500201

DRIVER

Name of Driver	MOHAMED ALAWOODHEEN PEER MOHAMED
Passport No/FIN	FXXXX448T
Date Of Birth	24/03/1977
Occupation	Indoor


Describe Circumstance of the Accident

NOTE: PLEASE TAKE NOTE THAT YOUR INSURER HAVE 14 DAYS TIME FRAME for you to submit OWN DAMAGE Claim under your Own Comprehensive policy. Pls check your policy for more information.

() Claim Own Policy (☒) Claim Third party () Reporting Only

() Claim OD/ TP at other workshop ()

Sketch Plan



I park my vehicle stationary and behind there was a lorry park at. Suddenly the lorry (YP 19803) did not check behind and went reversing cause it lorry hit onto my vehicle rear portion and cause damage.

Declaration

I/We declare the foregoing particulars are true in every respect.

[Signature] 22/10/2022
Policyholder's Signature / Date & Time

[Signature] 22/10/22
Driver's Signature (if driver is not the policyholder) / Date & Time

(W.L.) 22/10/22
Witnessed by Reporting Centre Personnel
(Name as in NRIC/ID card)