

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

AIG

Name : Kung Wai Chun (83486623)

Accident Date : 18-Oct-22

Vehicle No : JUA5367 (DOR160620)

Vehicle Model : Yamaha Y15ZR

Estimated Repair Costs

Qty	Description	Amount S(\$)
	<u>List Items</u>	
2	Front fork tube assy Bent/twr	\$ 480 640.00 ✓
1	Fork under bracket Bnt	\$ 185.00 ✓
1	Front wheel rim worn	\$ 290 380.00 ✓
1	Front rim shaft n	\$ 65.00 X
1	Front rim bearing n	\$ 90.00 ✓
1	Front brake disc n	\$ 185.00 X
1	Brake master pump bracket cne	\$ 95.00 ✓
1	Handle bar Bent	\$ 165.00 ✓
1	Handle-bar end (1 set) m.s	\$ 30 105.00 ✓
1	Hand grip (1 set) 70-1	\$ 45 85.00 ✓
1	Headlamp assy cne	\$ 320 580.00 ✓
1	Mirror BND	\$ 60 150.00 ✓
1	Brake lever cne	\$ 40 85.00 ✓
1	Clutch lever SCR	\$ 40 85.00 ✓
1	Front sigal (1 set) cne	\$ 60 140.00 ✓
1	Pilot lights cne	\$ 145 228.00 ✓
2	Front side lower cover - matt black cur/cne	\$ 160.00 ✓
1	Front horn inner cover centre matt black cur/cne	\$ 85.00 ✓
1	Front horn inner cover cne	\$ 60 135.00 ✓
1	Pillions footrest bracket n/cne	\$ 115 180.00 ✓
1	Pillion footrest (1 set) n/cne	\$ 60 98.00 ✓
1	Radiator 2 n	\$ 380 525.00 ✓
1	Engine cover cne	\$ 400 480.00 ✓
1	Rider footrest(1 set) n/s 70-1	\$ 60 88.00 ✓
1	Rider footrest bracket (1 set) Bent	\$ 115 170.00 ✓
1	Brake pedal Bent	\$ 125.00 ✓
1	Gear pedal Bent	\$ 115.00 ✓
1	Fairing assy (1 set) cne	\$ 480 580.00 ✓
		\$ 6,004.00
	Less 10%	\$ 600.40
		\$ 5,403.60

Not Authorized
2/5 \$2800/
4 days
27/10/22
Whaphle-Att-14

EROFIA MOTOR TRADING PTE LTD (201202259N)

No 1 Kaki Bukit Avenue 6 #02-62 AutoBay @ Kaki Bukit Singapore 417883

Tel : 67527740 Fax : 67528669

E-mail: erofia@singnet.com.sg

Name : Kung Wai Chun (83486623)

Accident Date : 18-Oct-22

Vehicle No : JUA5367 (DOR160620)

Vehicle Model : Yamaha Y15ZR

Estimated Repair Costs

<u>Special Net Items</u>				
1	Number plate (1 set)	nee front	\$	38.00 10
2	Fork oils	17	\$	30.00 X
2	Fork oil seals	17	\$	56.00 X
1	Steering cone (1 set)	nee	\$	95.00 60
1	E.R.P. IU	su	\$	180.00 X
1	Rear box	cu7	\$	380.00 200
1	Rear box bracket	cu7	\$	180.00 100
1	Sticker set	nee	\$	120.00 ✓
			\$	1,079.00

S/No. Labour

1	To provide towing service (LOD) \$50.00	\$	-
2	To check wiring and reset headlamp focusing	\$	17 80.00 X
3	To repair body frame	\$	M 350.00 X
4	To provide labour	\$	480.00 300
		\$	910.00

Grand Total

\$ 7,392.60

Singapore Dollars: Seven Thousand Three Hundred Ninety-Two and Cents: Sixty only

EROFIA MOTOR TRADING PTE LTD

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: