

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 62563561 FAX: (065) 62564315

Your Ref: AJ.tk,7459.2020.XY Date: 11th Nov 2022

Our Ref: CS1/LAW22010639/Aqy3e2

M/s Crossborders LLC

133 New Bridge Road #23-03 Chinatown Point Singapore 059413 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SMP 6696P

INSURED VEHICLE: GBD 626A ACCIDENT DATE: 14/09/2020

We thank you for your instruction on 27/10/2022.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SMP 6696P from M/s Pro-option Services.
- b) Final Repair Bill of SMP 6696P from M/s Xin Yun Auto Private Limited.
- c) Singapore Accident Statement of Vehicles SMP 6696P and GBD 626A.
- d) Colour damaged vehicle photographs of SMP 6696P.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number : SMP 6696P

Make & Model : Mercedes Benz GLA180 Auto

Chassis Number : WDC1569422J585108

Year of Registration : 2019 Engine Capacity : 1595 cc

- 2. We recommend that the repairs of the entire damage require about 12 (Twelve) working days to complete.
- 3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.