

ComfortDelGro Engineering Pte Ltd (Co.Reg.No:199506048W)

205 Braddell Road
Singapore 579701

Tel: 63837613 Fax: 62815767/65462533 Email: teokeejin@cdge.com.sg

INSURER: **India International Insurance Pte Ltd (HQ)**

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	
Policy No:	D18MFL0003414_03	Date of Loss:	11/10/2022
Vehicle Reg. No.:	SMG4727U	Driveable?	
Driver Age/Info:		Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	COMFORTDELGRO RENT-A-CAR PTE LTD		
Make/Model:	MAZDA 3, 1.5 SEDAN (A)	Vehicle Reg. Date:	20/12/2018
Vehicle Colour:	RED		
Engine No:	P520567710	Chassis No:	JM6BN22A8K0266583
Odometer:	77086 KM		
Paint Type:			
List Item Discount:	20.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	<i>1x 9 days</i>		
Present Location:	COMFORTDELGRO ENGINEERING PTE LTD (BRADDELL)		<i>Not Notified Primary B4 repair Ex TBA @ 22,083-76 B4 ex ass</i>

COST OF CLAIMS

	Amount
Parts	21,627.52
Miscellaneous Items	11.00
Labour	3,550.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	25,188.52
+ GST 7.00% (S\$)	1,763.20
Nett Amount (S\$)	26,951.72

This claim is handled by: **OI SUN PIN**

Generated using **Merimen e-Claims Internet Estimation & Adjusting System**

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 26 Oct 2022)
Parts: 143 MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: (Unsubmitted, no print-code for SMG4727U)
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *

Estimates on Parts

No.	Qty	Part No.	Particulars		%Disc	%Depr	Amount	
1	1		*FRONT BONNET ✓	Bu	20.00	0.00	*1,120.70 FL	✓
2	1		*FRONT BONNET LOCK ✓	Dis	20.00	0.00	*207.00 FL	✓
3	1		*FRONT BONNET HINGE LH	R	20.00	0.00	*45.05 FL	✓
4	1		*FRONT BONNET HINGE RH	R	20.00	0.00	*45.05 FL	✓
5	1		*FRONT BUMPER ✓	Bu / CM	20.00	0.00	*995.00 FL	✓
6	1		*FRONT NUMBER PLATE BRACKET	Dis	20.00	0.00	*56.80 FL	✓
7	1		*FRONT BUMPER RETAINER LH ✓	Dis	20.00	0.00	*16.00 FL	✓
8	1		*FRONT BUMPER RETAINER RH	Sm	20.00	0.00	*16.00 FL	X
9	1		*FRONT BUMPER CLIPS ✓	Sm	20.00	0.00	*30.00 FL	✓
10	1		*FRONT BUMPER TOP PANEL ✓	Dis	20.00	0.00	*329.40 FL	✓
11	1		*FRONT RADIATOR GRILLE ✓	CM	20.00	0.00	*164.00 FL	✓
12	1		*FRONT RADIATOR CHROME LH	CM	20.00	0.00	*232.00 FL	✓
13	1		*FRONT RADIATOR CHROME RH ✓	CM	20.00	0.00	*232.00 FL	✓
14	1		*FRONT REINFORCEMENT GARNISH ✓	CM	20.00	0.00	*70.40 FL	✓
15	1		*FRONT GRILLE EMBLEM ✓	CM	20.00	0.00	*75.00 FL	✓
16	1		*FRONT GRILLE EMBLEM BASE ✓	Dis	20.00	0.00	*27.00 FL	✓
17	1		*FRONT SIGNAL LAMP LH	Sm	20.00	0.00	*169.00 FL	X
18	1		*FRONT FOG LAMP LH	Sm	20.00	0.00	*761.00 FL	X
19	1		*FRONT FOG LAMP GARNISH LH ✓	Dis	20.00	0.00	*28.00 FL	✓
20	1		*LH HEADLAMP ✓	CM	20.00	0.00	*4,336.00 FL	✓
21	1		*RH HEADLAMP ✓	My CM	20.00	0.00	*4,336.00 FL	✓
22	1		*FRONT LEFT FENDER ✓		20.00	0.00	*349.00 FL	✓
23	1		*FRONT LEFT FENDER CLIPS ✓		20.00	0.00	*30.00 FL	✓
24	1		*FRONT REINFORCEMENT BAR	R	20.00	0.00	*502.80 FL	X
25	1		*FRONT TOP SUPPORT PANEL ✓	Bu	20.00	0.00	*130.20 FL	✓
26	1		*FRONT SUPPORT PANEL ASSY ✓	As	20.00	0.00	*480.00 FL	✓
27	1		*CONDENSOR ✓	Pr	20.00	0.00	*1,086.00 FL	✓
28	1		*FRONT RADIATOR ✓	BT	20.00	0.00	*1,118.20 FL	✓
29	1		*FAN COWLING	Sm	20.00	0.00	*442.20 FL	X
30	1		*COOLANT SPARE TANK	R	20.00	0.00	*71.00 FL	X
31	1		*DRIVER AIRBAG ✓	Av24	20.00	0.00	*1,826.00 FL	✓
32	1		*FRONT LEFT PASSENGER AIRBAG ✓ 1400	h	20.00	0.00	*1,564.00 FL	✓
33	1		*AIRBAG MODULE ✓ 1147	Av24	20.00	0.00	*1,507.00 FL	✓
34	1		*STEERING CLOCK SPRING ✓	Sm	20.00	0.00	*520.00 FL	✓
35	1		*DASHBOARD ✓ 1429.60	Tn	20.00	0.00	*1,500.60 FL	✓
36	1		*DRIVER SEATBELT ✓ 1023	Tn	20.00	0.00	*1,308.00 FL	✓
37	1		*FRONT LEFT PASSENGER SEATBELT ✓ 1023	Tn	20.00	0.00	*1,308.00 FL	✓

F=Franchise part. L=ListItemDisc.

Sub Total (S\$)	27,034.40
- List Item Discount on L Items (S\$)	5,406.88
Total Parts (S\$)	21,627.52

Report was unsubmitted during this print-out.
 Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
Miscellaneous Items			
1	1	OD/TP Case (Insurer)	11.00
Sub Total (S\$)			11.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
Labour Items			
1	To knock & straighten on accident area, to remove & Front refit damage parts.	New	600l 1,320.00
2	To putty & respray on Front damage area	New	1000l 1,200.00
3	To check wiring, focus headlamp	New	20l 80.00
4	To remove & refit radiator, condenser to assist work load, to top up A/C gas.to top up A/C gas.	New	100.00 ✓
5	To refit airbag system	New	200l 250.00
6	To remove & refit dashboard to assist work load.	New	250.00 ✓
7	To reset airbag control unit	New	200l 350.00
Gross Labour Cost (S\$)			3,550.00

Report was unsubmitted during this print-out.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

REPAIR DETAILS

Reference

Part Source: MRM-SG Version: 1.0 (Last Synchronised: 14 Feb 2023)
Parts: 143 MAZDA 3 1.5 SEDAN (A) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's (Price-denominated Standard List)
Print Code: ComfortDelGro Engineering Pte Ltd/SMG4727U/14/02/2023 12:17
Validity: These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.

Estimates on Parts

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*FRONT BONNET WHEATERSTRIP	<i>CM</i> 20.00	0.00	*66.80 FL
2	1		*FRONT GRILLE INNER BRACKET LH	<i>CM</i> 20.00	0.00	*33.00 FL
3	1		*FRONT GRILLE INNER BRACKET RH	<i>CM</i> 20.00	0.00	*33.00 FL
4	1		*FRONT GRILLE INNER BRACKET CLIP LH	<i>CM</i> 20.00	0.00	*3.00 FL
5	1		*FRONT GRILLE INNER BRACKET CLIP RH	<i>CM</i> 20.00	0.00	*3.00 FL
6	1		*FRONT TOP PANEL TRIM	<i>CM</i> 20.00	0.00	*116.00 FL
7	1		*FRONT BRACE PANEL	<i>CM</i> 20.00	0.00	*40.80 FL
8	1		*FRONT GRILLE COVER LH	<i>CM</i> 20.00	0.00	*13.00 FL
9	1		*FRONT GRILLE COVER RH	<i>CM</i> 20.00	0.00	*13.00 FL
10	1		*FRONT GRILLE CHROME ASSEMBLY	<i>CM</i> 20.00	0.00	*445.80 FL
11	1		*FRONT BUMPER PLATE	<i>CM</i> 0	0.00	*35.00 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	802.40
- List Item Discount on L Items (\$)	153.48
Total Parts (\$)	648.92

ComfortDelGro Engineering Pte Ltd/SMG4727U/14/02/2023 12:17. Not valid without Reference section.
 Generated using Merimen e-Claims IEAS