

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile						
	STRIDES AUTOMO		Ref:	CS/SMR22010651/Gqy3e2		
		NDUSTRIAL PARK		Date:	19/01/2023	
				Code:	SMR	
1.	Policy Particulars :- THIRD PARTY CLAIM					
	Insured Veh.	SMB 1509D	Veh. Inspected		SMH 95E	
	Policy No.		Coverage (\$)		0.00	
	Claim No.	BUS/10/22/5027	Excess (\$)		0.00	
	Assign From	HUA YEN	Assign Date		26/10/2022	
2. Vehicle Particulars & Condition						
	Make & Model	HONDA CIVIC 1.6	c.c		1597	
	Engine No.	HIDDEN	Year of Reg.		2019	
	Chassis No.	MRHFC5650KT000581	Colour		BLUE	
	Odometer	61055 KM	Steering		IN ORDER	
	Brakes	IN ORDER	Modification		STANDARD ALLOY RIM	
	General	GOOD				
3.	Conditions of Tyres					
		Size	Make		Balance	
	R/H Front Tyre	215/55 R16	YOKOHAMA		6 mm	
	L/H Front Tyre	215/55 R16	YOKOHAMA		6 mm	
	R/H Rear Tyre	215/55 R16	YOKOHAMA		6 mm	
	L/H Rear Tyre	215/55 R16	YOKOHAMA		6 mm	
4.	Description of Damages					
	THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION.					
	DAMAGES SEE DETAILS.					
5.	General Information					
	Accident Date	22/10/2022	Inspection Date	<del>)</del>	27/10/2022	
	Survey held at	KAH MOTOR.CO.SDN.BHD				
		6A MANDAI ESTATE SINGAPORE 729903				
5a.	Remarks					
	A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.					
5b.		Estimate Days of Repair				
	ESTIMATED NOR	ESTIMATED NORMAL PERIOD FOR REPAIR: 12 Working Days				