



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
INCOME INSURANCE LTD 75 BRAS BASAH ROAD INCOME CENTRESINGAPORE 189557 ATTN: JENNY PE			Ref: CS3/INC22009014/Gny3e2-1 Date: 14/12/2022 Code: INC	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SNE 8818M	Veh. Inspected	SKX 171H	
Policy No.		Coverage (\$)	0.00	
Claim No.	MT/1188371-001	Excess (\$)	0.00	
Assign From	JENNY PE	Assign Date	26/10/2022	
2. Vehicle Particulars & Condition				
Make & Model	HONDA CIVIC 1.5 TURBO	c.c	1498	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	MRHFC1660GT000103	Colour	RED	
Odometer	165065 KM	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	235/45Z R17	KUMHO	6 mm	
L/H Front Tyre	235/45Z R17	KUMHO	6 mm	
R/H Rear Tyre	235/45Z R17	KUMHO	6 mm	
L/H Rear Tyre	235/45Z R17	KUMHO	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	11/09/2022	Inspection Date	13/09/2022	
Survey held at	D'S GRAFFITI CONCEPTS PTE LTD 8 KAKI BUKIT AVENUE 4 #02-24 PREMIER @ KAKI BUKIT SINGAPORE 415875			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:			5 Working Days	