

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way
#09-16
Singapore 079120

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Hor, Yinrul

Date: 15 Feb 2023

Preliminary Advice

Vehicle No	: SLH9764K	Accident Date	: 17/10/2022
Make	: AUDI Q7	Policy No.	: 2100490068
Assignment Date	: 28/10/2022	Excess	: S\$1,000.00
Date of Inspection	: 26/10/2022	Est. Duration of Repair	: 5
Inspection At	: PREMIUM AUTOMOBILES PTE LTD (UBI) 55 UBI ROAD 1 SINGAPORE 408699		

Point of Impact / General Description of Damages

Parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	31,612.00 (Est \$30,997.00 + Supp \$615.00)
Revised Amount	:S\$	20,428.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	20,428.24
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	145,000.00
COE / PARF Rebate	:S\$	77,624.00
Salvage Value	:S\$	
Margin for Repair	:S\$	67,376.00

Remarks

- (X) The vehicle is repairable at our adjusted amount. We have also confirmed excess and policy coverage. Kindly let us have your authorisation.
- () The vehicle is uneconomical to be repaired, you are advised to invite tender for the wreck.
- (X) Other comments : Kindly approve on Supplementary
- Please note that the preliminary advice amount (Revised) stated are subject to consistency check, part prices and labour cost.