

LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile | | | | | | |
|---|---|---|----------------|-------|-------------------|--|
| | MSIG INSURANCE | (S) PTE LTD | | Ref: | CS/MSG22010685/y3 | |
| | 4 SHENTON WAY SGX CENTRE 2 SI | #21-01 NGAPORE 068807 | | Date: | 28/10/2022 | |
| | | | | Code: | MSG | |
| 1. | I. Policy Particulars :- THIRD PARTY CLAIM | | | | | |
| | Insured Veh. | FBH 5679T | Veh. Inspected | l | FBT 594Z | |
| | Policy No. | 1001778191 | Coverage (\$) | | 0.00 | |
| | Claim No. | 280910 | Excess (\$) | | 0.00 | |
| | Assign From | RICHARD ANG | Assign Date | | 27/10/2022 | |
| 2. Vehicle Particulars & Condition | | | | | | |
| | Make & Model | | c.c | | 0 | |
| | Engine No. | HIDDEN | Year of Reg. | | | |
| | Chassis No. | | Colour | | | |
| | Odometer - | | Steering | | | |
| | Brakes | | Modification | | | |
| | General | | | | | |
| 3. Conditions of Tyres | | | | | | |
| | | Size | Make | | Balance | |
| | R/H Front Tyre | | | | mm | |
| | L/H Front Tyre | | | | mm | |
| | R/H Rear Tyre | | | | mm | |
| | L/H Rear Tyre | | | | mm | |
| 4. | Description of Damages | | | | | |
| | | | | | | |
| 5. | General Information | | | | | |
| | Accident Date | 25/07/2022 | Inspection Dat | е | | |
| | Survey held at | WIN AUTOMOTIVE SERVICES | | | | |
| | | BLK 6, 399J WOODLANDS ROAD YEW TEE INDUSTRIAL ESTATE SINGAPORE 678008 | | | | |
| 5a. Remarks | | | | | | |
| | A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. | | | | | |