



LION CITY RENTALS PTE LTD
4 Jalan Besut S(619557)

Ms MS FIRST CAPITAL INSURANCE LIMITED
Date: 27/10/2022
Attn: MOTOR CLAIMS DEPT

ESTIMATE

VEHICLE NO.: SLM3381U
CHASSIS NO: JTDKB3FU703554455
MAKE / MODEL: TOYOTA PRIUS HYBRID 1.8 CVT
DATE OF ACCIDENT: 24/10/2022
YOUR INSURED VEHICLE NUMBER: SHB19955

PARTS DISCRPTION	QTY	UNIT PRICE	LIST PRICE	
1 TAILGATE / <i>DN</i>	1	\$1,612.00	\$1,612.00	1147 ✓
2 TAILGATE OUTER GARNISH ? X nn	1	\$ 341.00	\$ 341.00	
3 TAILGATE EMBLEM 'LOGO' ? X nn	1	\$ 74.40	\$ 74.40	
4 TAILGATE EMBLEM 'PRIUS' ? X nn	1	\$ 68.00	\$ 68.00	
5 TAILGATE EMBLEM 'HYBRID' ? X nn	1	\$ 69.00	\$ 69.00	
6 TAILGATE GLASS PANEL MOULDING / <i>MP</i>	1	\$ 241.80	\$ 241.80	208 ✓
7 TAILGATE LOCK ? X nn	1	\$ 245.00	\$ 245.00	
8 REAR BUMPER / <i>OR</i>	1	\$ 658.00	\$ 658.00	503 ✓
9 REAR BUMPER LOWER LH / RH ? X nn	2	\$ 112.00	\$ 224.00	
10 REAR BUMPER LOWER GARNISH / <i>CNT</i>	1	\$ 289.00	\$ 289.00	✓
11 REAR BUMPER UNDER COVER ? X nn	1	\$ 221.00	\$ 221.00	
12 REAR BUMPER BRACKET LH / RH <i>OR</i> ? X nn	2	\$ 65.90	\$ 131.80	
13 REAR BUMPER SIDE RETAINER LH / RH / <i>OR</i>	2	\$ 55.70	\$ 111.40	✓
14 TAILLAMP LH / RH X nn	2	\$ 415.00	\$ 830.00	
15 TAILLAMP LOWER BRACKET LH / RH X nn	2	\$ 46.90	\$ 93.80	
16 REAR END PANEL / <i>DN</i>	1	\$ 599.00	\$ 599.00	✓
17 REAR END PANEL TOP GARNISH / <i>CR4</i>	1	\$ 360.90	\$ 360.90	165 ✓
18. <i>Bump - Inflated H. - BT</i>			\$332	
			LIST TOTAL S\$:	\$ 6,170.10
			25.00% DISCOUNT S\$:	\$ 1,542.53
				<u>\$ 4,627.58</u>

3354.40
-25%
2515.80

SPECIAL NETT

1 TAILGATE GLASS PANEL SEALANT / <i>MC</i>	1	\$ 80.00	\$ 80.00	✓
2 REAR NUMBER PLATE X nn	1	\$ 50.00	\$ 50.00	
3 REAR BUMPER CLIP SET / <i>MC</i>	1	\$ 50.00	\$ 50.00	30
4 REAR END PANEL TOP GARNISH CLIPS SET / <i>MC</i>	1	\$ 60.00	\$ 60.00	15
5 REAR END PANEL INSULATION SEAL / <i>MC</i>	1	\$ 150.00	\$ 150.00	30
6 REVERSE SENSOR / <i>Shnd</i>	1	\$ 280.00	\$ 280.00	210

355

Special Nett Total S\$: \$ 670.00

LABOUR CHARGES

1	TO PANEL BEAT, REMOVE AND REPLACE PARTS	800	\$ 1,000.00
2	TO SPRAY PAINT AFFECTED AREA	600	\$ 800.00
3	TUFF COAT	30	\$ 150.00
4	TO REMOVE AND REINSTALL TAILGATE GLASS PANEL	1430	\$ 80.00 ✓

LABOUR TOTAL S\$: \$ 2,030.00

4300.80

L/S - 3440.64
= 3450

TOTAL S\$: \$ 7,327.58

7% GST: \$ 512.93

GRAND TOTAL S\$: \$ 7,840.51

Steve (LKK)

28/10/22, 12.00pm

ML PL

L/S

M AL Ly

S d 75

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: